



#### **RTA Standards**

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

#### **1 Months Warranty**

Enjoy peace of mind for your car purchase

#### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.



# 2014 MITSUBISHI PAJERO GLS HIGHLINE | 189,288 KM

VIN: JMYLYV97WEJ705997

# **Car highlights**



#### Four wheel drive

This car has a Four wheel drive



#### **Cruise control**

Cruise control to drive with ease & comfort



#### **Bluetooth**

Enjoy your drive with bluetooth



## **Amazing Comfort**


Power driver seat

### **Basic Details**



## **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



Fog Light Front	<b>✓</b>	Roof Rails	•
Rear Bumper Spoiler	<b>✓</b>	Halogen Headlights	<b>~</b>
HID Headlights	<b>~</b>		
☆ Safety & Security			
Parking Sensors Rear	~	Reverse Camera	•
Traction Control	<b>✓</b>	Airbag Curtain Shield	<b>✓</b>
Airbag Driver Front	<b>✓</b>	ABS	•
Central Locking	<b>~</b>	Child Safety Locking	<b>✓</b>
Performance			
Differential Locks	<b>✓</b>		
୍ୟଣ Entertainment			
Bluetooth Player	~	Infotainment System	<b>✓</b>
USB player			

## **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Door Trim: Light Scuffing < 50mm

Trunk conditon


**Pillars Condition** 

Trunk

Front right door Moulding: Light Scuffing < 50mm, Paint Chipoff < 5mm Rear right door (!)Moulding: Paint Chip-off < 5mm Right Fender Right Fender: Scratch < 50mm, Paint Chip-off (!) < 5mm Right Quarter Panel (!)Condition: Scratch < 50mm

Left A Pillar	<b>✓</b>	Right A Pillar	<b>✓</b>
Left A to B Pillar Beading	<b>✓</b>	Right A to B Pillar Beading	<b>✓</b>
Right A to B Pillar Light Scuffing < 50mm	(!)	Left B Pillar	<b>✓</b>
Left B Pillar Trim Light Scuffing	!	Left B to C Pillar Beading	<b>✓</b>
Right C Pillar Trim	<b>✓</b>	Right B to C Pillar  Light Scuffing < 80mm	(!)
Right B to C Pillar Beading	<b>✓</b>	Left C Pillar Scratch < 50mm	(!)
Running Board Condition  Left Running Board  Front Left Floor Trim: Light Scuffing < 80mm  Sunroof Glass Condition (If Equipped)	!	Right Running Board Front Right Floor Trim: Light Scuffing < 80mm	(!)
Sun Roof Glass	<b>✓</b>		
Windshield Condition Front Windshield Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm	!	Rear Windshield	<b>✓</b>
Structural Assessment			
Chassis Condition	<b>✓</b>	Radiator Support	<b>✓</b>
Apron	<b>✓</b>	Boot Floor  Door Skirting: Low Visual Dent < 30mm, Light  Scuffing < 50mm, Paint Chip-off < 5mm	!
Firewall Condition	•	Cowl Top Beading: Crack/Fair Use Wear<50mm	(!)
Head Light Support Condition	<b>✓</b>		
Cowl Top			
Cowl Top	<b>✓</b>		
Rear View Mirror Condition  Left Hand Side Mirror  Body: Paint Chip-off < 5mm	!	Left Side Mirror	<b>✓</b>
Right Side Mirror	<b>✓</b>	Right Hand Side Mirror	<b>✓</b>
Alloy Wheel/ Rim			

Left Front Alloy/ Rim	<b>✓</b>	Rim: Alloy Edge/ Scuff < 80mm	!
Right Front Alloy/ Rim	!	Right Rear Alloy/ Rim	(!)
Rim: Alloy Edge/ Scuff < 80mm		Rim: Alloy Edge/ Scuff < 80mm	
Spare Alloy/ Rim Condition	•		
Wheel cover	<b>✓</b>	Antenna	<b>✓</b>
Grill Condition Light Scuffing < 50mm	(!)	Monogram Chrome Low Brightness/ Fair Use Wear	!
Window Glass	<b>✓</b>	Wiper	<b>✓</b>
Panel Condition			
Rear Trunk Panel Scratch < 50mm	!		
<b>■ Engine &amp; Transmission</b>			
Engine			
Engine Body	<b>✓</b>	Engine Performance	<b>✓</b>
Engine Oil (Condition & Level)	<b>✓</b>	Exhaust System	<b>✓</b>
Radiator Condition	<b>✓</b>	Radiator Coolant	•
Battery			
Battery Terminal & Tightness	<b>✓</b>		
Fuel System			
Fuel Tank	<b>✓</b>		
Transmission Operation			
Gear Shifting	<b>✓</b>	Drive Axle	<b>✓</b>
4*4 Condition (If Applicable)	<b>✓</b>	Transmission Fluid	<b>✓</b>
Steering, Suspension & Brakes			
Steering			
Steering wheel	<b>✓</b>		
Brake System			
Parking Brake	<b>✓</b>	Brake Master Cylinder	<b>✓</b>



Crack/Fair Use Wear			
Rear Left AC Vent RHS Crack/Fair Use Wear	!		
Parking Sensors	<b>✓</b>	Rear Defogger Extensive Wear Of Strip	!
USB Charging Port	•	Power/ Manual Windows Front Left: Master Switch Buttons Faded	!
🖺 Interiors & Luggage			
Dashboard And Instrument Panel  Dashboard And Instrument Panel: Light  Scuffing/Crack	(!)	Central Console  Arm Rest: Minor Disfiguration	(!)
Cup Holder	<b>✓</b>	Glove Box Glove Box: Glove Box Retainer Faulty, Minor Scuffing/Crack/Fair Use Wear	!
Steering Wheel Steering Wheel Fair Use Wear	!	Sunvisor	<b>✓</b>
Seat Upholstery Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears, Minor Fair Wear/Fade off, Minor Smudge/ Cracks	(!)	Manual Seat Movement	<b>✓</b>
Seat Belts	<b>✓</b>	Head Rest	<b>✓</b>
Door Controls And Trim Front Left Door: Scuffing, Scuffing/ Disfiguration	(!)	Grab Handle	•
Carpet Front Left Floor Mat: Smudge/Burn/Crack	(!)	Headliner Front Left: Crack/Fair Use Wear, Light Smudge/Disfiguration	!
Rear View Mirror	<b>✓</b>	Toolkit	<b>✓</b>
Tyres			
Tyres Condition			
Left Hand Side Front Tyre	<b>✓</b>	Left Hand Side Rear Tyre	<b>✓</b>
Right Hand Side Front Tyre	<b>✓</b>	Right Hand Side Rear Tyre	<b>✓</b>
Tyres Depth (Remaining)			

LHS Front Tyre	<85%	LHS Rear Tyre	<90%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE