

Car Report



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.

2014 FORD EDGE

SE | 203,676 KM

VIN: 2FMDK4GC1EBB70680

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Rear



Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

Yes	Specs	GCC	203676	Kilometers	
Basic Option	Option Type		3.5L	Engine	
All Wheel Drive	Drive	।-@-। ।-ᠿ-।	Automatic	Transmission	
Petrol	Fuel		SUV	Body Type	
Exterior Color White	Exterior Color		Alloy Wheels	Wheel Type	
4 Airbags	Number of Airbags	х <mark>с</mark> о	Fabric Trim	Interior Trim	*
2 Keys	Number of keys	Ç	5 Seats	Seating Capacity	Å
			2FMDK4GC1EBB70680	VIN number	

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

© Comfort & Convenience			
Cruise Control	~	Rear Armrest with cupholder	~
Steering Mounted Audio Controls	~	Rear Defogger	~
Central Armrest	~	Automatic Headlights	~
吟 Safety & Security			
Parking Sensors Rear	~	Traction Control	~

Airbag Driver Front	 	ABS	~
Central Locking	 	Child Safety Locking	~
Exteriors			
Roof Rails	~	Rear Bumper Spoiler	~
Halogen Headlights	 		
们。 Entertainment			
Bluetooth Player	 	USB player	 Image: A start of the start of

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed			
🕾 Exterior			
Doors condition			
Front left door	 	Front right door Panel: Light Scuffing < 50mm	(!)
Rear left door Panel: Paint Chip-off < 5mm	(!)	Rear right door Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm	!
Fenders Condition			
Left Fender Condition: Paint Chip-off < 5mm	(!)	Right Fender	~
Quarter Panels Condition			
Left Quarter Panel Condition: Chip<5mm	(!)	Right Quarter Panel Condition: Acid Marks/Bird Dropping<5mm, Chip<5mm	!
Front Bumper Condition			
Front Bumper	 		
Rear Bumper Condition Rear Bumper Rear Bumper: Light Scuffing < 80mm, Dent < 50mm	(!)		
Hood Condition			
Hood	 		
Trunk Condition			
Trunk	 Image: A start of the start of		
Trunk conditon			
Trunk	 		
Roof Condition			
Roof	~		
Pillars Condition			

Left A Pillar	~	Right A Pillar	~
Left A to B Pillar Beading	~	Right A to B Pillar Beading Beading Crack/ Tear < 5mm	!
Right A to B Pillar	~	Left B Pillar	~
Left B Pillar Trim	~	Left B to C Pillar Beading	~
Right C Pillar Trim	 Image: A start of the start of	Right B to C Pillar	~
Right B to C Pillar Beading	 Image: A start of the start of	Left C Pillar	~
Running Board Condition			
Left Running Board	 Image: A start of the start of	Right Running Board	~
Windshield Condition			
Front Windshield	 	Rear Windshield	~
Structural Assessment			
Chassis Condition	 Image: A start of the start of	Radiator Support	~
Apron	~	Boot Floor	~
Firewall Condition	•	Cowl Top Beading: Crack/Fair Use Wear<50mm	!
Head Light Support Condition	~		
Cowl Top			
Cowl Top	 		
Rear View Mirror Condition			
Left Hand Side Mirror	 Image: A start of the start of	Left Side Mirror	~
Right Side Mirror	~	Right Hand Side Mirror	~
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	 Image: A start of the start of	Left Rear Alloy/ Rim	~
Right Front Alloy/ Rim	~	Right Rear Alloy/ Rim	~
Spare Alloy/ Rim Condition	 Image: A start of the start of		
Wheel cover	•	Antenna	•
Grill Condition	•	Monogram	~

Window Glass	 	Wiper	~
Panel Condition Rear Trunk Panel Paint Chip Off < 5mm	(!)		
Engine & Transmission			
Engine			
Engine Body	 	Engine Performance	 Image: A start of the start of
Engine Oil (Condition & Level)	~	Exhaust System	~
Radiator Condition	 	Radiator Coolant Hoses: Crack/ Fair Use Wear	(!)
Battery			
Battery Terminal & Tightness	~		
Fuel System			
Fuel Cap	 	Fuel Tank	
Transmission Operation			
Gear Shifting	 	Drive Axle	
4*4 Condition (If Applicable)	~	Transmission Fluid	 Image: A start of the start of
Steering, Suspension & Brakes			

Steering			
Steering wheel	 		
Brake System			
Brake Master Cylinder	 	Brake Disc & Brake Pad	
Brake Fluid	 		
Pedals	 		
Suspension			
Shock Absorbers	 		

Electricals, Controls & Lights

Keys

Master Key Remote/Engine Start Not Working	!	Spare Key(s) Remote Engine Start Not Working	!
Door Locks			
Child Safety Locking	~		
Dashboard			
Instrument Panel	 Image: A start of the start of		
Airbags			
Airbags	 		
Controls	~	Cruise Control	 Image: A start of the start of
Infotainment Display	~	Engine Sensors	~
OBD Connector	~	Music System	~
Lights			
Headlight	 Image: A start of the start of	Interior Lights	
Tail Light Cluster	 	License Plate Light	
Air Conditioning			
AC Cooling	 Image: A start of the start of	AC Switch	
AC System Leaks	 	Center AC Vent	~
Front Right AC Vent	 Image: A start of the start of	Heater Heater Not Working	!
Rear Blower Switch	 		
Parking Sensors	 Image: A start of the start of	Rear Defogger	 Image: A start of the start of
USB Charging Port	 	Power/ Manual Windows	 Image: A start of the start of
Ӓ Interiors & Luggage			
Dashboard And Instrument Panel	~	Central Console Cigarette Lighter: Cigarette Lighter Missing	(!)
Glove Box	~	Steering Wheel	
Sunvisor	~	Seat Upholstery	•

Manual Seat Movement	 	Seat Belts	
Head Rest	 	Door Controls And Trim	~
Grab Handle	 Image: A start of the start of	Carpet	 Image: A start of the start of
Headliner	 Image: A start of the start of	Rear View Mirror	 Image: A start of the start of
Toolkit	 Image: A start of the start of		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	 	Left Hand Side Rear Tyre	~
Right Hand Side Front Tyre	 	Right Hand Side Rear Tyre	~
Spare Tyre	~		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<45%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE