

Car Report



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2017 TOYOTA YARIS SE / E | 123,321 KM

VIN: MR2K19F35H1017001

Car highlights

Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat



Airbag safety

Airbag Driver Front



Tilt Steering wheel

Tilt steering wheel for extra comfort

Basic Details

Yes	Specs	GCC	123321	Kilometers	
Basic	Option Type		1.3L	Engine	
Front Wheel Drive	Drive	।~ ♀ ~। । -ᠿ-।	Automatic	Transmission	
Petrol	Fuel		НАТСНВАСК	Body Type	
Exterior Color White	Exterior Color		Steel Wheels	Wheel Type	
2 Airbags	Number of Airbags	Ъ°	Fabric Trim	Interior Trim	*
3 Keys	Number of keys	Ş	5 Seats	Seating Capacity	Å
			MR2K19F35H1017001	VIN number	

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Safety & Security			
Traction Control	 	Airbag Driver Front	~
ABS	 	Central Locking	 Image: A start of the start of
Child Safety Locking	 Image: A start of the start of		
Comfort & Convenience			
Rear Defogger	~		

ග්ෂ Entertainment			
Bluetooth Player	~	USB player	
Exteriors			
Halogen Headlights	 		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

 \checkmark

🕾 Exterior			
Doors condition			
Front left door Inner Frame: Scratch < 50mm	(!)	Front right door Handle: Paint Chip-off < 5mm	!
Rear left door Moulding: Paint Chip-off < 5mm	(!)	Rear right door Panel: Light Scuffing < 50mm, Low Visual Dent < 30mm, Paint Chip-off < 5mm	!
Fenders Condition			
Left Fender Condition: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm	(!)	Right Fender Right Fender: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm	!
Quarter Panels Condition			
Left Quarter Panel Condition: Scratch < 50mm, Dent < 30mm	(!)	Right Quarter Panel Condition: Dent < 30mm, Scratch < 50mm	!
Front Bumper Condition			
Front Bumper	 		
Rear Bumper Condition Rear Bumper Rear Bumper: Dent < 50mm, Light Scuffing < 80mm, Chip< 8mm	(!)		
Hood Condition			
Hood Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm	(!)		
Trunk Condition			
Trunk Door Trim: Light Scuffing < 50mm	(!)		
Trunk conditon			
Trunk	 Image: A start of the start of		
Roof Condition			

Pillars Condition			
Left A Pillar	 Image: A start of the start of	Right A Pillar	~
Left A to B Pillar Beading	 Image: A start of the start of	Right A to B Pillar Beading	~
Right A to B Pillar	 	Left B Pillar Condition: Chip < 5mm, Scratch < 50mm	!
Left B Pillar Trim	 Image: A start of the start of	Left B to C Pillar Beading	~
Right C Pillar Trim	 Image: A start of the start of	Right B to C Pillar	~
Right B to C Pillar Beading	 	Left C Pillar Scratch < 50mm	!
Running Board Condition			
Left Running Board Front Left Sill Trim: Scratch < 80mm	(!)	Right Running Board Front Right Sill Trim: Light Scuffing < 80mm	!
Windshield Condition Front Windshield Condition: Passenger Side/Stone Chip Mark<8mm, Driver Side/Stone Chip Mark<5mm	(!)	Rear Windshield Tint Fair Use Wear < 30mm	!
Structural Assessment			
Chassis Condition	 Image: A start of the start of	Radiator Support	~
Apron	 Image: A start of the start of	Boot Floor	~
Firewall Condition	 Image: A start of the start of	Cowl Top	~
Head Light Support Condition	~		
Cowl Top			
Cowl Top	 		
Rear View Mirror Condition			
Left Hand Side Mirror	 Image: A start of the start of	Left Side Mirror	~
Right Side Mirror Body: Scratch < 50mm	!	Right Hand Side Mirror	~
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	 Image: A start of the start of		
Wheel Arch	•	Wheel cover Front Right: Face/ Scuffs < 50mm, Edge/	!

Roof

Scuffs < 80mm

Antenna Bent/Broken/Fair Use Wear/Missing	(!)	Grill Condition Light Scuffing < 50mm	(!)
Monogram	 	Window Glass	
Wiper	 		
Panel Condition			
Rear Trunk Panel Acid Marks/ Bird Dropping < 5mm	(!)		

Engine			
Engine Body	 	Engine Performance	 Image: A start of the start of
Engine Oil (Condition & Level)	 Image: A start of the start of	Exhaust System	 Image: A start of the start of
Radiator Condition	~	Radiator Coolant	 Image: A start of the start of
Battery			
Battery Terminal & Tightness	 		
Fuel System			
Fuel Cap	 	Fuel Tank	 Image: A start of the start of
Transmission Operation			
Gear Shifting	 	Drive Axle	 Image: A start of the start of
Transmission Fluid	~		

Steering, Suspension & Brakes			
Steering			
Steering wheel	 		
Brake System			
Parking Brake	 	Brake Master Cylinder	~
Brake Disc & Brake Pad	 Image: A start of the start of	Brake Fluid	~
Pedals	 Image: A start of the start of		
Suspension			

Electricals, Controls & Lights			
Keys			
Master Key	 Image: A start of the start of	Spare Key(s)	 Image: A start of the start of
Door Locks			
Child Safety Locking	 Image: A start of the start of		
Dashboard			
Instrument Panel	 Image: A start of the start of		
Airbags			
Airbags	 		
Controls	~	Infotainment Display	~
Engine Sensors	~	OBD Connector	
Music System	~		
Lights			
Headlight Left: Light Scuff Marks < 50mm	(!)	Interior Lights	~
Tail Light Cluster	 Image: A start of the start of	License Plate Light	~
Air Conditioning			
AC Cooling	 Image: A start of the start of	AC Switch	~
AC System Leaks	 Image: A start of the start of	Center AC Vent	
Front Right AC Vent	~	Heater	~
USB Charging Port	~	Power/ Manual Windows	~
∄ Interiors & Luggage			
Dashboard And Instrument Panel Dashboard And Instrument Panel: Light	(!)	Central Console	(!)

 Dashboard And Instrument Panel
 Image: Central Console

 Dashboard And Instrument Panel: Light
 Image: Central Console

 Scuffing/Crack
 Box: Minor Crack/Fair Use Wear/ Scuffing

 Cup Holder
 Image: Central Console

 Box: Minor Crack/Fair Use Wear/ Scuffing

()

Glove Box: Minor Scuffing/Crack/Fair Use

Wear, Glove Box Retainer Faulty

Steering Wheel Steering Wheel Fair Use Wear	(!)	Sunvisor	
Seat Upholstery Driver Seat: Minor Fair Wear/Fade off	(!)	Manual Seat Movement	
Seat Belts	 Image: A start of the start of	Head Rest	
Door Controls And Trim Front Right Door: Light Scuffing	(!)	Grab Handle	
Carpet Front Left Floor Mat: Smudge/Burn/Crack	(!)	Headliner	
Rear View Mirror	 Image: A start of the start of	Toolkit	
🕲 Tyres			
Tyres Condition			
Left Hand Side Front Tyre	~	Left Hand Side Rear Tyre	~
Right Hand Side Front Tyre	 	Right Hand Side Rear Tyre	
Spare Tyre	 		
Tyres Depth (Remaining)			
LHS Front Tyre	<55%	LHS Rear Tyre	<65%
RHS Front Tyre	<55%	RHS Rear Tyre	<65%

<65%

Spare Tyre



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE