



### RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

### 1 Months Warranty

Enjoy peace of mind for your car purchase

### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





**2013 TOYOTA COROLLA**

**XLI | 203,309 KM**

VIN: RKLBC42E4D5308557

## **Car highlights**



### **Cruise control**

Cruise control to drive with ease & comfort



### **Amazing Comfort**

Power driver seat



### **Airbag safety**
















Airbag Driver Front



### **Central Arm Rest**











Central arm rest for extra comfort

## Basic Details

 Kilometers	<b>203309</b>	 Specs	<b>Yes</b>
 Engine	<b>1.8L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Steel Wheels</b>	 Exterior Color	<b>Exterior Color Black</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>RKLBC42E4D5308557</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Cruise Control		Rear Armrest with cupholder	
Rear Defogger		Central Armrest	
 <b>Safety &amp; Security</b>			
Traction Control		Airbag Driver Front	
ABS		Central Locking	

Child Safety Locking



**Exteriors**

Halogen Headlights



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

#### Front left door

Frame Extension Cover: Scratch < 50mm



#### Front right door

Panel: Light Scuffing < 50mm, Scuffing > 50mm



#### Rear left door



#### Rear right door

Panel: Scuffing > 50mm, Low Visual Dent < 30mm, Paint Chip-off < 5mm



### Fenders Condition

#### Left Fender

Condition: Dent < 30mm, Scratch < 50mm



#### Right Fender

Right Fender: Scratch < 50mm



### Quarter Panels Condition

#### Left Quarter Panel

Condition: Scratch < 50mm



#### Right Quarter Panel



### Front Bumper Condition

#### Front Bumper



### Rear Bumper Condition

#### Rear Bumper

Rear Bumper: Replaced, Fully Repainted, Dent < 50mm, Light Scuffing < 80mm, Paint Faded



### Hood Condition

#### Hood

Bonnet: Paint Damage/ Low Brightness, Light Scuffing < 50mm, Acid Marks/ Bird Dropping < 5mm



### Trunk Condition

#### Trunk



#### Trunk condition

#### Trunk



Roof Condition


Roof 

Pillars Condition

Left A Pillar 

Right A Pillar 

Left A to B Pillar Beading 

Right A to B Pillar Beading 

Right A to B Pillar 


Left B Pillar 

Left B Pillar Trim 

Left B to C Pillar Beading 


Right C Pillar Trim 


Right B to C Pillar 

Right B to C Pillar Beading 


Left C Pillar 

Running Board Condition

Left Running Board  
Condition: Scratch < 80mm 

Right Running Board  
Condition: Light Scuffing < 80mm 

Windshield Condition

Front Windshield  
Beading: Mouldings Crack/ Fair Use Wear > 50mm 


Rear Windshield 

Structural Assessment

Chassis Condition 

Radiator Support 

Apron 

Boot Floor  
Condition: Poor Refurb Job, Refurbished to RTA standards 

Firewall Condition 

Cowl Top 

Head Light Support Condition 


Cowl Top

Cowl Top 

Rear View Mirror Condition

Left Hand Side Mirror  
Body: Paint Faded 

Left Side Mirror 

Right Side Mirror  
Body: Scratch < 50mm, Paint Defects 

Right Hand Side Mirror 

Alloy Wheel/ Rim

Spare Alloy/ Rim Condition 

Wheel Arch		Wheel cover	
		Rear Right: Edge/ Scuffs < 80mm	
Antenna		Grill Condition	
		Light Scuffing < 50mm	
Monogram		Window Glass	
Wiper			
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm			

## Engine & Transmission

Engine			
Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Radiator Condition		Radiator Coolant	
Battery			
Battery Terminal & Tightness			
Fuel System			
Fuel Cap		Fuel Tank	
Transmission Operation			
Gear Shifting		Drive Axle	
Transmission Fluid			

## Steering, Suspension & Brakes

Steering			
Steering wheel			
Brake System			
Parking Brake		Brake Master Cylinder	
Brake Disc & Brake Pad		Brake Fluid	
Pedals			

Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Sunroof Operation

Sunroof



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Defogger



Power/ Manual Windows



## Interiors & Luggage



Dashboard And Instrument Panel	✓	Central Console Box: Lock Damage	⚠
Cup Holder	✓	Glove Box	✓
Steering Wheel Steering Wheel Fair Use Wear	⚠	Sunvisor Left: Sunvisor LHS Minor Crack/Fair Use Wear, Sunvisor RHS Major Crack/Damage, Sunvisor RHS Minor Crack/Damage, RHS Sunvisor Fabric Fair Use Wear	⚠
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle Rear Left: Crack/Fair Use Wear	⚠
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

### Tyres Condition

Left Hand Side Rear Tyre	✓	Right Hand Side Front Tyre	✓
Right Hand Side Rear Tyre	✓	Spare Tyre	✓
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<55%		



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE