

Car Report



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.



2013 AUDI Q3 STD | 178,170 KM

VIN: WA1DFAFS7DR000197

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

Yes	Specs	GCC	178170	Kilometers	
Basic	Option Type		2.0L	Engine	•
All Wheel Drive	Drive	।-∲-। ।-∯-।	Automatic	Transmission	
Petrol	Fuel		SUV	Body Type	
Exterior Color Grey	Exterior Color		Alloy Wheels	Wheel Type	
6 Airbags	Number of Airbags	<mark>Д</mark> о	Leather Trim	Interior Trim	*
1 Keys	Number of keys	Ş	5 Seats	Seating Capacity	Å
			WA1DFAFS7DR000197	VIN number	

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Climate Control AC	~	Cruise Control	~
Steering Mounted Audio Controls	~	Rear Defogger	~
Central Armrest	 	Automatic Headlights	~
Exteriors			
Fog Light Front	~	Roof Rails	 Image: A start of the start of

Running Lights	 	Rear Bumper Spoiler	~
HID Headlights	~		
Safety & Security			
Parking Sensors Rear	~	Traction Control	~
Airbag Curtain Shield	~	Airbag Driver Front	~
ABS	~	Central Locking	~
ඥ් Entertainment			
Bluetooth Player	~	Infotainment System	~

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed			
🕾 Exterior			
Doors condition			
Front left door	 Image: A start of the start of	Front right door Panel: Light Scuffing < 50mm, Low Visibility Dent < 30mm	!
Rear left door Panel: Dent < 30mm	(!)	Rear right door Panel: Dent > 30mm	!
Fenders Condition Left Fender Condition: Scratch < 50mm	(!)	Right Fender	~
Quarter Panels Condition Left Quarter Panel Condition: Dent < 30mm, Scratch < 50mm	(!)	Right Quarter Panel Condition: Dent < 30mm	!
Front Bumper Condition			
Front Bumper	~		
Rear Bumper Condition Rear Bumper Rear Bumper: Light Scuffing < 80mm	(!)		
Hood Condition Hood Bonnet: Paint Chip-off < 5mm	(!)		
Trunk Condition			
Trunk	 Image: A start of the start of		
Trunk conditon			
Trunk	 		
Roof Condition			
Roof	~		
Pillars Condition			

Left A Pillar Inner Condition: Fair Use Wear	(!)	Right A Pillar Inner Condition: Light Scuffing	(!)
Left A to B Pillar Beading	 	Right A to B Pillar Beading	~
Right A to B Pillar	 Image: A start of the start of	Left B Pillar	~
Left B Pillar Trim	~	Left B to C Pillar Beading	~
Right C Pillar Trim	 Image: A start of the start of	Right B to C Pillar	~
Right B to C Pillar Beading	 Image: A start of the start of	Left C Pillar	~
Running Board Condition			
Left Running Board	 Image: A start of the start of	Right Running Board	~
Windshield Condition			
Front Windshield	 Image: A start of the start of	Rear Windshield	~
Structural Assessment			
Chassis Condition	 	Radiator Support	~
Apron	 Image: A start of the start of	Boot Floor	~
Firewall Condition	 	Cowl Top	~
Head Light Support Condition Not Fixed Properly	!		
Cowl Top			
Cowl Top	 		
Rear View Mirror Condition			
Left Hand Side Mirror	 	Left Side Mirror	~
Right Side Mirror Body: Paint Chip-off < 5mm	(!)	Right Hand Side Mirror	•
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	 	Left Rear Alloy/ Rim	~
Right Front Alloy/ Rim	 	Right Rear Alloy/ Rim	~
Spare Alloy/ Rim Condition	~		
Wheel Arch Front Left: Misaligne/ Not Properly Fixed	(!)	Wheel cover	~
Antenna	•	Grill Condition Light Scuffing < 50mm	!

Monogram	~	Window Glass	
Wiper	 Image: A start of the start of		
Panel Condition			
Rear Trunk Panel	 Image: A start of the start of		
Engine & Transmission			
Engine			
Engine Body			
Bulk Head Condition: Visible Fair Use Wear/ Bend	(!)	Engine Performance	
Engine Oil (Condition & Level)	 Image: A start of the start of	Exhaust System	
Turbocharger/ Supercharger	 	Radiator Condition	
Radiator Coolant	 		
Battery			
Battery Terminal & Tightness	 		
Fuel System			
Fuel Tank	 		
Transmission Operation			
Gear Shifting	 Image: A start of the start of	Drive Axle	
4*4 Condition (If Applicable)	 	Transmission Fluid	 Image: A start of the start of
Steering, Suspension & Brakes			
Steering			
Steering wheel			
Brake System			
Parking Brake	 	Brake Master Cylinder	~
Brake Disc & Brake Pad	 Image: A start of the start of	Brake Fluid	 Image: A start of the start of
Pedals	~		

~

Suspension

Shock Absorbers

Electricals, Controls & Lights

Keys			
Master Key	!		
Button Faded	\odot		
Door Locks			
Child Safety Locking	 Image: A start of the start of		
Dashboard			
Instrument Panel	~		
Airbags			
Airbags	~		
-			
Controls	 Image: A start of the start of	Cruise Control	 Image: A set of the set of the
Infotainment Display	~	Engine Sensors	~
OBD Connector	 Image: A start of the start of	Music System	 Image: A start of the start of
Lights			
Headlight			
Left: Low Brightness lamps	!	Interior Lights	\checkmark
Toil Light Cluster		Turn Signal Lighta	
Tail Light Cluster		Turn Signal Lights	\checkmark
Daylight Running Lights	!	License Plate Light	
Right DRL: Low Brightness			
Fog Lights			
5 5			
Air Conditioning			
AC Cooling	~	AC Switch	~
AC System Leaks	\checkmark	Center AC Vent	\checkmark
		Heater	
Front Right AC Vent	\checkmark	Heater Not Working	!
De en Discon Occitate			
Rear Blower Switch			
Parking Sensors		Rear Defogger	
			·
USB Charging Port		Power/ Manual Windows	
			·

≜ Interiors & Luggage

Dashboard And Instrument Panel	 Image: A start of the start of	Central Console	~
Glove Box	•	Steering Wheel Steering Wheel Fair Use Wear	(!)
Sunvisor	~	Seat Upholstery Driver Seat: Minor Smudge/ Cracks, Minor Leather/ Fabric Fair Use Wear/ Tears	(!)
Manual Seat Movement	~	Seat Belts	 Image: A start of the start of
Head Rest	 Image: A start of the start of	Door Controls And Trim Front Left Door: Light Scuffing/ Disfiguration, Light Scuffing	(!)
Grab Handle	~	Carpet	~
Headliner Front Left: Light Smudge/Disfiguration	(!)	Rear View Mirror	•
Toolkit	~		

Itres

Tyres Condition			
Left Hand Side Front Tyre	 	Left Hand Side Rear Tyre	
Right Hand Side Front Tyre	~	Right Hand Side Rear Tyre	 Image: A start of the start of
Spare Tyre	~		
Life remaining			
LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<75%
Spare Tyre	<45%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE