

Car Report



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2020 CADILLAC CT4 PREMIUM LUXURY | 41,079 KM

VIN: 1G6D95RK9L0123909

Car highlights



Low Mileage

This car has been driven less than 15,000 km a year



Cruise control

Cruise control to drive with ease & comfort



Music System

Enjoy your drive with music system



Amazing Comfort

Power driver seat, Memory Seats

Basic Details

Kilometers 4107	79 GCC	Specs	Yes
Engine 2.0	DL 🚑	Option Type	Semi Loaded
Transmission Automat	tic IIII	Drive	Rear Wheel Drive
Body Type SEDA	N 🖺	Fuel	Petrol
Wheel Type Alloy Whee	els 🖗	Exterior Color	Exterior Color White
Minterior Trim	m ^k	Number of Airbags	8 Airbags
A Seating Capacity 5 Sea	ts 🖇	Number of keys	2 Keys
O O O O O </th <th>09</th> <th></th> <th></th>	09		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

© Comfort & Convenience			
Sunroof	~	Cruise Control	~
Memory Seats	 	Steering Mounted Audio Controls	
Heads up Display	 		
Safety & Security			
Parking Sensors Front	~	Parking Sensors Rear	

Reverse Camera	 		
ිය Entertainment			
USB Charging Port	~	Infotainment System	~

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

 \checkmark

🕾 Exterior			
Doors condition			
Front left door		Front right door	
Weather Strip: Chrome Low Brightness, Light Scuffing < 50mm	!	Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm	(!)
Rear left door Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm, Low Visual Dent < 30mm	(!)	Rear right door Inner Frame: Light Scuffing < 80mm	(!)
Fenders Condition			
Left Fender Condition: Paint Chip-off < 5mm, Light Scuffing < 50 mm	(!)	Right Fender Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm	!
Quarter Panels Condition			
Left Quarter Panel Condition: Low Visual Dent<30mm, Light Scuffing<50mm	(!)	Right Quarter Panel Condition: Light Scuffing<50mm, Low Visual Dent < 30mm	!
Front Bumper Condition			
Front Bumper			
Moulding: Fair Use Wear, Misaligned/ Not Properly Fixed	!		
Rear Bumper Condition			
Rear Bumper			
Rear Bumper: Light Scuffing < 80mm, Chip< 8mm	!		
Hood Condition			
Hood			
Bonnet: Light Scuffing < 50mm, Scuffing > 50mm	!		
Trunk Condition			
Trunk	 Image: A start of the start of		
Trunk conditon			

Trunk	~		
Roof Condition			
Roof	~		
Pillars Condition			
Left A Pillar	~	Right A Pillar	~
Left A to B Pillar Beading	~	Right A to B Pillar Beading	~
Right A to B Pillar	~	Left B Pillar	~
Left B Pillar Trim	~	Left B to C Pillar Beading	~
Right C Pillar Trim Scratch	(!)	Right B to C Pillar	~
Right B to C Pillar Beading	~	Left C Pillar	~
Running Board Condition Left Running Board Condition: Scratch	!	Right Running Board Condition: Light Scuffing < 80mm	(!)
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	~		
Windshield Condition			
Front Windshield	~	Rear Windshield	
Structural Assessment			
Chassis Condition	~	Radiator Support	~
Apron	~	Boot Floor	
Firewall Condition	~	Cowl Top	~
Head Light Support Condition	~		
Cowl Top			
Cowl Top	~		
Rear View Mirror Condition			
Left Hand Side Mirror	~	Left Side Mirror	
Right Side Mirror Body: Paint Chip-off < 5mm	(!)	Right Hand Side Mirror	~
Alloy Wheel/ Rim			

Left Front Alloy/ Rim Left Rear Alloy/ Rim	
Right Front Alloy/ Rim Right Rear Alloy/ Rim	
Antenna Grill Condition Light Scuffing < 50mm ()	
Monogram Vindow Glass	
Wiper	
Panel Condition	
Rear Trunk Panel	

Engine & Transmission

Engine			
Engine Body	~	Engine Performance	~
Engine Oil (Condition & Level)	 	Exhaust System	
Turbocharger/ Supercharger	 	Radiator Condition	 Image: A start of the start of
Radiator Coolant	 		
Battery			
Battery Terminal & Tightness	 		
Fuel System			
Fuel Tank	 		
Transmission Operation			
Gear Shifting	 Image: A start of the start of	Gear shift	
Drive Axle	 	Transmission Fluid	

Steering, Suspension & Brakes

Steering			
Steering wheel	 		
Brake System			
Parking Brake	 	Brake Master Cylinder	 Image: A start of the start of
Brake Disc & Brake Pad	~	Brake Fluid	 Image: A start of the start of

Pedals	
Suspension	

~

Shock Absorbers

Air Conditioning

Electricals, Controls & Lights			
Keys			
Master Key	~	Spare Key(s)	 Image: A start of the start of
Door Locks			
Child Safety Locking	~		
Dashboard			
Instrument Panel	~		
Airbags			
Airbags	~		
Controls	 Image: A start of the start of	Cruise Control	~
Heads Up Display		Infotainment Display	
houdo op blopidy		motarimont Dioplay	
Engine Sensors	~	OBD Connector	~
Radar (If Equipped)		Navigation System	
(– 1		Condition: Not Working	\odot
Music System	 		
Sunroof Operation			
Sunroof	 Image: A start of the start of		
Camera	 Image: A start of the start of		
Lights			
Headlight			
Left: Cracks/ Holes, Scratch	(!)	Interior Lights	\checkmark
Tail Light Cluster	~	Turn Signal Lights	~
Daylight Running Lights	~	License Plate Light	~

AC Cooling	~	AC Switch	~
AC System Leaks	~	Center AC Vent	
Front Right AC Vent	 Image: A start of the start of	Heater	
Rear Blower Switch	 Image: A start of the start of		
Rear Defogger	~	USB Charging Port	~
Power/ Manual Windows	~	Seat Heaters	
Memory Seats	~		

▲ Interiors & Luggage

Dashboard And Instrument Panel	 Image: A start of the start of	Central Console	•
Cup Holder	 	Glove Box	 Image: A start of the start of
Steering Wheel	 	Sunvisor	 Image: A start of the start of
Seat Upholstery Driver Seat: Minor Stain/ Cracks	(!)	Manual Seat Movement	~
Seat Belts	~	Head Rest Front Right Seat: Major Wear & Tear	(!)
Door Controls And Trim	 	Grab Handle	
Carpet Rear Floor Carpet: Wear & Tear < 80mm	(!)	Headliner Rear Left: Scratch	!
Rear View Mirror	~	Toolkit	~

🙆 Tyres

Tyres Condition			
Left Hand Side Front Tyre	 Image: A start of the start of	Left Hand Side Rear Tyre	 Image: A start of the start of
Right Hand Side Front Tyre	~	Right Hand Side Rear Tyre	~
Tyres Depth (Remaining)			
LHS Front Tyre	<55%	LHS Rear Tyre	<55%
RHS Front Tyre	<65%	RHS Rear Tyre	<85%

tyre



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE