



#### **RTA Standards**

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

#### **1 Months Warranty**

Enjoy peace of mind for your car purchase

#### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.



# 2016 HYUNDAI ACCENT GL | 126,523 KM

VIN: KMHCT41D5GU954657

# **Car highlights**



### **Amazing Comfort**


Power driver seat



### **Tilt Steering wheel**


Tilt steering wheel for extra comfort

### **Basic Details**



## **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.






### **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Inner Condition: Light Scuffing

Left A to B Pillar Beading	<b>✓</b>	Right A to B Pillar Beading	<b>✓</b>
Right A to B Pillar	<b>✓</b>	Left B Pillar	<b>✓</b>
Left B Pillar Trim	<b>✓</b>	Left B to C Pillar Beading	<b>✓</b>
Right C Pillar Trim	<b>✓</b>	Right B to C Pillar  Low Visual Dent < 50mm	(!)
Right B to C Pillar Beading Beading Crack/ Tear < 5mm	(!)	Left C Pillar	<b>✓</b>
Running Board Condition  Left Running Board  Condition: Dent	!	Right Running Board Condition: Low Visual Dent < 50mm	!
Windshield Condition			
Front Windshield	<b>✓</b>	Rear Windshield	<b>✓</b>
Structural Assessment			
Chassis Condition	<b>✓</b>	Radiator Support	<b>✓</b>
Apron	<b>✓</b>	Boot Floor Condition: Light Scuffing < 80mm	(!)
Firewall Condition	<b>✓</b>	Cowl Top	<b>✓</b>
Head Light Support Condition	<b>✓</b>		
Cowl Top			
Cowl Top	<b>✓</b>		
Rear View Mirror Condition			
Left Hand Side Mirror Body: Paint Faded	(!)	Left Side Mirror	~
Right Side Mirror	<b>✓</b>	Right Hand Side Mirror	<b>✓</b>
Alloy Wheel/ Rim  Spare Alloy/ Rim Condition  Rim: Alloy Edge/ Scuffing < 80mm	(!)		
Wheel Arch	<b>✓</b>	Wheel cover	•
Antenna	<b>✓</b>	Grill Condition	<b>✓</b>
Monogram	•	Window Glass	•



Button Faded			
Door Locks			
Child Safety Locking	<b>✓</b>		
Dashboard			
Instrument Panel	<b>✓</b>		
Airbags			
Airbags	<b>✓</b>		
Controls	<b>✓</b>	Infotainment Display	•
Engine Sensors	<b>✓</b>	OBD Connector	~
Music System  Condition: Button(s) Faded, Knob Fair Use  Wear	(!)		
Lights Headlight Left: Light Scuff Marks < 50mm	(!)	Interior Lights	<b>✓</b>
Tail Light Cluster	<b>✓</b>	Turn Signal Lights	<b>✓</b>
License Plate Light	<b>✓</b>	Fog Lights	<b>✓</b>
Air Conditioning			
AC Cooling	<b>✓</b>	AC Switch	<b>✓</b>
AC System Leaks	<b>✓</b>	Center AC Vent	<b>✓</b>
Front Right AC Vent	<b>✓</b>	Heater	<b>✓</b>
Rear Defogger	<b>✓</b>	USB Charging Port	<b>✓</b>
Power/ Manual Windows	<b>✓</b>		
🖺 Interiors & Luggage			
Dashboard And Instrument Panel  Dashboard And Instrument Panel: Color  Faded	(!)	Central Console  Box: Minor Crack/Fair Use Wear/ Scuffing	(!)
Glove Box	•	Steering Wheel Steering Wheel Fair Use Wear	!

Sunvisor	<b>✓</b>	Seat Upholstery  Driver Seat: Minor Smudge/ Cracks	!
Manual Seat Movement	<b>✓</b>	Seat Belts	<b>✓</b>
Head Rest	•	Door Controls And Trim  Front Left Door: Fair Use Wear, Light Scuffing/ Disfiguration	(!)
Grab Handle	<b>✓</b>	Carpet Front Left Floor Mat: Smudge/Burn/Crack	(!)
Headliner Front Left: Light Smudge/Disfiguration	(!)	Rear View Mirror  De Silvered Mirror<10%	(!)
Toolkit	<b>✓</b>		
Tyres Condition			
Left Hand Side Front Tyre	<b>✓</b>	Left Hand Side Rear Tyre	<b>✓</b>
Right Hand Side Front Tyre	<b>✓</b>	Right Hand Side Rear Tyre	•
Spare Tyre	<b>✓</b>		
Life remaining			
LUO Frank Tres			.050/
LHS Front Tyre	<75%	LHS Rear Tyre	<65%
RHS Front Tyre	<75% <75%	LHS Rear Tyre  RHS Rear Tyre	<65%



## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE