

Car Report



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2016 FORD FOCUS AMBIENTE | 152,590 KM

VIN: WF0BC2KBXGLD45426

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Enjoy your drive with bluetooth



Music System

Enjoy your drive with music system



Amazing Comfort

Power driver seat

Basic Details

| Yes | Specs | GCC | 152590 | Kilometers | |
|---------------------|----------------------|------------|-------------------|------------------|---|
| Basic | Option Type | * == | 1.5L | Engine | • |
| Front Wheel Drive | Drive | ւ⊗ւ ւ⊕ւ | Automatic | Transmission | |
| Petrol | Fuel | P | SEDAN | Body Type | |
| Exterior Color Blue | Exterior Color | | Steel Wheels | Wheel Type | |
| 4 Airbags | Number of Airbags |)Å | Fabric Trim | Interior Trim | * |
| 2 Keys | Number of keys | R | 5 Seats | Seating Capacity | Â |
| | | | WF0BC2KBXGLD45426 | VIN number | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| Exteriors | | | |
|------------------------------------|---|--------------------|---|
| Rear Bumper Spoiler | Image: A start of the start of | Halogen Headlights | Image: A start of the start of |
| Comfort & Convenience | | | |
| Steering Mounted Audio Controls | ~ | Rear Defogger | ~ |
| ্যিন্স Entertainment | | | |

| Bluetooth Player | ~ | USB player | Image: A start of the start of |
|---------------------|---|----------------------|---|
| Safety & Security | | | |
| Airbag Driver Front | ~ | ABS | |
| Central Locking | ~ | Child Safety Locking | |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

| Passed | | | |
|--|-----|---|-----|
| 🕾 Exterior | | | |
| Doors condition | | | |
| Front left door | ~ | Front right door Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm | (!) |
| Rear left door Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm | ! | Rear right door Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm | (!) |
| Fenders Condition | | | |
| Left Fender Condition: Light Scuffing < 50 mm | (!) | Right Fender Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm | (!) |
| Quarter Panels Condition | | | |
| Left Quarter Panel Condition: Light Scuffing<50mm | (!) | Right Quarter Panel Condition: Low Visual Dent < 30mm, Light Scuffing<50mm | (!) |
| Front Bumper Condition | | | |
| Front Bumper | ~ | | |
| Rear Bumper Condition | | | |
| Rear Bumper Rear Bumper: Light Scuffing < 80mm | (!) | | |
| Hood Condition Hood Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm | (!) | | |
| Trunk Condition Trunk Door Trim: Light Scuffing < 50mm | ! | | |
| Trunk conditon | | | |
| Trunk | ~ | | |
| Roof Condition | | | |

| Roof | | | |
|---|----------------------|---|----------------------|
| Pillars Condition | | | |
| Left A Pillar | ~ | Right A Pillar Inner Condition: Light Scuffing | ! |
| Left A to B Pillar Beading | ~ | Right A to B Pillar Beading | ~ |
| Right A to B Pillar | ~ | Left B Pillar | ~ |
| Left B Pillar Trim | ~ | Left B to C Pillar Beading | |
| Right C Pillar Trim | ~ | Right B to C Pillar | ~ |
| Right B to C Pillar Beading | | Left C Pillar Chip < 5mm | ! |
| Running Board Condition Left Running Board Front Left Sill Trim: Scratch < 80mm Windshield Condition | (!) | Right Running Board Front Right Sill Trim: Light Scuffing < 80mm | (!) |
| Front Windshield Condition: Passenger Side/Light Scuffing<50mm, Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm | (!) | Rear Windshield Tint Fair Use Wear < 30mm | (!) |
| Structural Assessment | | | |
| Chassis Condition | | Radiator Support | ~ |
| Apron | ~ | Boot Floor | ~ |
| Firewall Condition | | Cowl Top | ~ |
| Head Light Support Condition | ~ | | |
| Cowl Top | | | |
| Cowl Top | ~ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | | Left Side Mirror | |
| Right Side Mirror Body: Scratch < 50mm | (!) | Right Hand Side Mirror | ~ |
| Alloy Wheel/ Rim | | | |
| Spare Alloy/ Rim Condition | ~ | | |

| Wheel Arch | Image: A start of the start of | Wheel cover | |
|------------------------------------|---|--|----------------------|
| Antenna | | Grill Condition Light Scuffing < 50mm | (!) |
| Monogram | Image: A start of the start of | Window Glass | |
| Wiper | Image: A start of the start of | | |
| Panel Condition | | | |
| Rear Trunk Panel Scratch < 50mm | ! | | |

Engine & Transmission

| Engine | | | |
|--------------------------------|---|--------------------|---|
| Engine Body | | Engine Performance | Image: A start of the start of |
| Engine Oil (Condition & Level) | | Exhaust System | |
| Turbocharger/ Supercharger | Image: A start of the start of | Radiator Condition | Image: A start of the start of |
| Radiator Coolant | | | |
| Battery | | | |
| Battery Terminal & Tightness | | | |
| Fuel System | | | |
| Fuel Tank | ~ | | |
| Transmission Operation | | | |
| Gear Shifting | | Drive Axle | ~ |
| Transmission Fluid | Image: A start of the start of | | |
| | | | |

Steering, Suspension & Brakes

| Steering | | | |
|-------------------------------|---|-----------------------|----------------------|
| Steering wheel | ~ | | |
| Brake System | | | |
| Parking Brake Button Faded | ! | Brake Master Cylinder | |
| Brake Disc & Brake Pad | ~ | Brake Fluid | |

| Pedals | |
|-----------------|--|
| Suspension | |
| Shock Absorbers | |

| | Electricals, | Controls | & | Lights | |
|--|--------------|----------|---|--------|--|
|--|--------------|----------|---|--------|--|

| Keys | | | |
|---|---|---|---|
| Master Key | | Spare Key(s) | Image: A start of the start of |
| Door Locks | | | |
| Child Safety Locking | ~ | | |
| Dashboard | | | |
| Instrument Panel | ~ | | |
| Airbags | | | |
| Airbags | ~ | | |
| Controls | ~ | Infotainment Display | Image: A start of the start of |
| Engine Sensors | ~ | OBD Connector | ~ |
| Music System | Image: A start of the start of | | |
| Lights | | | |
| Headlight Left: Light Scuff Marks < 50mm | (!) | Interior Lights | |
| Tail Light Cluster | ~ | Turn Signal Lights Right ORVM: Light Scuffing < 50mm | (!) |
| License Plate Light | ~ | | |
| Air Conditioning | | | |
| AC Cooling | ~ | AC Switch Button(s) Faded | (!) |
| AC System Leaks | ~ | Center AC Vent | Image: A start of the start of |
| Front Right AC Vent | ~ | Heater | ✓✓ |
| USB Charging Port | ~ | Power/ Manual Windows | ~ |

▲ Interiors & Luggage

| Dashboard And Instrument Panel Dashboard And Instrument Panel: Light Scuffing/Crack | ! | Central Console Box: Minor Crack/Fair Use Wear/ Scuffing | (!) |
|---|---|---|---|
| Cup Holder | | Glove Box | |
| Steering Wheel Steering Wheel Fair Use Wear | (!) | Sunvisor Left: Sunvisor LHS Minor Crack/Fair Use Wear | (!) |
| Seat Upholstery Driver Seat: Minor Fair Wear/Fade off | ! | Manual Seat Movement | |
| Seat Belts | | Head Rest | |
| Door Controls And Trim Front Left Door: Light Scuffing, Light Scuffing/ Disfiguration | (!) | Grab Handle | ~ |
| Carpet | | Headliner Front Left: Light Smudge/Disfiguration | (!) |
| Rear View Mirror | | Toolkit | |
| 🕲 Tyres | | | |
| Tyres Condition | | | |
| Left Hand Side Front Tyre | Image: A start of the start of | Left Hand Side Rear Tyre | Image: A start of the start of |
| Right Hand Side Front Tyre | Image: A start of the start of | Right Hand Side Rear Tyre | Image: A start of the start of |
| Spare Tyre | | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <75% | LHS Rear Tyre | <85% |
| RHS Front Tyre | <75% | RHS Rear Tyre | <85% |
| Spare Tyre | <75% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE