

Car Report



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2017 MITSUBISHI MONTERO SPORT GLS MID | 104,443 KM

VIN: MMEMC21X7HH004184

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

Yes	Specs	GCC	104443	Kilometers	
Semi Loaded	Option Type	(*) () () () () () () () () () () () () ()	3.0L	Engine	
Rear Wheel Drive	Drive	ו∲ו ו∱ו	Automatic	Transmission	
Petrol	Fuel		SUV	Body Type	
Exterior Color Blue	Exterior Color		Alloy Wheels	Wheel Type	
2 Airbags	Number of Airbags	ĬÇ ⁰	Leather Trim	Interior Trim	*
1 Keys	Number of keys	E	7 Seats	Seating Capacity	Å
			MMEMC21X7HH004184	VIN number	

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Climate Control AC	~	Cruise Control	~
Rear Armrest with cupholder	~	Steering Mounted Audio Controls	~
Power Folding Mirrors	~	Rear Defogger	~
Central Armrest	~		
🐵 Exteriors			

Fog Light Front	~	Running Lights	~
Halogen Headlights	~		
Safety & Security			
Parking Sensors Rear	~	Reverse Camera	~
Traction Control	~	Airbag Driver Front	~
ABS	~	Central Locking	~
Child Safety Locking	~		
୍ୟ Entertainment			
Bluetooth Player	~	USB player	~

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

 \checkmark

Exterior			
Doors condition			
Front left door Inner Frame: Scratch < 50mm	!	Front right door Frame: Light Scuffing < 50mm	!
Rear left door Panel: Scratch < 50mm	!	Rear right door Panel: Light Scuffing < 50mm	(!)
Fenders Condition Left Fender Condition: Low Visual Dent < 30mm, Light Scuffing < 50 mm	(!)	Right Fender Condition: Light Scuffing < 50mm	(!)
Quarter Panels Condition			
Left Quarter Panel Condition: Scratch < 50mm	(!)	Right Quarter Panel Condition: Low Visual Dent < 30mm, Light Scuffing<50mm	(!)
Front Bumper Condition			
Front Bumper	 		
Rear Bumper Condition Rear Bumper Rear Bumper: Light Scuffing < 80mm	(!)		
Hood Condition Hood Bonnet: Light Scuffing < 50mm	(!)		
Trunk Condition			
Trunk	 Image: A start of the start of		
Trunk conditon			
Trunk	 Image: A start of the start of		
Roof Condition			
Roof Roof Moulding Condition: Minor Rubber Beading Fair Use Wear	(!)		

Pillars Condition


Left A Pillar Condition: Dent < 100mm	!	Right A Pillar	•
Left A to B Pillar Beading	 	Right A to B Pillar Beading	~
Right A to B Pillar	~	Left B Pillar	~
Left B Pillar Trim	 Image: A start of the start of	Left B to C Pillar Beading	~
Right C Pillar Trim	•	Right B to C Pillar Light Scuffing < 80mm	(!)
Right B to C Pillar Beading	 	Left C Pillar	~
Running Board Condition Left Running Board Front Left Sill Trim: Scratch < 80mm	(!)	Right Running Board Condition: Light Scuffing < 80mm	(!)
Windshield Condition Front Windshield	 Image: A start of the start of	Rear Windshield	~
Structural Assessment			
Chassis Condition	~	Radiator Support	~
Apron	~	Boot Floor	~
Firewall Condition	 Image: A start of the start of	Cowl Top	~
Head Light Support Condition	~		
Cowl Top			
Cowl Top	~		
Rear View Mirror Condition			
Left Hand Side Mirror	~	Left Side Mirror	~
Right Side Mirror	~	Right Hand Side Mirror	~
Alloy Wheel/ Rim Left Front Alloy/ Rim Rim: Alloy Edge Scuffing > 50mm	(!)	Left Rear Alloy/ Rim	 Image: A start of the start of
Right Front Alloy/ Rim	~	Right Rear Alloy/ Rim	~
Spare Alloy/ Rim Condition	~		
Wheel Arch	~	Wheel cover	•

Antenna	 	Grill Condition Light Scuffing < 50mm	(!)
Monogram	 	Window Glass	 Image: A start of the start of
Wiper	 		
Panel Condition			
Rear Trunk Panel Scratch < 50mm	(!)		

Engine & Transmission

Engine			
Engine Body	 	Engine Performance	 Image: A start of the start of
Engine Oil (Condition & Level)	 	Exhaust System	
Radiator Condition	 	Radiator Coolant	
Battery			
Battery Terminal & Tightness	 		
Fuel System			
Fuel Cap minor imperfection	(!)	Fuel Tank	
Transmission Operation			
Gear Shifting	 	Drive Axle	
Transmission Fluid	 		

Steering, Suspension & Brakes			
Steering			
Steering wheel	 Image: A start of the start of		
Brake System			
Parking Brake	 Image: A start of the start of	Brake Master Cylinder	~
Brake Disc & Brake Pad	 	Brake Fluid	~
Pedals	 Image: A start of the start of		
Suspension			



▲ Interiors & Luggage

Dashboard And Instrument Panel Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted	!	Central Console Box: Minor Color Low Brightness, Minor Crack/Fair Use Wear/ Scuffing	!
Cup Holder	~	Glove Box	
Steering Wheel Steering Wheel Fair Use Wear	!	Sunvisor Left: Sunvisor LHS Vanity Mirror Cover Damage	(!)
Seat Upholstery Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears, Minor Fair Wear/Fade off	!	Manual Seat Movement	•
Seat Belts	 	Head Rest	
Door Controls And Trim Front Left Door: Light Scuffing, Light Scuffing Disfiguration	(!)	Grab Handle	~
Carpet	 	Headliner Rear Left: Smudge/Disfiguration	(!)
Rear View Mirror	~	Toolkit	~
Tyres			
Tyres Condition			
Left Hand Side Front Tyre	 Image: A start of the start of	Left Hand Side Rear Tyre	 Image: A start of the start of
Right Hand Side Front Tyre	 Image: A start of the start of	Right Hand Side Rear Tyre	•
Spare Tyre	 Image: A start of the start of		
Tyres Depth (Remaining)			
LHS Front Tyre	<90%	LHS Rear Tyre	<90%
RHS Front Tyre	<90%	RHS Rear Tyre	<90%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE