



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2019 SUZUKI CIAZ GL | 89,503 KM

VIN: MA3VC7A15KA375650

Car highlights



Bluetooth

Enjoy your drive with bluetooth



Music System

Enjoy your drive with music system



Amazing Comfort


Power driver seat



Airbag safety


Airbag Driver Front

Basic Details



Specs and features


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.




| Child Safety Locking | ✓ | | |
|----------------------|----------|-------------------|----------|
| ্ৰি Entertainment | | | |
| Bluetooth Player | ✓ | USB Charging Port | ✓ |
| USB player | ✓ | | |
| Exteriors | | | |
| Halogen Headlights | ✓ | | |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



| Left A Pillar | ✓ | Right A Pillar | ✓ |
|--|----------|-----------------------------|----------|
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition Left Running Board Front Left Sill Trim: Scratch < 80mm | ! | Right Running Board | ✓ |
| Windshield Condition Front Windshield Condition: Driver Side/Stone Chip Mark<5mm | . ! | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | • |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | Right Hand Side Mirror | ✓ |
| Alloy Wheel/ Rim | | | |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel Arch | ✓ | Wheel cover | ✓ |
| Grill Condition | ✓ | Monogram | ✓ |
| Window Glass | ✓ | Wiper | ✓ |
| Panel Condition | | | |



| Dashboard | | | |
|--|----------|------------------------------------|----------|
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Infotainment Display | • |
| Engine Sensors | ✓ | OBD Connector | ✓ |
| Music System Audio Inputs: Connectivity Issue | (!) | | |
| Lights | | | |
| Headlight Right: Light Scuff Marks < 50mm | (!) | Interior Lights | ~ |
| Tail Light Cluster | ✓ | Turn Signal Lights | ✓ |
| License Plate Light | ✓ | | |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks minor imperfection | (!) | Center AC Vent Crack/Fair Use Wear | (!) |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| USB Charging Port | ~ | Power/ Manual Windows | ✓ |
| 🖺 Interiors & Luggage | | | |
| Dashboard And Instrument Panel | | | |
| Dashboard And Instrument Panel: Light | ! | Central Console | ✓ |
| Scuffing/Crack | | | |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ✓ | Sunvisor | ✓ |
| Seat Upholstery | | | |
| Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears | (!) | Manual Seat Movement | • |
| | | | |

| Seat Belts | ✓ | Head Rest | • |
|--|----------|---------------------------|----------|
| Door Controls And Trim Front Left Door: Light Scuffing/ Disfiguration | (!) | Grab Handle | • |
| Carpet Trunk Floor Carpet: Fair Use Wear < 80mm | (!) | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |
| Tyres | | | |
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <75% | LHS Rear Tyre | <85% |
| RHS Front Tyre | <75% | RHS Rear Tyre | <85% |
| Spare Tyre | <55% | | |
| | | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE