

Car Report



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2019 PEUGEOT 3008 GT LINE | 54,701 KM

VIN: VF3M45GY1KS022732

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat, Memory Seats & more

Basic Details

Yes	Specs	GCC	54701	Kilometers	
Semi Loaded	Option Type	* ==	1.6L	Engine	•
Front Wheel Drive	Drive	।∕ବୁ∙। ।√ମି∙।	Automatic	Transmission	
Petrol	Fuel	ŗ	SUV	Body Type	
Exterior Color Grey	Exterior Color		Alloy Wheels	Wheel Type	
6 Airbags	Number of Airbags	²⁰	Leather Trim	Interior Trim	*
2 Keys	Number of keys	Ę	5 Seats	Seating Capacity	Â
			VF3M45GY1KS022732	VIN number	

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Comfort & Convenience			
Panoramic Sunroof	~	Cruise Control	~
Memory Seats	~	Steering Mounted Audio Controls	~
Power Tailgate/ Power Trunk	~	Central Armrest	~
Exteriors			
Fog Light Front	~	Running Lights	<

Safety & Security			
Parking Sensors Front	~	Navigation	
Parking Sensors Rear	~	Reverse Camera	
Blind Spot Monitor	~	Front Camera	~
ABS	~	Central Locking	~
្សារា Entertainment			
Bluetooth Player	~	USB Charging Port	
Infotainment System	~		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

~

🕾 Exterior			
Doors condition			
Front left door Condition: Scratched	(!)	Front right door Condition: Scratched, Dented	(!)
Rear left door Condition: Scratched	(!)	Rear right door Condition: Scratched	(!)
Fenders Condition			
Left Fender Condition: Scratched	(!)	Right Fender	~
Quarter Panels Condition Left Quarter Panel Condition: Scratched	(!)	Right Quarter Panel Condition: Scratched	(!)
Front Bumper Condition Front Bumper Condition: Scratched	(!)		
Rear Bumper Condition Rear Bumper Rear Bumper: Scratched	(!)		
Hood Condition Hood Bonnet: Scratched	(!)		
Trunk conditon			
Trunk	 Image: A start of the start of		
Pillars Condition			
Left A Pillar	 Image: A start of the start of	Right A Pillar	\checkmark
Left B Pillar	~	RHS Pillar B Condition	~
RHS Pillar C Condition	~	Left C Pillar	~
Left D pillar	~		
Running Board Condition			

Left Running Board	~	Right Running Board	~
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	 Image: A start of the start of		
Windshield Condition			
Front Windshield		Rear Windshield	
Condition: Beading Missing/Broken	(!)	Real Willushielu	
Structural Assessment			
Chassis Condition	~	Apron	~
Boot Floor	 Image: A start of the start of	Firewall Condition	 Image: A start of the start of
Head Light Support Condition			
No structural damage			
Chassis Conditon		Upper Cross Member Condition	\checkmark
Lower Cross Member Condition	~	Chassis Condition	~
Radiator Support	~		
Cowl Top			
Cowl Top	~		
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror	~	Right Hand Side Mirror	
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	 Image: A start of the start of	Left Rear Alloy/ Rim	~
Right Front Alloy/ Rim	 Image: A start of the start of	Right Rear Alloy/ Rim	~
Grill Condition		Window Glass	~
Wiper	~		
Panel Condition			
Rear Trunk Panel	~		



Engine

Engine Body	 	Engine Performance	~
Engine Oil (Condition & Level)	 	Exhaust System	
Turbocharger/ Supercharger	 	Radiator Condition	~
Radiator Coolant	 		
Battery			
Battery Terminal & Tightness	 		
Transmission Operation			
Transmission Operation	 Image: A start of the start of		

Steering			
Steering wheel	 	Shock absorbers	
Brake System			
Parking Brake	 	Brake Master Cylinder	
Brake Fluid	 		
Suspension			
Suspension	~		

Electricals, Controls & Lights

Steering, Suspension & Brakes

Keys			
Master Key	 		
Door Locks			
Central Locking Operation	~	Child Safety Locking	~
Dashboard			
Instrument Panel	~		
Cruise Control	~	Radar (If Equipped)	~
Navigation System	 	Music System	~
Bluetooth Operations	~		
Sunroof Operation			

Sunroof	~		
Camera	~		
Lights			
Lights	 	Running lights	~
Headlight	~	Interior Lights	~
Tail Light Cluster	~	Turn Signal Lights	~
License Plate Light	~	Back Up Light	~
Fog Lights	~	Trunk Lid Release/Trunk Lid Light Operation	~
Air Conditioning			
AC Air Direction Switch	~	Blower Motor	~
Compressor	~	Condenser	~
AC Cooling	 Image: A start of the start of	AC Switch	~
AC System Leaks	~	Heater	~
AC Heater Operation Switch	~	AC Blower Switch	~
AC Wind Direction	 		
Rear Defogger	~	USB Charging Port	~
Power/ Manual Windows	~	Seat Heaters	~
Memory Seats	~		

▲ Interiors & Luggage

Dashboard And Instrument Panel	~	Central Console Condition: Scratched	!
Cup Holder	~	Sunvisors	~
Seat Upholstery Driver Seat: Depressed/Pressure Mark	(!)	Manual Seat Movement	~
Seat Belts	~	Seat Belt with issues	~
Head Rest	~	Door Controls And Trim	!

Front Right Door: Stained

		Hom Hight Doon Otamod	
Door Hinge Condition	~	Carpet	 Image: A start of the start of
Headliner	~	Rear View Mirror	~
Toolkit	~		
Tyres			
Tyres Condition			
Left Hand Side Front Tyre	 Image: A start of the start of	Left Hand Side Rear Tyre	 Image: A start of the start of
Right Hand Side Front Tyre	~	Right Hand Side Rear Tyre	
Spare Tyre	 Image: A start of the start of		
Tyres Depth (Remaining)			
LHS Front Tyre	<90%	LHS Rear Tyre	<90%
RHS Front Tyre	<90%	RHS Rear Tyre	<90%

<85%

Spare Tyre



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE