

Car Report



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2016 HONDA ACCORD

EX | 100,433 KM

VIN: LUCCR2667G3406467

Car highlights



Sunroof

This car has a sunroof



Cruise control

Cruise control to drive with ease & comfort



Music System

Enjoy your drive with music system



Amazing Comfort

Power driver seat

Basic Details

Yes	Specs	GCC	100433	Kilometers	
Mid Option	Option Type	* [==]	2.4L	Engine	•
Front Wheel Drive	Drive	।∳ा ।⊕।	Automatic	Transmission	
Petrol	Fuel	<u>"</u>	SEDAN	Body Type	(III)
Exterior Color Grey	Exterior Color		Alloy Wheels	Wheel Type	
8 Airbags	Number of Airbags	² Co	Fabric Trim	Interior Trim	*
2 Keys	Number of keys	Ę	5 Seats	Seating Capacity	Â
			LUCCR2667G3406467	VIN number	

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

🖄 Comfort & Convenience		
Sunroof	~	Cruise Control
Steering Mounted Audio Controls	~	
Exteriors		
Fog Light Front	~	
Safety & Security		

Parking Sensors Rear	 		
୍ୟିଣ Entertainment			
USB Charging Port	~	Infotainment System	~

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

 \checkmark

അ Exterior			
Doors condition			
Front left door Weather Strip: Minor Rubber Fair Use Wear	(!)	Front right door Panel: Paint Chip-off < 5mm	(!)
Rear left door Panel: Paint Chip-off < 5mm	(!)	Rear right door Frame: Light Scuffing < 50mm	!
Fenders Condition Left Fender			
Condition: Low Visual Dent < 30mm, Light Scuffing < 50 mm	(!)	Right Fender	
Quarter Panels Condition Left Quarter Panel			
Condition: Low Visual Dent<30mm, Chip<5mm	!	Right Quarter Panel	~
Front Bumper Condition			
Front Bumper Condition: Misaligned	(!)		
Rear Bumper Condition			
Rear Bumper Rear Bumper: Light Scuffing < 80mm	(!)		
Hood Condition			
Hood Bonnet: Paint Chip-off < 5mm, Light Scuffing < 50mm	!		
Trunk Condition			
Trunk	 Image: A start of the start of		
Trunk conditon			
Trunk	 Image: A start of the start of		
Roof Condition			
Roof Roof Moulding Condition: Minor Rubber	(!)		

Beading Fair Use Wear

Pillars Condition

Left A Pillar	~	Right A Pillar	
Left A to B Pillar Beading	 Image: A start of the start of	Right A to B Pillar Beading	
Right A to B Pillar	~	Left B Pillar	~
Left B Pillar Trim	 Image: A start of the start of	Left B to C Pillar Beading	~
Right C Pillar Trim	 Image: A start of the start of	Right B to C Pillar	~
Right B to C Pillar Beading	 Image: A start of the start of	Left C Pillar	~
Running Board Condition Left Running Board Front Left Sill Trim: Minor Scuffing < 80mm Sunroof Glass Condition (If Equipped) Sun Roof Glass	!	Right Running Board Front Right Floor Trim: Light Scuffing < 80mm	(!)
Windshield Condition Front Windshield Beading: Mouldings Crack/ Fair Use Wear < 50mm	!	Rear Windshield	~
Structural Assessment			
Chassis Condition	 	Radiator Support	
Apron	 Image: A start of the start of	Boot Floor	•
Firewall Condition	~	Cowl Top Beading: Crack/Fair Use Wear>50mm	!
Head Light Support Condition	~		
Cowl Top			
Cowl Top	~		
Rear View Mirror Condition Left Hand Side Mirror Body: Chip < 5mm	(!)	Left Side Mirror	
Right Side Mirror Body: Paint Chip-off < 5mm	(!)	Right Hand Side Mirror	~
Alloy Wheel/ Rim Left Front Alloy/ Rim			
Rim: Alloy Edge Scuffing > 50mm	!	Left Rear Alloy/ Rim Rim: Alloy Edge Scuffing > 50mm	!

Right Front Alloy/ Rim	 	Right Rear Alloy/ Rim Rim: Alloy Edge/Scuffing<80mm	(!)
Spare Alloy/ Rim Condition	 		
Grill Condition Light Scuffing < 50mm	(!)	Monogram	~
Window Glass	 	Wiper	•
Panel Condition			
Rear Trunk Panel Scratch < 50mm	(!)		

Engine & Transmission

Engine			
Engine Body	 	Engine Performance	
Engine Oil (Condition & Level)	 	Exhaust System	 Image: A start of the start of
Radiator Condition	 	Radiator Coolant	 Image: A start of the start of
Battery			
Battery Terminal & Tightness	 		
Fuel System			
Fuel Cap	 Image: A start of the start of	Fuel Tank	 Image: A start of the start of
Transmission Operation			
Gear Shifting	~	Drive Axle	 Image: A start of the start of
Transmission Fluid	~		

Steering, Suspension & Brakes			
Steering			
Steering wheel	 		
Brake System			
Parking Brake	 	Brake Master Cylinder	~
Brake Disc & Brake Pad	 	Brake Fluid	
Pedals	 		

Suspension

Electricals, Controls & Lights	5		
Keys			
Master Key	~	Spare Key(s)	
Door Locks			
Child Safety Locking	~		
Dashboard			
Instrument Panel	~		
Airbags			
Airbags	~		
Controls	~	Cruise Control	~
Infotainment Display	~	Engine Sensors	~
OBD Connector	~	Music System	~
Sunroof Operation			
Sunroof	~		
Lights			
Headlight Left: Light Scuff Marks < 50mm	!	Interior Lights	~
Tail Light Cluster	~	Turn Signal Lights	
Daylight Running Lights	 Image: A start of the start of	License Plate Light	\checkmark
Fog Lights	 		
Air Conditioning			
AC Cooling	~	AC Switch	~
AC System Leaks	~	Center AC Vent	
Front Right AC Vent	~	Heater	~
Rear Blower Switch	 		
Rear Defogger	~	USB Charging Port	~

 \checkmark

≜ Interiors & Luggage

Dashboard And Instrument Panel	~	Central Console Gear Shift Knob: Buttons Faded	(!)
Cup Holder	 	Glove Box	 Image: A start of the start of
Steering Wheel Color Faded	(!)	Sunvisor	
Seat Upholstery Driver Seat: Minor Smudge/ Cracks	(!)	Manual Seat Movement	
Seat Belts	~	Head Rest	~
Door Controls And Trim	 Image: A start of the start of	Grab Handle	
Carpet Front Left Floor Mat: Smudge/Burn/Crack	(!)	Headliner	
Rear View Mirror	 Image: A start of the start of	Toolkit	~

 \checkmark

Tyres

Tyres Condition			
Left Hand Side Front Tyre	 	Left Hand Side Rear Tyre	 Image: A start of the start of
Right Hand Side Front Tyre	~	Right Hand Side Rear Tyre	 Image: A start of the start of
Spare Tyre	 Image: A start of the start of		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE