



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2019 MITSUBISHI PAJERO GLS | 75,750 KM

VIN: JE4NR52R0KJ700253

Car highlights



Four wheel drive

This car has a Four wheel drive



Cruise control

Cruise control to drive with ease & comfort



Bluetooth


Enjoy your drive with bluetooth



Amazing Comfort


Power driver seat

Basic Details



Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.




| Running Lights | ✓ | Rear Bumper Spoiler | ✓ |
|----------------------|----------|-----------------------|----------|
| Halogen Headlights | ~ | | |
| Safety & Security | | | |
| Parking Sensors Rear | ~ | Reverse Camera | • |
| Traction Control | ✓ | Airbag Curtain Shield | ✓ |
| Airbag Driver Front | ✓ | ABS | ✓ |
| Central Locking | ✓ | Child Safety Locking | ~ |
| ☐ Entertainment | | | |
| Bluetooth Player | ✓ | USB Charging Port | ✓ |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality





Front right door Frame: Light Scuffing < 50mm, Paint Chip-off Rear right door Moulding: Paint Chip-off < 5mm, Light (!)Scuffing < 50mm Right Fender Condition: Paint Chip-off < 5mm, Light Scuffing < 50mm Right Quarter Panel Condition: Chip<5mm, Light Scuffing<50mm

Trunk Condition

Trunk

Door Trim: Scuff/ Disfiguration < 50mm, Light

Scuffing < 50mm

Trunk condition

Trunk



Roof Condition Roof Pillars Condition Right A Pillar Left A Pillar Condition: Light Scuffing<50mm Right A to B Pillar Beading Left A to B Pillar Beading Left B Pillar Right A to B Pillar Left B Pillar Trim Left B to C Pillar Beading Right C Pillar Trim Right B to C Pillar Light Scuffing Light Scuffing < 80mm Left C Pillar Right B to C Pillar Beading Light Scuffing < 50mm **Running Board Condition** Left Running Board Right Running Board (!) Rear Right Floor Trim: Light Scuffing < 80mm Front Left Floor Trim: Light Scuffing < 80mm Sunroof Glass Condition (If Equipped) Sun Roof Glass (!) Noise/Vibration Windshield Condition Front Windshield Rear Windshield Structural Assessment **Chassis Condition** Radiator Support **Boot Floor** Apron Condition: Light Scuffing < 80mm Firewall Condition Cowl Top Head Light Support Condition Cowl Top Cowl Top Rear View Mirror Condition Left Hand Side Mirror (!) Left Side Mirror Body: Chip < 5mm, Light Scuffing < 50mm Right Side Mirror (!) Right Hand Side Mirror Body: Paint Chip-off < 5mm Alloy Wheel/ Rim


| Left Front Alloy/ Rim Rim: Alloy Face Light Scuffing < 50mm | ! | Left Rear Alloy/ Rim Rim: Alloy Face Light Scuffing < 50mm, Alloy Edge Scuffing > 50mm | (!) |
|---|----------|--|----------|
| Right Front Alloy/ Rim Rim: Alloy Edge Scuffing < 80mm | (!) | Right Rear Alloy/ Rim Rim: Alloy Face/Light Scuffing<50mm | (!) |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel cover | • | Grill Condition | ✓ |
| Monogram | ✓ | Window Glass | ✓ |
| Wiper | ✓ | | |
| Panel Condition | | | |
| Rear Trunk Panel Scratch < 50mm | ! | | |
| Engine & Transmission | | | |
| Engine | | | |
| Engine Body | | Engine Performance | |
| Damage & Leaks: Engine Vibration By Characteristics | ! | Idle Condition: Characteristic Pulley Noise, Engine Characteristic Vibration | (!) |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |
| Battery | | | |
| Battery Terminal & Tightness | ✓ | | |
| Fuel System | | | |
| Fuel Tank | ✓ | | |
| Transmission Operation | | | |
| Gear Shifting | (!) | Drive Axle | |
| Minor Gear Shift Shock | \odot | DIIVE ANIE | |
| willor Gear Shift Shock | | | |

Steering

Steering wheel



Brake System



| Air Conditioning | | | |
|--|----------------|--|----------|
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | Center AC Vent | ✓ | |
| Front Right AC Vent | ~ | Heater | ✓ |
| Rear Blower Switch | ~ | Rear Left AC Vent | ✓ |
| Parking Sensors | ✓ | Rear Defogger | ✓ |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |
| 🖺 Interiors & Luggage | | | |
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder | ✓ | Glove Box | • |
| Steering Wheel Steering Wheel Fair Use Wear | ! | Sunvisor | ✓ |
| Seat Upholstery Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears, Minor Smudge/ Cracks, Minor Fair Wear/Fade off | ! | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Grab Handle | • |
| Carpet | • | Headliner Rear Left: Smudge/Disfiguration, Light Scuffing, Fair Use Wear | (!) |
| Rear View Mirror | ✓ | Toolkit | ~ |
| Tyres | | | |
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ~ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ~ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| | | | |

| Tyres Depth (Remaining) | | | |
|-------------------------|------|---------------|------|
| LHS Front Tyre | <75% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <75% | RHS Rear Tyre | <65% |
| Spare Tyre | <65% | | |
| | | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE