



#### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



# 2015 HYUNDAI TUCSON GL | 109,724 KM

VIN: KMHJT81C5FU961855

## **Car highlights**



## **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear



#### **Bluetooth**

Enjoy your drive with bluetooth



## **Music System**


Enjoy your drive with music system



## **Amazing Comfort**


Power driver seat

### **Basic Details**



## **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



Safety & Security					
Parking Sensors Rear	~	Reverse Camera	<b>✓</b>		
Airbag Driver Front	~	ABS	<b>✓</b>		
Central Locking	•	Child Safety Locking	<b>✓</b>		
্ৰি Entertainment					
Rear Seat Entertainment	<b>✓</b>	Bluetooth Player	•		
USB player	<b>✓</b>				

### **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality




Trunk

Roof

**Roof Condition** 

Front right door (!) Weather Strip: Minor Rubber Fare Use Wear Rear right door (!)Weather Strip: Minor Fair Use Rubber Wear Right Fender (!)Condition: Light Scuffing < 50mm Right Quarter Panel Condition: Low Visual Dent < 30mm, Chip>5mm

## **Pillars Condition** Left A Pillar Right A Pillar Left A to B Pillar Beading Right A to B Pillar Beading Left B Pillar Right A to B Pillar Condition: Light Scuffing Scratch < 50mm Left B Pillar Trim Left B to C Pillar Beading Right C Pillar Trim Right B to C Pillar Left C Pillar Right B to C Pillar Beading Low Visual Dent < 30mm **Running Board Condition** Left Running Board Right Running Board Front Right Floor Trim: Light Scuffing < 80mm Rear Left Sill Trim: Light Scuffing < 80mm Windshield Condition Front Windshield Rear Windshield Structural Assessment **Chassis Condition** Radiator Support **Boot Floor** Apron Door Skirting: Colour Mismatch/ Fade/ Fair Use Wear Firewall Condition Cowl Top Head Light Support Condition Cowl Top Cowl Top Rear View Mirror Condition Left Hand Side Mirror Left Side Mirror Right Side Mirror Right Hand Side Mirror **Body: Paint Defects** Alloy Wheel/ Rim Left Front Alloy/ Rim Left Rear Alloy/ Rim Right Front Alloy/ Rim Right Rear Alloy/ Rim Rim: Alloy Edge Scuffing < 80mm Spare Alloy/ Rim Condition



Parking Sensors




# **Electricals, Controls & Lights**

F Electricals, Controls & Lights			
Keys			
Master Key	(!)	Spare Key(s)	
Button Faded			
Door Locks			
Child Safety Locking	<b>✓</b>		
Dashboard			
Instrument Panel	<b>✓</b>		
Airbags			
Airbags	<b>✓</b>		
Controls	~	Infotainment Display	<b>✓</b>
Engine Sensors	~	OBD Connector	<b>✓</b>
Music System	~	Camera	<b>✓</b>
Lights			
Headlight		Interior Lights	
Left: Light Scuff Marks < 50mm	!	interior Lights	
Tail Light Cluster	(!)	Turn Signal Lights	(!)
Right Tail Lamp: Light Scuffing < 50mm	$\odot$	Right ORVM: Light Scuffing < 50mm	$\odot$
License Plate Light	<b>✓</b>	Fog Lights	<b>✓</b>
Air Conditioning			
AC Cooling		AC Switch	(!)
7.6 Cooming		Button(s) Faded	$\odot$
AC System Leaks	<b>✓</b>	Center AC Vent	<b>✓</b>
Front Right AC Vent	<b>✓</b>	Heater	~
Rear Blower Switch	!		
Crack			
Parking Sensors	~	Rear Defogger	(!)

Not Working

(!)





# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE