

Car Report



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2019 RENAULT CAPTUR PE | 81,711 KM

Car highlights



Amazing Comfort

Power driver seat



Tilt Steering wheel

Tilt steering wheel for extra comfort

Basic Details

Yes	Specs	GCC	81711	Kilometers	
e Basic	Option Type		1.6L	Engine	•
Front Wheel Drive	Drive	ו-ੴ- ו-∯-ו	Automatic	Transmission	
Petrol	Fuel		SUV	Body Type	(<u> </u>
olor Exterior Color Blue	Exterior Color		Steel Wheels	Wheel Type	
4 Airbags	Number of Airbags	²⁰	Fabric Trim	Interior Trim	*
keys 1 Keys	Number of keys	G	5 Seats	Seating Capacity	Å
			VF12RRJR2KW459691	VIN number	

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Le Comfort & Convenience			
Cruise Control	 	Steering Mounted Audio Controls	~
୍ୟିଣ Entertainment			
USB Charging Port	~	Infotainment System	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed			
അ Exterior			
Doors condition			
Front left door	 	Front right door Panel: Paint Chip-off < 5mm	(!)
Rear left door	 	Rear right door Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm	(!)
Fenders Condition			
Left Fender	~	Right Fender	~
Quarter Panels Condition Left Quarter Panel Trim: Light Scuffing<80mm	(!)	Right Quarter Panel	•
Front Bumper Condition			
Front Bumper	 		
Rear Bumper Condition Rear Bumper Rear Bumper: Light Scuffing < 80mm	(!)		
Hood Condition Hood Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm	(!)		
Trunk Condition Trunk Door Trim: Light Scuffing < 50mm	(!)		
Trunk conditon			
Trunk	~		
Roof Condition			
Roof	 Image: A start of the start of		
Pillars Condition			

Left A Pillar Inner Condition: Fair Use Wear	(!)	Right A Pillar	•
Left A to B Pillar Beading	~	Right A to B Pillar Beading	
Right A to B Pillar	~	Left B Pillar	~
Left B Pillar Trim	~	Left B to C Pillar Beading	~
Right C Pillar Trim	~	Right B to C Pillar	
Right B to C Pillar Beading	~	Left C Pillar	~
Running Board Condition			
Left Running Board	~	Right Running Board	~
Windshield Condition Front Windshield Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm	!	Rear Windshield	•
Structural Assessment			
Chassis Condition	 	Radiator Support	~
Apron	~	Boot Floor	
Firewall Condition	~	Cowl Top	~
Head Light Support Condition	~		
Cowl Top			
Cowl Top	 		
Rear View Mirror Condition			
Left Hand Side Mirror	~	Left Side Mirror	
Right Side Mirror	 Image: A start of the start of	Right Hand Side Mirror	~
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	~		
Wheel Arch	~	Wheel cover	~
Antenna	~	Grill Condition Light Scuffing < 50mm	!
Monogram	~	Window Glass	~

Wiper Operation: Cover Missing	!		
Panel Condition			
Rear Trunk Panel	~		
Engine & Transmission			
Engine			
Engine Body	 Image: A start of the start of	Engine Performance	 Image: A start of the start of
Engine Oil (Condition & Level)	 	Exhaust System	~
Radiator Condition	~	Radiator Coolant	~
Battery			
Battery Terminal & Tightness	~		
Fuel System			
Fuel Tank	~		
Transmission Operation			
Gear Shifting	 	Drive Axle	~
Transmission Fluid	 Image: A start of the start of		

Steering, Suspension & Brakes

Steering			
Steering wheel	 Image: A start of the start of		
Brake System			
Parking Brake	 	Brake Master Cylinder	 Image: A start of the start of
Brake Disc & Brake Pad	 Image: A start of the start of	Brake Fluid	 Image: A start of the start of
Pedals	 		
Suspension			
Shock Absorbers	~		

Electricals, Controls & Lights

Keys

Master Key	~		
Door Locks			
Child Safety Locking	 Image: A start of the start of		
Dashboard			
Instrument Panel	 Image: A start of the start of		
Airbags			
Airbags	~		
Controls	~	Cruise Control	~
Infotainment Display	~	Engine Sensors	~
OBD Connector	~	Music System	~
Lights			
Headlight	~	Interior Lights	~
Tail Light Cluster	 Image: A start of the start of	Turn Signal Lights	~
Daylight Running Lights	~	License Plate Light	 Image: A start of the start of
Air Conditioning			
AC Cooling	~	AC Switch	
AC System Leaks	 Image: A start of the start of	Center AC Vent	
Front Right AC Vent	~	Heater	~
Rear Defogger Extensive Wear Of Strip	(!)	USB Charging Port	•
Power/ Manual Windows	~		

▲ Interiors & Luggage

Dashboard And Instrument Panel Dashboard And Instrument Panel: Color Faded, Light Disfiguration	(!)	Central Console Cigarette Lighter: Cigarette Lighter Missing	!
Cup Holder	 	Glove Box	~
Steering Wheel	~	Sunvisor Left: Sunvisor LHS Minor Crack/Fair Use	(!)

Wear, Sunvisor RHS Minor Crack/Damage

Seat Upholstery	~	Manual Seat Movement	 Image: A start of the start of
Seat Belts	~	Head Rest	~
Door Controls And Trim Front Left Door: Light Scuffing	(!)	Grab Handle	~
Carpet	 	Headliner Front Left: Light Smudge/Disfiguration	(!)
Rear View Mirror	~	Toolkit	 Image: A start of the start of
I Tyres			
Tyres Condition			
Left Hand Side Front Tyre	 Image: A start of the start of	Left Hand Side Rear Tyre	~
Right Hand Side Front Tyre	 Image: A start of the start of	Right Hand Side Rear Tyre	~
Spare Tyre	 Image: A start of the start of		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<40%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE