

Car Report



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2020 MAZDA CX 3 GS | 105,317 KM

VIN: JM7DKAW79L1430779

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Rear



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

| Yes | Specs | GCC | 105317 | Kilometers | |
|---------------------|----------------------|----------------|-------------------|------------------|---|
| Basic | Option Type | * == | 2.0L | Engine | • |
| Front Wheel Drive | Drive | וי∯יו ו-∯יו | Automatic | Transmission | |
| Petrol | Fuel | ŗ | SUV | Body Type | |
| Exterior Color Grey | Exterior Color | | Alloy Wheels | Wheel Type | |
| 2 Airbags | Number of Airbags | ,jo | Fabric Trim | Interior Trim | * |
| 2 Keys | Number of keys | È | 5 Seats | Seating Capacity | Â |
| | | | JM7DKAW79L1430779 | VIN number | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| Comfort & Convenience | | | |
|----------------------------------|----------------------|------------------------------------|---|
| Climate Control AC | ~ | Cruise Control | ~ |
| Rear Armrest with cupholder | ~ | Steering Mounted Audio Controls | ~ |
| Rear Defogger | ~ | Central Armrest | ~ |
| 🕾 Exteriors | | | |
| Fog Light Front | | Rear Bumper Spoiler | • |

| Halogen Headlights | | | |
|----------------------|---|----------------------|---|
| 吟 Safety & Security | | | |
| Parking Sensors Rear | ~ | Traction Control | ~ |
| Airbag Driver Front | Image: A start of the start of | ABS | ~ |
| Central Locking | Image: A start of the start of | Child Safety Locking | ~ |
| ୍ୟିଣ Entertainment | | | |
| Bluetooth Player | Image: A start of the start of | USB player | Image: A start of the start of |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed

 \checkmark

| 🕾 Exterior | | | |
|--|---|---|-----|
| Doors condition | | | |
| Front left door Handle: Paint Chip-off < 5mm | ! | Front right door Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm | (!) |
| Rear left door Panel: Scratch < 50mm, Dent < 30mm | (!) | Rear right door Panel: Light Scuffing < 50mm | (!) |
| Fenders Condition Left Fender Condition: Light Scuffing < 50 mm, Paint Chip-off < 5mm | (!) | Right Fender Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm | ! |
| Quarter Panels Condition Left Quarter Panel Condition: Dent < 30mm | (!) | Right Quarter Panel | ~ |
| Front Bumper Condition | | | |
| Front Bumper | | | |
| Rear Bumper Condition Rear Bumper Rear Bumper: Light Scuffing < 80mm | (!) | | |
| Hood Condition Hood Bonnet: Light Scuffing < 50mm | ! | | |
| Trunk Condition | | | |
| Trunk | Image: A start of the start of | | |
| Trunk conditon | | | |
| Trunk | Image: A start of the start of | | |
| Roof Condition | | | |
| Roof | ~ | | |
| Pillars Condition | | | |

| Left A Pillar | Image: A start of the start of | Right A Pillar | ~ |
|------------------------------|---|---|----------------------|
| Left A to B Pillar Beading | | Right A to B Pillar Beading | ~ |
| Right A to B Pillar | | Left B Pillar | ~ |
| Left B Pillar Trim | Image: A start of the start of | Left B to C Pillar Beading | ~ |
| Right C Pillar Trim | Image: A start of the start of | Right B to C Pillar | ~ |
| Right B to C Pillar Beading | | Left C Pillar | ~ |
| Running Board Condition | | | |
| Left Running Board | • | Right Running Board Front Right Sill Trim: Light Scuffing < 80mm | (!) |
| Windshield Condition | | | |
| Front Windshield | | Rear Windshield | ~ |
| Structural Assessment | | | |
| Chassis Condition | | Radiator Support | ~ |
| Apron | | Boot Floor | ~ |
| Firewall Condition | | Cowl Top | ~ |
| Head Light Support Condition | | | |
| Cowl Top | | | |
| Cowl Top | | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | | Left Side Mirror | ~ |
| Right Side Mirror | | Right Hand Side Mirror | ~ |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | Image: A start of the start of | Left Rear Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm | ! |
| Right Front Alloy/ Rim | Image: A start of the start of | Right Rear Alloy/ Rim | |
| Spare Alloy/ Rim Condition | Image: A start of the start of | | |
| Wheel Arch | ~ | Wheel cover | ~ |
| Antenna | | Grill Condition Light Scuffing < 50mm | (!) |

| Monogram | Image: A start of the start of | Window Glass | Image: A start of the start of |
|--|---|--------------------|---|
| Wiper | | | |
| Panel Condition | | | |
| Rear Trunk Panel Paint Chip Off < 5mm | (!) | | |
| Engine & Transmission | | | |
| Engine | | | |
| Engine Body | | Engine Performance | ~ |
| Engine Oil (Condition & Level) | | Exhaust System | |
| Radiator Condition | | Radiator Coolant | Image: A start of the start of |
| Battery | | | |
| Battery Terminal & Tightness | | | |
| Fuel System | | | |
| Fuel Cap | | Fuel Tank | Image: A start of the start of |

| Transmission Operation | | | |
|------------------------|---|------------|---|
| Gear Shifting | Image: A start of the start of | Drive Axle | ~ |
| Transmission Fluid | Image: A start of the start of | | |
| | | | |

| Ø | Steering, | Suspension | & | Brakes |
|---|-----------|------------|---|---------------|
|---|-----------|------------|---|---------------|

| Steering | | | |
|------------------------|---|-----------------------|----------------------|
| Steering wheel | | | |
| Brake System | | | |
| Parking Brake | | Brake Master Cylinder | |
| Brake Disc & Brake Pad | Image: A start of the start of | Brake Fluid | |
| Pedals | | | |
| Suspension | | | |
| Shock Absorbers | Image: A start of the start of | | |
| | | | |

| F | Electricals, | Controls | & | Lights |
|----------|--------------|----------|---|--------|
|----------|--------------|----------|---|--------|

Keys

| USB Charging Port | ~ | Power/ Manual Windows | ~ |
|----------------------|----------------------|---|----------------------|
| Parking Sensors | | Rear Defogger Extensive Wear Of Strip | (!) |
| Front Right AC Vent | ~ | Heater | |
| AC System Leaks | | Center AC Vent | ~ |
| AC Cooling | ~ | AC Switch | ~ |
| Air Conditioning | | | |
| License Plate Light | ~ | Fog Lights | ~ |
| Tail Light Cluster | ~ | Turn Signal Lights | ~ |
| Headlight | | Interior Lights | ~ |
| Lights | | | |
| Music System | | Camera | ~ |
| OBD Connector | | Condition: Available - SD Card Missing | ! |
| | · | Navigation System | · |
| Infotainment Display | | Engine Sensors | |
| Controls | ~ | Cruise Control | ~ |
| Airbags | | | |
| Airbags | | | |
| Instrument Panel | ~ | | |
| Dashboard | | | |
| Child Safety Locking | ~ | | |
| Door Locks | | | |
| Master Key | ~ | Spare Key(s) Remote Functions Not Responding | ! |

 \checkmark

▲ Interiors & Luggage

Dashboard And Instrument Panel

Central Console Cigarette Lighter: Cigarette Lighter Missing

(!)

| Cup Holder | ~ | Glove Box | Image: A start of the start of |
|--|---|----------------------|---|
| Steering Wheel Steering Wheel Fair Use Wear | (!) | Sunvisor | |
| Seat Upholstery | ~ | Manual Seat Movement | • |
| Seat Belts | Image: A start of the start of | Head Rest | • |
| Door Controls And Trim | ~ | Grab Handle | Image: A start of the start of |
| Carpet | Image: A start of the start of | Headliner | ~ |
| Rear View Mirror | | Toolkit | Image: A start of the start of |

Tyres

| Tyres Condition | | | |
|----------------------------|----------------------|---------------------------|---|
| Left Hand Side Front Tyre | ~ | Left Hand Side Rear Tyre | ~ |
| Right Hand Side Front Tyre | ~ | Right Hand Side Rear Tyre | Image: A start of the start of |
| Spare Tyre | | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <75% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <75% | RHS Rear Tyre | <65% |
| Spare Tyre | <85% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE