

# **Car Report**



#### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2018 MITSUBISHI ASX GLS | 73,829 KM

VIN: JE4LP21U3JU703811

### Car highlights



**Cruise control** 

Cruise control to drive with ease & comfort



#### **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear



Bluetooth

Enjoy your drive with bluetooth



#### **Amazing Comfort**

Power driver seat

#### **Basic Details**

Kilometers 73	829 GCC	Specs	Yes
Engine 2	2.0L	Option Type	Semi Loaded
Transmission Automa	atic ເ	Drive	Front Wheel Drive
Body Type	SUV 🖳	Fuel	Petrol
Wheel Type     Alloy Wheel	eels 🖗	Exterior Color	Exterior Color White
Mathematical Interior Trim Fabric T	rim ېې	Number of Airbags	2 Airbags
Seating Capacity <b>5 Se</b>	eats 🕅	Number of keys	2 Keys
O O O         O O </th <th>811</th> <th></th> <th></th>	811		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

🖄 Comfort & Convenience			
Climate Control AC	~	Cruise Control	~
Rear Armrest with cupholder	~	Steering Mounted Audio Controls	~
Rear Defogger	~	Central Armrest	~
🕾 Exteriors			
Fog Light Front	~	Roof Rails	~

Running Lights	~	Halogen Headlights	~
Safety & Security			
Navigation	~	Parking Sensors Rear	<ul> <li>Image: A start of the start of</li></ul>
Reverse Camera	~	Traction Control	~
Airbag Driver Front	~	ABS	~
Central Locking	~	Child Safety Locking	~
্যিন্ধ Entertainment			
Rear Seat Entertainment	~	Bluetooth Player	<ul> <li>Image: A start of the start of</li></ul>
USB Charging Port	~	USB player	~

## **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Doors condition       Front right door         Front left door       Panel: Low Visibility Dent < 30mm, Light 1       1         Rear left door       Rear right door       Panel: Low Visual Dent < 30mm, Light 1       1         Scuffing < 50mm       Panel: Low Visual Dent < 30mm, Light 1       1       1         Scuffing < 50mm       Panel: Low Visual Dent < 30mm, Light 1       1       1         Fenders Condition       Panel: Low Visual Dent < 30mm, Light 1       1       1         Condition: Light Scuffing < 50 mm       1       Right Fender Condition: Light Scuffing < 50mm, Paint Chip- 01       1         Condition: Light Scuffing < 50 mm       1       Right Quarter Panel Condition: Low Visual Dent < 30mm, Light 1       1         Couditor: Low Visual Dent < 30mm, Light 1       1       Condition: Low Visual Dent < 30mm, Light 1       1         Couditor: Low Visual Dent < 30mm, Light 1       1       Condition: Low Visual Dent < 30mm, Light 1       1         Scuffing < 50mm       1       Condition: Low Visual Dent < 30mm, Light 1       1       1         Front Bumper       1       Condition: Low Visual Dent < 30mm, Light 1       1       1         Rear Bumper       1       1       1       1       1         Hood       1       1       1       1       1 <th>Passed</th> <th></th> <th></th> <th></th>	Passed			
Front left door Front right door   Panel: Low Visual Dent < 30mm, Light ①   Rear left door Panel: Low Visual Dent < 30mm, Light   Panel: Low Visual Dent < 30mm, Light ①   Scuffing < 50mm Panel: Low Visual Dent < 30mm, Light   Fenders Condition ①   Left Fender Condition: Light Scuffing < 50 mm   Condition: Light Scuffing < 50 mm ①   Quarter Panels Condition Panel: Low Visual Dent < 30mm, Light   Left Quarter Panel Condition: Light Scuffing < 50mm, Paint Chip- ①   Condition: Low Visual Dent < 30mm, Light ①   Scuffing < 50mm ①   Pront Bumper Condition ①   Front Bumper ①   Rear Bumper ①   Rear Bumper ①   Condition: Low Visual Dent < 30mm, Light Scuffing < 80mm   Front Bumper ②   Rear Bumper ①   Condition ①   Rear Bumper ①   Condition ①   Condition ①   Condition ①   Panel: Condition ①   Rear Bumper ①   Condition ①   Condition ①   Condition ①   Condition ①   Condition ①   Condition ① <td< th=""><th>🕾 Exterior</th><th></th><th></th><th></th></td<>	🕾 Exterior			
Front left door       Panel: Low Visibility Dent < 30mm, Light       1         Rear left door       Panel: Low Visual Dent < 30mm, Light       1         Panel: Low Visual Dent < 30mm, Light       1       Panel: Low Visual Dent < 30mm, Light       1         Scuffing < 50mm       1       Panel: Low Visual Dent < 30mm, Light       1       Panel: Low Visual Dent < 30mm, Light       1         Fenders Condition       1       Right Fender       Condition: Light Scuffing < 50mm, Paint Chip- (1) off < 5mm       1         Condition: Light Scuffing < 50 mm       1       Right Visual Dent < 30mm, Light       1       1         Quarter Panels Condition       1       Right Quarter Panel       1       1       1       1         Condition: Low Visual Dent < 30mm, Light       1       Condition: Low Visual Dent < 30mm, Light       1	Doors condition			
Rear left door Rear fight door   Panel: Low Visual Dent < 30mm, Light			Front right door	
Panel: Low Visual Dent < 30mm, Light	Front left door	<ul> <li></li> </ul>		(!)
Souffing < 50mm	Rear left door		Rear right door	
Fenders Condition   Left Fender   Condition: Light Scuffing < 50 mm	Panel: Low Visual Dent < 30mm, Light	(!)	Panel: Low Visual Dent < 30mm, Light	(!)
Left Fender Condition: Light Scuffing < 50 mmRight Fender Condition: Light Scuffing < 50mm, Paint Chip- ① off < 5mmQuarter Panels Condition Left Quarter Panel Condition: Low Visual Dent<30mm, Light Scuffing<50mm	Scuffing < 50mm		Scuffing < 50mm, Paint Chip-off < 5mm	
Left Fender ① Condition: Light Scuffing < 50 mm	Fenders Condition			
Condition: Light Scuffing < 50 mm	Loft Fondor		Right Fender	
Ouarter Panels Condition   Left Quarter Panel   Condition: Low Visual Dent<30mm, Light		(!)	Condition: Light Scuffing < 50mm, Paint Chip-	(!)
Left Quarter Panel Condition: Low Visual Dent<30mm, Light Scuffing<50mm Front Bumper Condition Front Bumper Rear Bumper Condition Rear Bumper Condition Rear Bumper Rear Bumper Rear Bumper: Light Scuffing < 80mm Hood Condition Hood Bonnet: Paint Chip-off < 5mm, Light Scuffing < 50mm, Low Visibility Dent < 30mm Trunk Condition Trunk Door Trim: Scuff/ Disfiguration< 50mm, Light (1) Scuffing < 50mm			off < 5mm	
Condition: Low Visual Dent<30mm, Light	Quarter Panels Condition			
Scuffing<50mm	Left Quarter Panel		Right Quarter Panel	
Front Bumper Condition Front Bumper Rear Bumper Condition Rear Bumper Rear Bumper: Light Scuffing < 80mm Hood Condition Hood Bonnet: Paint Chip-off < 5mm, Light Scuffing < 50mm, Low Visibility Dent < 30mm Trunk Door Trim: Scuff/ Disfiguration< 50mm, Light Scuffing < 50mm Trunk conditon	Condition: Low Visual Dent<30mm, Light	(!)	Condition: Low Visual Dent < 30mm, Light	(!)
Front BumperImage: ConditionRear BumperImage: ConditionRear Bumper: Light Scuffing < 80mm	Scuffing<50mm		Scuffing<50mm	
Rear Bumper Condition   Rear Bumper   Rear Bumper: Light Scuffing < 80mm	Front Bumper Condition			
Rear Bumper Rear Bumper: Light Scuffing < 80mmIHood Condition	Front Bumper	<ul> <li></li> </ul>		
Rear Bumper: Light Scuffing < 80mm Hood Condition Hood Bonnet: Paint Chip-off < 5mm, Light Scuffing < 50mm, Low Visibility Dent < 30mm Trunk Condition Trunk Door Trim: Scuff/ Disfiguration< 50mm, Light () Scuffing < 50mm Trunk conditon	Rear Bumper Condition			
Hood Condition   Hood   Bonnet: Paint Chip-off < 5mm, Light Scuffing ()	Rear Bumper			
Hood Bonnet: Paint Chip-off < 5mm, Light Scuffing (!) < 50mm, Low Visibility Dent < 30mm Trunk Condition Trunk Door Trim: Scuff/ Disfiguration < 50mm, Light (!) Scuffing < 50mm Trunk conditon	Rear Bumper: Light Scuffing < 80mm	$\bigcirc$		
Bonnet: Paint Chip-off < 5mm, Light Scuffing () < 50mm, Low Visibility Dent < 30mm Trunk Condition Trunk Door Trim: Scuff/ Disfiguration< 50mm, Light () Scuffing < 50mm Trunk conditon	Hood Condition			
< 50mm, Low Visibility Dent < 30mm Trunk Condition Trunk Door Trim: Scuff/ Disfiguration< 50mm, Light () Scuffing < 50mm Trunk conditon	Hood			
Trunk Condition Trunk Door Trim: Scuff/ Disfiguration< 50mm, Light (!) Scuffing < 50mm Trunk conditon	Bonnet: Paint Chip-off < 5mm, Light Scuffing	(!)		
Trunk Door Trim: Scuff/ Disfiguration< 50mm, Light ① Scuffing < 50mm Trunk conditon	< 50mm, Low Visibility Dent < 30mm			
Door Trim: Scuff/ Disfiguration< 50mm, Light (!) Scuffing < 50mm Trunk conditon	Trunk Condition			
Scuffing < 50mm Trunk conditon	Trunk			
Trunk conditon	Door Trim: Scuff/ Disfiguration< 50mm, Light	(!)		
	Scuffing < 50mm			
Truck	Trunk conditon			
	Trunk	<ul> <li>Image: A start of the start of</li></ul>		

#### **Roof Condition**

Roof

<b>Pillars Condition</b>
--------------------------

$\checkmark$	

Left A Pillar Inner Condition: Fair Use Wear	!	Right A Pillar	~
Left A to B Pillar Beading	<ul> <li>Image: A start of the start of</li></ul>	Right A to B Pillar Beading	<ul> <li></li> </ul>
Right A to B Pillar	<ul> <li>Image: A start of the start of</li></ul>	Left B Pillar	<ul> <li>Image: A start of the start of</li></ul>
Left B Pillar Trim	<ul> <li></li> </ul>	Left B to C Pillar Beading	<ul> <li>Image: A start of the start of</li></ul>
Right C Pillar Trim	<ul> <li></li> </ul>	Right B to C Pillar	~
Right B to C Pillar Beading	~	Left C Pillar Low Visual Dent < 30mm	(!)
Running Board Condition			
Left Running Board		Right Running Board	
Front Left Sill Trim: Scratch < 80mm	(!)	Condition: Light Scuffing < 80mm	$\mathbf{O}$
Windshield Condition			
Front Windshield	~	Rear Windshield	~
Structural Assessment			
Chassis Condition	<ul> <li>Image: A start of the start of</li></ul>	Radiator Support	<ul> <li></li> </ul>
Apron	<ul> <li>Image: A start of the start of</li></ul>	Boot Floor	~
Firewall Condition	<ul> <li>Image: A start of the start of</li></ul>	Cowl Top	<ul> <li>Image: A start of the start of</li></ul>
Head Light Support Condition	<ul> <li>Image: A start of the start of</li></ul>		
Cowl Top			
Cowl Top	~		
Rear View Mirror Condition			
Left Hand Side Mirror	<ul> <li></li> </ul>	Left Side Mirror	~
Right Side Mirror		Dight Lland Cide Mirror	
Body: Scratch < 50mm	(!)	Right Hand Side Mirror	
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Rim: Alloy Edge Scuffing > 50mm	(!)	Rim: Alloy Edge Scuffing > 50mm	$\bigcirc$
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Rim: Alloy Edge Scuffing < 80mm	$\odot$	Rim: Alloy Edge/Scuffing<80mm	$\odot$

Spare Alloy/ Rim Condition	<ul> <li></li> </ul>		
Wheel Arch	<ul> <li></li> </ul>	Wheel cover	~
Antenna	~	Grill Condition Light Scuffing < 50mm	(!)
Monogram	<ul> <li></li> </ul>	Window Glass	~
Wiper	<ul> <li></li> </ul>		
Panel Condition			
Rear Trunk Panel	<ul> <li></li> </ul>		

## Engine & Transmission

Engine			
Engine Body	~	Engine Performance	<ul> <li></li> </ul>
Engine Oil (Condition & Level)	<ul> <li>Image: A start of the start of</li></ul>	Exhaust System	<ul> <li>Image: A start of the start of</li></ul>
Radiator Condition	<ul> <li>Image: A start of the start of</li></ul>	Radiator Coolant	<ul> <li>Image: A start of the start of</li></ul>
Battery			
Battery Terminal & Tightness	<ul> <li></li> </ul>		
Fuel System			
Fuel Cap	<ul> <li></li> </ul>	Fuel Tank	<ul> <li></li> </ul>
Transmission Operation			
Gear Shifting	<ul> <li></li> </ul>	Drive Axle	<ul> <li></li> </ul>
Transmission Fluid	~		

#### Steering, Suspension & Brakes

Steering			
Steering wheel	<ul> <li></li> </ul>		
Brake System			
Parking Brake	<ul> <li></li> </ul>	Brake Master Cylinder	<ul> <li></li> </ul>
Brake Disc & Brake Pad	~	Brake Fluid	<ul> <li></li> </ul>
Pedals	~		

Suspension

Shock Absorbers

~

## Electricals, Controls & Lights

Keys			
Master Key	<ul> <li></li> </ul>	Spare Key(s)	~
Door Locks			
Child Safety Locking	~		
Dashboard			
Instrument Panel	<ul> <li></li> </ul>		
Airbags			
Airbags	<ul> <li></li> </ul>		
Controls	~	Cruise Control	<ul> <li>Image: A start of the start of</li></ul>
Infotainment Display	~	Engine Sensors	<ul> <li>Image: A start of the start of</li></ul>
OBD Connector	~	Navigation System	<ul> <li>Image: A start of the start of</li></ul>
Music System	~	Camera	<ul> <li>Image: A start of the start of</li></ul>
Lights			
Headlight Left: Light Scuff Marks < 50mm	!	Interior Lights	~
Tail Light Cluster	~	Daylight Running Lights	<ul> <li>Image: A start of the start of</li></ul>
License Plate Light	<ul> <li></li> </ul>	Fog Lights	~
Air Conditioning			
AC Cooling	<ul> <li></li> </ul>	AC Switch	<ul> <li></li> </ul>
AC System Leaks	~	Center AC Vent	<ul> <li>Image: A start of the start of</li></ul>
Front Right AC Vent	<ul> <li></li> </ul>	Heater	~
Parking Sensors	~	Rear Defogger	<ul> <li>Image: A start of the start of</li></ul>
USB Charging Port	~	Rear Entertainment Left Seat LCD: minor imperfection	(!)

# ▲ Interiors & Luggage

Dashboard And Instrument Panel	<ul> <li>Image: A start of the start of</li></ul>	Central Console Box: Minor Crack/Fair Use Wear/ Scuffing	(!)
Cup Holder	~	Glove Box	~
Steering Wheel	~	Sunvisor	~
Seat Upholstery Rear Left Seat: Minor Leather/ Fabric Fair Use Wear/ Tears	(!)	Manual Seat Movement	<ul> <li>Image: A start of the start of</li></ul>
Seat Belts	~	Head Rest	<ul> <li></li> </ul>
Door Controls And Trim Front Left Door: Light Scuffing	!	Grab Handle	~
Carpet	~	Headliner Front Left: Light Smudge/Disfiguration	(!)
Rear View Mirror	~	Toolkit	~

 $\checkmark$ 

# Itres

Tyres Condition			
Left Hand Side Front Tyre	<ul> <li></li> </ul>	Left Hand Side Rear Tyre	<ul> <li></li> </ul>
Right Hand Side Front Tyre	<ul> <li>Image: A start of the start of</li></ul>	Right Hand Side Rear Tyre	~
Spare Tyre	~		
Tyres Depth (Remaining)			
LHS Front Tyre	<55%	LHS Rear Tyre	<85%
RHS Front Tyre	<55%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



### A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE