



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 MITSUBISHI ATTRAGE

GLX MID | 96,878 KM

VIN: MMDAF26J2KH005477

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Music System

Enjoy your drive with music system



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	96878	 Specs	Yes
 Engine	1.2L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MMDAF26J2KH005477		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors	
Fog Light Front	
 Comfort & Convenience	
Cruise Control	
Steering Mounted Audio Controls	
 Safety & Security	
Rear Armrest with cupholder	
Rear Defogger	

Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
Entertainment			
Bluetooth Player		Infotainment System	
USB player			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm

Rear left door



Rear right door



Panel: Dent < 30mm, Scratch < 50mm

Panel: Low Visual Dent < 30mm

Fenders Condition

Left Fender



Right Fender



Condition: Low Visual Dent < 30mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm



Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm, Chip < 8mm

Hood Condition

Hood



Bonnet: Paint Chip-off < 5mm

Trunk Condition

Trunk



Door Trim: Light Scuffing < 50mm

Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Low Visual Dent < 50mm	
		Left C Pillar	

Running Board Condition

Left Running Board		Right Running Board	
--------------------	--	---------------------	--

Windshield Condition

Front Windshield		Rear Windshield	
------------------	--	-----------------	--

Structural Assessment

Chassis Condition		Radiator Support	
-------------------	--	------------------	--

Condition: minor imperfection

Apron		Boot Floor	
-------	--	------------	--

Firewall Condition		Cowl Top	
--------------------	--	----------	--

Head Light Support Condition

Cowl Top			
----------	--	--	--

Cowl Top

--	--	--	--

Rear View Mirror Condition

Left Hand Side Mirror		Left Side Mirror	
-----------------------	--	------------------	--

Right Side Mirror		Right Hand Side Mirror	
-------------------	--	------------------------	--

Alloy Wheel/ Rim

Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
-----------------------	--	----------------------	--

Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
------------------------	--	-----------------------	--

Spare Alloy/ Rim Condition			
----------------------------	--	--	--

Wheel Arch		Wheel cover	
------------	--	-------------	--

Antenna		Grill Condition	
---------	--	-----------------	--

minor imperfection

Light Scuffing < 50mm

Monogram



Window Glass



Wiper



Panel Condition



Rear Trunk Panel

Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key		Spare Key(s) Buttons Faded	
------------	---	-------------------------------	---

Door Locks

Child Safety Locking	
----------------------	---

Dashboard

Instrument Panel	
------------------	---

Airbags

Airbags	
---------	---

Controls		Cruise Control	
----------	---	----------------	---

Infotainment Display		Engine Sensors	
----------------------	---	----------------	---

OBD Connector		Music System	
---------------	---	--------------	---

Lights

Headlight		Interior Lights	
-----------	---	-----------------	---

Tail Light Cluster		Turn Signal Lights	
--------------------	---	--------------------	---

License Plate Light		Fog Lights	
---------------------	---	------------	---

Air Conditioning

AC Cooling		AC Switch	
------------	---	-----------	---

AC System Leaks		Center AC Vent	
-----------------	---	----------------	---

Front Right AC Vent		Heater	
---------------------	---	--------	---

Rear Defogger		USB Charging Port	
---------------	---	-------------------	---

Power/ Manual Windows	
-----------------------	---

Interiors & Luggage

Dashboard And Instrument Panel		Central Console Cigarette Lighter: Cigarette Lighter Missing	
--------------------------------	---	---	---

Cup Holder		Glove Box	
Steering Wheel		Sunvisor	
Steering Wheel Fair Use Wear			
Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Rear Left Door: Light Scuffing			
Carpet		Headliner	
Rear Left Floor Carpet: Smudge / Fair Use Wear		Front Left: Light Smudge/Disfiguration	
Rear View Mirror		Toolkit	

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			

Tyres Depth (Remaining)

LHS Front Tyre	<85%	LHS Rear Tyre	<75%
RHS Front Tyre	<85%	RHS Rear Tyre	<65%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE