



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2019 MITSUBISHI ATTRAGE

GLX MID | 69,861 KM

VIN: MMDAF26J2KH006306

Car highlights



Great Parking Assistance

Reverse Camera



Bluetooth

Enjoy your drive with bluetooth



Music System

Enjoy your drive with music system



Amazing Comfort

Power driver seat

Basic Details

| | | | |
|--|--------------------------|---|-----------------------------|
|  Kilometers | 69861 |  Specs | Yes |
|  Engine | 1.2L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SEDAN |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color White |
|  Interior Trim | Fabric Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | MMDAF26J2KH006306 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | |
|--|---|
|  Exteriors | |
| Fog Light Front |  |
|  Comfort & Convenience | |
| Rear Armrest with cupholder |  |
| Rear Defogger |  |
|  Safety & Security | |

| | | | |
|---------------------|---|----------------------|---|
| Reverse Camera |  | Traction Control |  |
| Airbag Driver Front |  | ABS |  |
| Central Locking |  | Child Safety Locking |  |

 **Entertainment**

| | | | |
|------------------|---|---------------------|---|
| Bluetooth Player |  | Infotainment System |  |
| USB player |  | | |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Panel: Dent < 30mm

Fenders Condition

Left Fender



Right Fender



Condition: Low Visual Dent < 30mm

Quarter Panels Condition

Left Quarter Panel

Condition: Scratch < 50mm, Dent < 30mm,
Paint Chip-off < 5mm



Right Quarter Panel



Condition: Low Visual Dent < 30mm, Light
Scuffing<50mm

Front Bumper Condition

Front Bumper



Condition: minor imperfection

Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip<
8mm

Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

| | | | |
|------------------------------|--|---|--|
| Left A Pillar | | Right A Pillar | |
| Left A to B Pillar Beading | | Right A to B Pillar Beading | |
| Right A to B Pillar | | Left B Pillar | |
| Left B Pillar Trim | | Left B to C Pillar Beading | |
| Right C Pillar Trim | | Right B to C Pillar | |
| | | Low Visual Dent < 50mm | |
| Right B to C Pillar Beading | | Left C Pillar | |
| Running Board Condition | | | |
| Left Running Board | | Right Running Board | |
| Windshield Condition | | | |
| Front Windshield | | Rear Windshield | |
| Structural Assessment | | | |
| Chassis Condition | | Radiator Support | |
| Apron | | Boot Floor | |
| Firewall Condition | | Cowl Top | |
| Head Light Support Condition | | | |
| Cowl Top | | | |
| Cowl Top | | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | | Left Side Mirror | |
| Right Side Mirror | | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | | Left Rear Alloy/ Rim | |
| | | Right Rear Alloy/ Rim | |
| Right Front Alloy/ Rim | | Rim: Alloy Edge/ Scuff < 80mm, Alloy Face/ Scuff < 50mm | |
| Spare Alloy/ Rim Condition | | | |
| Antenna | | Grill Condition | |
| | | Light Scuffing < 50mm | |
| Monogram | | Window Glass | |

Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Navigation System



Music System



Camera



Lights

Headlight



Left: minor imperfection

Interior Lights



Tail Light Cluster



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Glove Box



Steering Wheel



Color Faded

Sunvisor



| | | | |
|-----------------------------------|---|----------------------|---|
| Seat Upholstery | ! | Manual Seat Movement | ✓ |
| Driver Seat: Minor Cigarette Burn | | | |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ! | Grab Handle | ✓ |
| Front Left Door: Light Scuffing | | | |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

| | | | |
|----------------------------|------|---|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre minor imperfection | ! |
| Spare Tyre | ✓ | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <45% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <55% |
| Spare Tyre | <75% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE