



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 HYUNDAI GRAND SANTA FE

GLS | 139,473 KM

VIN: KMHSN81E6FU100751

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat




Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 139473 |  Specs | Yes |
|  Engine | 3.3L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | Four Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Black |
|  Interior Trim | Fabric Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 7 Seats |  Number of keys | 1 Keys |
|  VIN number | KMHSN81E6FU100751 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|---------------------------------|---|
|  Comfort & Convenience | | | |
| Climate Control AC |  | Cruise Control |  |
| Rear Armrest with cupholder |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors |  | Rear Defogger |  |
| Central Armrest |  | Automatic Headlights |  |
|  Exteriors | | | |

| | | | |
|--|---|---------------------|---|
| Fog Light Front | ✓ | Roof Rails | ✓ |
| Rear Bumper Spoiler | ✓ | LED Headlights | ✓ |
| Halogen Headlights | ✓ | | |
|  Safety & Security | | | |
| Parking Sensors Rear | ✓ | Reverse Camera | ✓ |
| Traction Control | ✓ | Airbag Driver Front | ✓ |
| ABS | ✓ | Central Locking | ✓ |
| Child Safety Locking | ✓ | | |
|  Performance | | | |
| Hill Descent Control | ✓ | Differential Locks | ✓ |
|  Entertainment | | | |
| Bluetooth Player | ✓ | Infotainment System | ✓ |
| USB player | ✓ | | |





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|------------------------------------|---|------------------------------|---|
| Front left door |  | Front right door |  |
| | | Panel: Light Scuffing < 50mm | |
| Rear left door |  | Rear right door |  |
| Panel: Scratch < 50mm, Dent < 30mm | | Panel: Light Scuffing < 50mm | |

Fenders Condition

| | | | |
|-----------------------------------|---|--|---|
| Left Fender |  | Right Fender |  |
| Condition: Light Scuffing < 50 mm | | Fender Liner: Misaligned/ Not Properly Fixed | |


Quarter Panels Condition

| | | | |
|---------------------------|--|--|--|
| Left Quarter Panel |  | Right Quarter Panel |  |
| Condition: Scratch < 50mm | | Condition: Low Visual Dent < 30mm, Light Scuffing<50mm | |


Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|---|---|
| Rear Bumper | |
| Rear Bumper: Light Scuffing < 80mm, Dent < 50mm |  |

Hood Condition

| | |
|--|---|
| Hood | |
| Bonnet: Acid Marks/ Bird Dropping < 5mm, Light Scuffing < 50mm |  |

Trunk Condition

| | |
|--|---|
| Trunk | |
| Door Trim: Light Scuffing < 50mm, Scuff/ Disfiguration< 50mm |  |

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

Roof

Roof Moulding Condition: Minor Rubber
Beading Fair Use Wear



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar
Light Scuffing < 80mm



Right B to C Pillar Beading



Left C Pillar



Running Board Condition

Left Running Board



Right Running Board
Front Right Sill Trim: Low Visual Dent <
50mm, Light Scuffing < 80mm



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim

Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/



Left Rear Alloy/ Rim

Rim: Alloy Edge/ Scuff < 80mm



Scuff < 80mm

Right Front Alloy/ Rim

Rim: Alloy Edge/ Scuff < 80mm, Alloy Face/
Scuff < 50mm



Right Rear Alloy/ Rim

Rim: Alloy Edge/ Scuff < 80mm



Spare Alloy/ Rim Condition



Antenna



Grill Condition

Light Scuffing < 50mm



Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

| | | | |
|------------------------|---|-----------------------|---|
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
| Pedals | ✓ | | |
| Suspension | | | |
| Shock Absorbers | ✓ | | |

Electricals, Controls & Lights

| | | | |
|---|---|---|---|
| Keys | | | |
| Master Key minor imperfection | ! | | |
| Door Locks | | | |
| Child Safety Locking | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | Engine Sensors | ✓ |
| OBD Connector | ✓ | Navigation System Condition: Available - SD Card Missing | ! |
| Music System | ✓ | | |
| Sunroof Operation | | | |
| Sunroof | ✓ | | |
| Camera | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | License Plate Light | ✓ |
| Fog Lights | | | |
| Right Fog Light: Light Scuff Marks < 50mm | ! | | |

| | | | |
|---|---|--------------------------------------|---|
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent minor imperfection | ! |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | | | |
| Front Left: Master Switch Buttons Faded | ! | | |

Interiors & Luggage

| | | | |
|--|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ✓ | Sunvisor | ✓ |
| Seat Upholstery Driver Seat: Minor Smudge/ Cracks | ! | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim Front Left Door: Light Scuffing/ Disfiguration, Fair Use Wear | ! | Grab Handle | ✓ |
| Carpet Front Left Floor Mat: Smudge/Burn/Crack | ! | Headliner Front Left: Light Smudge/Disfiguration | ! |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

| | | | |
|----------------------------|---|---------------------------|---|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Tyres Depth (Remaining) | | | |

| | | | |
|----------------|------|---------------|------|
| LHS Front Tyre | <85% | LHS Rear Tyre | <85% |
| RHS Front Tyre | <85% | RHS Rear Tyre | <85% |
| Spare Tyre | <65% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE