



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2015 HYUNDAI TUCSON

GL | 159,772 KM

VIN: KMHJT81E2FU955738

Car highlights



Four wheel drive

This car has a Four wheel drive



Great Parking Assistance

Reverse Camera



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	159772	 Specs	Yes
 Engine	2.0L	 Option Type	Basic
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	KMHJT81E2FU955738		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front		Roof Rails	
Rear Bumper Spoiler		Halogen Headlights	
 Comfort & Convenience			
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	



Performance

Differential Locks



Safety & Security

Reverse Camera



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Entertainment

Bluetooth Player



Infotainment System



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Moulding: Scratch < 50mm

Front right door



Panel: Low Visibility Dent < 30mm, Light

Scuffing < 50mm, Paint Chip-off < 5mm

Rear left door



Handle: Paint Chip-off < 5mm

Rear right door



Panel: Paint Chip-off < 5mm, Low Visual Dent

< 30mm, Light Scuffing < 50mm

Fenders Condition

Left Fender



Condition: Scratch < 50mm, Dent < 30mm

Right Fender



Right Fender: Scratch < 50mm, Paint Chip-off

< 5mm, Dent < 30mm

Quarter Panels Condition

Left Quarter Panel



Condition: Dent < 30mm, Scratch < 50mm,

Paint Chip-off < 5mm, Repaired and Painted

Right Quarter Panel



Condition: Scratch < 50mm, Paint Chip-off <

5mm, Dent < 30mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Refurbished to RTA standards

Hood Condition

Hood



Bonnet: Low Visibility Dent < 30mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof	!		
Roof Moulding Condition: Colour fade			
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	
Condition: Driver Side/Stone Chip		Front Right Sill Trim: Light Scuffing < 80mm	!
Mark<5mm, Passenger Side/Stone Chip	!	Rear Windshield	✓
Mark<8mm			
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror			
Body: Paint Faded	!	Left Side Mirror	✓
Right Side Mirror			
Body: Mirror Case Fair Use Wear	!	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim			
Rim: Alloy Face/ Scuff < 50mm	!	Left Rear Alloy/ Rim	!
Right Front Alloy/ Rim	!	Rim: Alloy Face/ Scuff < 50mm	
		Right Rear Alloy/ Rim	!

Rim: Alloy Face/ Scuff < 50mm

Spare Alloy/ Rim Condition



Wheel Arch



Antenna



Wheel cover



Monogram



Grill Condition

Light Scuffing < 50mm



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Dent < 30mm

Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Button Faded

Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System



Camera



Lights

Headlight



Left: Light Scuff Marks < 50mm

Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Fog Lights

Left Fog Light: Cracks/ Holes/ Fair Wear Use



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Defogger



Extensive Wear Of Strip

USB Charging Port





🎒 Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/
Disfigurement/ Melted



Central Console

Gear Shift Knob: Buttons Faded



Cup Holder



Glove Box



Steering Wheel



Steering Wheel Fair Use Wear

Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim

Front Left Door: Light Scuffing



Grab Handle



Carpet

Front Left Floor Mat: Smudge/Burn/Crack



Headliner



Rear View Mirror



Toolkit



🌐 Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<85%

RHS Front Tyre

<65%

RHS Rear Tyre

<85%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE