



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2016 MERCEDES BENZ GL 500**

**AMG | 88,196 KM**

VIN: WDCDF7DE5GA656658

## Car highlights



### **Power packed**

Engine size of 4.7 Litres & 8.0 cylinders



### **Panoramic Roof**

This car has a panoramic roof



### **Adaptive cruise control**
















Adaptive cruise control to drive with ease & comfort



### **Amazing Comfort**








Power driver seat

## Basic Details

 Kilometers	<b>88196</b>	 Specs	<b>Yes</b>
 Engine	<b>4.7L</b>	 Option Type	<b>Fully Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>All Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Black</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>10 Airbags</b>
 Seating Capacity	<b>7 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>WDCDF7DE5GA656658</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Safety &amp; Security</b>			
Adaptive cruise control		360 degree Camera	
Navigation		Reverse Camera	
Front Camera		Side Camera	

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door



Front right door

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm



Rear left door

Panel: Scratch < 50mm



Rear right door

Panel: Light Scuffing < 50mm, Scuffing > 50mm



### Fenders Condition

Left Fender

Condition: Paint Chip-off < 5mm



Right Fender



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Colour Mismatch/ Low Brightness



### Hood Condition

Hood



### Trunk Condition

Trunk



### Trunk condition

Trunk



### Roof Condition

Roof



### Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar Low Visual Dent < 30mm	⚠	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar Scratch < 50mm	⚠
Running Board Condition			
Left Running Board Left Foot Board: Scratch < 80mm	⚠	Right Running Board Right Foot Board: Light Scuffing < 80mm	⚠
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top Beading: Crack/Fair Use Wear>50mm	⚠
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror Body: Mirror Case Fair Use Wear	⚠	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		

Antenna		Grill Condition	
		Light Scuffing < 50mm	
Monogram		Window Glass	
		Rear Right Window Curtain: Fair Use Wear	
Wiper			
Panel Condition			
Rear Trunk Panel			

## Engine & Transmission

Engine			
Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Turbocharger/ Supercharger		Radiator Condition	
Radiator Coolant			
Battery			
Battery Terminal & Tightness			
Fuel System			
Fuel Tank			
Transmission Operation			
Gear Shifting		Gear shift	
Drive Axle		4*4 Condition (If Applicable)	
Transmission Fluid			

## Steering, Suspension & Brakes

Steering			
Steering wheel			
Brake System			
Parking Brake		Brake Master Cylinder	
Brake Disc & Brake Pad		Brake Fluid	

Pedals 

Suspension

Shock Absorbers 

---

 **Electricals, Controls & Lights**

Keys

Master Key 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls 


Cruise Control 

Infotainment Display 

Engine Sensors 

OBD Connector 

Navigation System 


Music System   
Condition: Button(s) Faded

Sunroof Operation

Sunroof 

Camera 

Lights

Headlight   
Left Washer: Not Working

Interior Lights 

Tail Light Cluster 

Turn Signal Lights 

Daylight Running Lights 

License Plate Light 

Air Conditioning

AC Cooling 

AC Switch   
Button(s) Faded

AC System Leaks		Center AC Vent	
Front Right AC Vent Crack/Fair Use Wear		Heater	
Rear Blower Switch		Rear Left AC Vent	
Rear Defogger Extensive Wear Of Strip		USB Charging Port	
Rear Entertainment Left Seat LCD: Not Working Properly		Power/ Manual Windows	
Seat Heaters		Memory Seats	

### Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Cup Holder		Glove Box	
Steering Wheel Steering Wheel Fair Use Wear > 80 mm		Sunvisor	
Seat Upholstery Driver Seat: Minor Fair Wear/Fade off		Manual Seat Movement	
Seat Belts		Head Rest Driver Seat: Not Functioning Properly	
Door Controls And Trim Front Left Door: Crack/Fair Use Wear>10mm		Grab Handle	
Carpet		Headliner	
Rear View Mirror		Toolkit	

### Tyres

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<55%	LHS Rear Tyre	<55%



RHS Front Tyre

<55%

RHS Rear Tyre

<55%

Spare Tyre

<45%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE