



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2014 BMW X6**

**XDRIVE 35I | 130,659 KM**

VIN: WBAFG2104E0G90519

## Car highlights



### **Supercharger/turbocharger**

This car has a Supercharger/turbocharger



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**












Power driver seat, Memory Seats & more





























## Basic Details

 Kilometers	<b>130659</b>	 Specs	<b>Yes</b>
 Engine	<b>3.0L</b>	 Option Type	<b>Fully Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>All Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Blue</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>8 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>WBAFG2104E0G90519</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Safety &amp; Security</b>	
360 degree Camera 	Navigation 
Parking Sensors Front 	Parking Sensors Rear 
Reverse Camera 	Traction Control 
Front Camera 	Side Camera 
Airbag Curtain Shield 	Airbag Driver Front 

ABS		Central Locking	
Child Safety Locking			
 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Memory Seats		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Power Folding Mirrors	
Power Tailgate/ Power Trunk		Power Head Rest	
Rear Defogger		Central Armrest	
Automatic Headlights			
 <b>Exteriors</b>			
Fog Light Front		Roof Rails	
Running Lights		LED Headlights	
 <b>Performance</b>			
Paddle Shift		Hill Descent Control	
 <b>Entertainment</b>			
Bluetooth Player		USB Charging Port	
Infotainment System		USB player	

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door

Inner Beading: Rubber Crack/ Tear < 5mm



Front right door



Rear left door

Inner Frame: Scratch < 80mm



Rear right door

Weather Strip: Minor Fair Use Rubber Wear



### Fenders Condition

Left Fender

Condition: Scratch < 50mm, Paint Chip-off < 5mm



Right Fender

Right Fender: Paint Chip-off < 5mm



### Quarter Panels Condition

Left Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm



Right Quarter Panel



### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip < 8mm



### Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Light Scuffing < 50mm



### Trunk Condition

Trunk

Door Trim: Light Scuffing < 50mm



### Trunk condition

Trunk



### Roof Condition

Roof			
Pillars Condition			
Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
		Condition: Scratch < 50mm	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board		Right Running Board	
Rear Left Sill Trim: Scratch < 80mm			
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass			
Windshield Condition			
Front Windshield		Rear Windshield	
Condition: Driver Side/Stone Chip			
Mark<5mm, Passenger Side/Stone Chip			
Mark<8mm			
Structural Assessment			
Chassis Condition		Radiator Support	
Apron		Boot Floor	
Firewall Condition		Cowl Top	
Head Light Support Condition			
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Body: Paint Chip-off < 5mm			
Right Side Mirror		Right Hand Side Mirror	
Alloy Wheel/ Rim			

Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	⚠	Rim: Alloy Edge/ Scuff < 80mm	⚠
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Rim: Alloy Edge/ Scuff < 80mm	⚠	Rim: Alloy Edge/ Scuff < 80mm	⚠
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition		Monogram	✓
Light Scuffing < 50mm	⚠	Wiper	✓
Window Glass	✓		
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm	⚠		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	4*4 Condition (If Applicable)	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering

Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		



### Electricals, Controls & Lights

Keys			
Master Key	✓		
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Navigation System	✓
Music System	⚠		
Condition: Button(s) Faded			
Sunroof Operation			
Sunroof	✓		
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓



License Plate Light	✓	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC Switch Button(s) Faded	!
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater Heater Not Working	!
Rear Blower Switch	!		
Fair Use Wear			
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Memory Seats	✓

### Interiors & Luggage

Dashboard And Instrument Panel Dashboard Trim: Light Scuffing/Disfiguration	!	Central Console Box: Minor Crack/Fair Use Wear/ Scuffing, Minor Disfiguration	!
Cup Holder	✓	Glove Box	✓
Steering Wheel Color Faded	!	Sunvisor	✓
Seat Upholstery Driver Seat: Minor Smudge/ Cracks	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Front Left Door: Light Scuffing/ Disfiguration, Light Scuffing, Fair Use Wear	!	Carpet	✓
Headliner Rear Left: Light Scuffing, Smudge/Disfiguration	!	Rear View Mirror	✓
Toolkit	✓		

### Tyres

Tyres Condition

Left Hand Side Front Tyre 

Left Hand Side Rear Tyre 

Right Hand Side Front Tyre 

Right Hand Side Rear Tyre 

Spare Tyre 

Life remaining

LHS Front Tyre <85%

LHS Rear Tyre <75%

RHS Front Tyre <85%

RHS Rear Tyre <75%

Spare Tyre <45%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE