



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





## 2014 LAND ROVER RANGE ROVER SPORT

SPORT HSE | 114,247 KM

VIN: SALWA2VF6EA334480

### Car highlights



#### **Panoramic Roof**

This car has a panoramic roof



#### **Great Parking Assistance**

Parking Sensors Front, Reverse Camera & more



#### **Bluetooth**














Enjoy your drive with bluetooth



#### **Amazing Comfort**












Power driver seat, Memory Seats


Basic Details

 Kilometers	114247	 Specs	Yes
 Engine	3.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Seating Capacity	5 Seats
 VIN number	SALWA2VF6EA334480		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Panoramic Sunroof		Memory Seats	
Power Tailgate/ Power Trunk		Remote Engine Start	
 <b>Exteriors</b>			
Fog Light Front		Running Lights	
 <b>Safety &amp; Security</b>			
Parking Sensors Front		Parking Sensors Rear	

Reverse Camera	✓	Blind Spot Monitor	✓
ABS	✓		
 <b>Entertainment</b>			
Bluetooth Player	✓	USB Charging Port	✓
Infotainment System	✓		

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 


## Exterior

### Doors condition


Front left door Condition: Scratched		Front right door	
---	---	------------------	---

Rear left door		Rear right door Condition: Scratched	
----------------	---	---	---

### Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---


### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

### Front Bumper Condition

Front Bumper Condition: Scratched	
--------------------------------------	---

### Rear Bumper Condition

Rear Bumper Rear Bumper: Logo Faded	
--	---

### Hood Condition

Hood	
------	---

### Trunk conditon

Trunk	
-------	---

### Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left B Pillar Condition: Scratched		RHS Pillar B Condition Scratched	
---------------------------------------	---	-------------------------------------	---

RHS Pillar C Condition Scratched		Left C Pillar Faded	
-------------------------------------	---	------------------------	---

Left D pillar	
---------------	---

### Running Board Condition

Left Running Board	✓	Right Running Board Condition: Dented	!
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		
No structural damage			
Chassis Conditon	✓	Upper Cross Member Condition	✓
Lower Cross Member Condition	✓	Chassis Condition	✓
Radiator Support	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror Body: Scratched	!	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Alloy Wheel: Scratched	!	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim Alloy Wheel: Scratched	!	Right Rear Alloy/ Rim Alloy Wheel: Scratched	!
Grill Condition	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

## Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Transmission Operation

Drive Axle



Transmission Operation



## Steering, Suspension & Brakes

### Steering

Steering wheel

Condition: Trim Scratched



Shock absorbers



### Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



### Suspension

Suspension



## Electricals, Controls & Lights

### Keys

Master Key



Remote Key Operations

Keyless/ Remote Start



### Dashboard

Instrument Panel



Cruise Control

Operation: Scratched



Radar (If Equipped)



Music System

Steering Mounted Audio Controls: Scratched



Bluetooth Operations



Sunroof Operation

Sunroof



Lights			
Lights	✓	Running lights	✓
Headlight	✓	Interior Lights	✓
Tail Light Cluster	!	Turn Signal Lights	✓
Left Tail Lamp: Beading Missing/Broken			
License Plate Light	✓	Back Up Light	✓
Fog Lights	✓	Trunk Lid Release/Trunk Lid Light Operation	✓
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓
Memory Seats	✓		

## Interiors & Luggage

Dashboard And Instrument Panel	!	Central Console	!
Dashboard And Instrument Panel: Scratched		Condition: Missing/Broken	
Cup Holder	✓	Sunvisors	✓
Seat Upholstery	!	Manual Seat Movement	✓
Driver Seat: Depressed/Pressure Mark			
Seat Belts	✓	Seat Belt with issues	✓
Head Rest	✓	Door Controls And Trim	!
		Front Left Door: Scratched	
Door Hinge Condition	✓	Carpet	✓



Headliner



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<85%

LHS Rear Tyre

<85%

RHS Front Tyre

<85%

RHS Rear Tyre

<85%

Spare Tyre

<85%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE