



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2020 NISSAN PATROL**

**LE PLATINUM | 84,070 KM**

VIN: JN8AY2NY6L9402035

## **Car highlights**



### **Power packed**

Engine size of 5.6 Litres & 8.0 cylinders



### **Adaptive cruise control**

Adaptive cruise control to drive with ease & comfort



### **Rear Seat Entertainment**
















Enjoy your drive with Rear Seat Entertainment



### **Amazing Comfort**











Power driver seat, Memory Seats & more


Basic Details

 Kilometers	84070	 Specs	Yes
 Engine	5.6L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	JN8AY2NY6L9402035		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Sunroof		Cruise Control	
Memory Seats		Rear Seat Entertainment	
Steering Mounted Audio Controls		Power Tailgate/ Power Trunk	
Central Armrest		Remote Engine Start	
 <b>Safety &amp; Security</b>			

Parking Sensors Front	✓	Navigation	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Front Camera	✓	Side Camera	✓
ABS	✓	Central Locking	✓
 <b>Entertainment</b>			
Bluetooth Player	✓	USB Charging Port	✓
Infotainment System	✓		





# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
Condition: Scratched, Dented		Condition: Scratched	
Rear left door		Rear right door	
Condition: Scratched		Condition: Scratched	

### Fenders Condition

Left Fender		Right Fender	
Condition: Scratched			

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Scratched		Condition: Scratched	

### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper	
Rear Bumper: Faded	








### Hood Condition

Hood	
Bonnet: Scratched	

### Trunk conditon

Trunk	
-------	---

### Pillars Condition

Left A Pillar		Right A Pillar	
Left B Pillar		RHS Pillar B Condition	
RHS Pillar C Condition		Left C Pillar	
Left D pillar			

### Running Board Condition

Left Running Board	!	Right Running Board	!
Condition: Scratched		Condition: Scratched	
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		
No structural damage			
Chassis Conditon	✓	Upper Cross Member Condition	✓
Lower Cross Member Condition	✓	Chassis Condition	✓
Radiator Support	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

## Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Transmission Operation			
Drive Axle	✓	Transmission Operation	✓

## **Steering, Suspension & Brakes**

Steering			
Steering wheel	✓	Shock absorbers	✓
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Suspension	✓		

## **Electricals, Controls & Lights**

Keys			
Master Key	✓		
Remote Key Operations			
Keyless/ Remote Start	✓		
Door Locks			
Central Locking Operation	✓	Child Safety Locking	✓
Dashboard			
Instrument Panel	✓		
Controls	✓	Cruise Control	✓
Radar (If Equipped)	✓	Navigation System	✓
Music System	✓	Bluetooth Operations	✓

## Sunroof Operation

Sunroof



## Lights

Lights



Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Back Up Light



Trunk Lid Release/Trunk Lid Light Operation



## Air Conditioning

AC Air Direction Switch



Blower Motor



Compressor



Condenser



AC Cooling



AC Switch



AC System Leaks



Heater



AC Heater Operation Switch



AC Blower Switch



AC Wind Direction



Parking Sensors



Rear Defogger



USB Charging Port



Rear Entertainment



Power/ Manual Windows



Seat Heaters



Memory Seats



## Interiors & Luggage

Dashboard And Instrument Panel



Dashboard And Instrument Panel: Scratched

Central Console



Cup Holder



Sunvisors



Seat Upholstery



Manual Seat Movement



Seat Belts



Seat Belt with issues



Head Rest



Door Controls And Trim

Front Left Door: Scratched





Door Hinge Condition



Carpet



Headliner



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<85%

LHS Rear Tyre

<85%

RHS Front Tyre

<85%

RHS Rear Tyre

<85%

Spare Tyre

<85%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE