



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2015 INFINITI QX50**

**LUXURY | 119,604 KM**

## Car highlights



### **Sunroof**

This car has a sunroof



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**















Enjoy your drive with bluetooth



### **Amazing Comfort**












Power driver seat, Memory Seats























## Basic Details

 Kilometers	<b>119604</b>	 Specs	<b>Yes</b>
 Engine	<b>3.7L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>All Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Red</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>6 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>JNRBJ0HR4FM260377</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Safety &amp; Security</b>	
360 degree Camera 	Navigation 
Parking Sensors Front 	Parking Sensors Rear 
Reverse Camera 	Traction Control 
Airbag Curtain Shield 	Airbag Driver Front 
ABS 	Central Locking 

Child Safety Locking			
 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Memory Seats		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Power Folding Mirrors	
Rear Defogger		Central Armrest	
Automatic Headlights		Steering Column Adjuster	
 <b>Exteriors</b>			
Fog Light Front		Roof Rails	
Rear Bumper Spoiler		Halogen Headlights	
HID Headlights			
 <b>Entertainment</b>			
Bluetooth Player		Infotainment System	
USB player			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door Condition: Scratched		Front right door Condition: Scratched	
---	---	--	---

Rear left door Condition: Scratched, Dented		Rear right door Condition: Dented	
--	---	--------------------------------------	---

### Fenders Condition

Left Fender		Right Fender Right Fender: Paint Chip-off	
-------------	---	--	---

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	--	---------------------	--

### Front Bumper Condition

Front Bumper 

### Rear Bumper Condition

Rear Bumper 

### Hood Condition

Hood 

### Trunk Condition

Trunk 

### Trunk condition

Trunk 

### Roof Condition

Roof 

### Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading		Right A to B Pillar Beading	
----------------------------	---	-----------------------------	---

Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
RHS Pillar B Condition	✓	Right C Pillar Trim	✓
RHS Pillar C Condition	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Left D pillar	✓		
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
No structural damage			
Chassis Conditon	✓	Upper Cross Member Condition	✓
Lower Cross Member Condition	✓	Chassis Condition	✓
Radiator Support	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓

Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna Bent/Broken/Fair Use Wear/Missing	!
Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓
Transmission Operation	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel Condition: Trim Faded	!	Shock absorbers	✓
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓

Suspension

Suspension



Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Door Locks

Central Locking Operation



Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Heads Up Display



Infotainment Display



OBD Connector



Navigation System



Music System



Sunroof Operation

Sunroof



Camera



Lights

Lights



Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Back Up Light



Fog Lights



Trunk Lid Release/Trunk Lid Light Operation



Air Conditioning

AC Air Direction Switch



Blower Motor





Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
Rear Blower Switch	✓	AC Wind Direction	✓
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Memory Seats	✓

### Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel Steering Wheel Fair Use Wear	⚠	Sunvisors	✓
Sunvisor	✓	Seat Upholstery Driver Seat: Minor Fair Wear/Fade off	⚠
Manual Seat Movement	✓	Seat Belts	✓
Seat Belt with issues	✓	Head Rest	✓
Door Controls And Trim	✓	Door Hinge Condition	✓
Grab Handle	✓	Carpet Front floor carpet: Missing/Torn	⚠
Headliner	✓	Rear View Mirror	✓
Toolkit Luggage Compartment: Scratched	⚠		

### Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓

Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<45%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE