



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 RENAULT SYMBOL

PE | 94,527 KM

VIN: VF14SRAB1KT459909

Car highlights



Running Lights

This car has a Running lights



Music System

Enjoy your drive with music system



Central Arm Rest
















Central arm rest for extra comfort



Tilt Steering wheel









Tilt steering wheel for extra comfort

Basic Details

 Kilometers	94527	 Specs	Yes
 Engine	1.6L	 Option Type	Basic Option
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Fabric Trim	 Number of Airbags	1 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	VF14SRAB1KT459909		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front		Running Lights	
 Comfort & Convenience			
Central Armrest			
 Entertainment			
USB Charging Port		Infotainment System	



Safety & Security

ABS



Central Locking



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door
Condition: Dented



Front right door
Condition: Beading Missing/Broken,
Scratched



Rear left door
Condition: Scratched



Rear right door
Condition: Scratched, Dented



Fenders Condition

Left Fender
Condition: Mud Flap Broken



Right Fender
Condition: Mud Flap Broken



Quarter Panels Condition

Left Quarter Panel
Condition: Scratched



Right Quarter Panel
Condition: Dented



Front Bumper Condition

Front Bumper
Condition: Scratched



Rear Bumper Condition

Rear Bumper
Rear Bumper: Scratched



Hood Condition

Hood
Bonnet: Rusted



Trunk condition

Trunk



Pillars Condition

Left A Pillar



Right A Pillar



Left B Pillar



RHS Pillar B Condition



RHS Pillar C Condition



Left C Pillar



Left D pillar



Running Board Condition

Left Running Board
Condition: Scratched



Right Running Board



Windshield Condition

Front Windshield
Condition: Spots



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



No structural damage

Chassis Condition



Upper Cross Member Condition



Lower Cross Member Condition



Chassis Condition



Radiator Support



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Grill Condition

Chrome Chipped



Window Glass



Wiper



Panel Condition

Rear Trunk Panel
Faded



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Transmission Operation

Drive Axle



Transmission Operation



 **Steering, Suspension & Brakes**

Steering

Steering wheel



Shock absorbers



Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



Suspension

Suspension



 **Electricals, Controls & Lights**

Keys

Master Key



Door Locks

Central Locking Operation



Child Safety Locking



Dashboard

Instrument Panel



Music System



Lights

Lights



Running lights



Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Back Up Light



Fog Lights

Right Fog Light: Cover Scratched



Trunk Lid Release/Trunk Lid Light Operation




Air Conditioning

AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
USB Charging Port	✓	Power/ Manual Windows	✓


Interiors & Luggage

Dashboard And Instrument Panel

Dashboard And Instrument Panel: Knob Chrome Faded, Infotainment System Display Faded, Cigarette Lighter Not Available, Trim Scratched 

Central Console

Condition: Trim Stained 

Cup Holder	✓	Sunvisors	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Seat Belt with issues	✓
Head Rest	✓	Door Controls And Trim Front Left Door: Scratched	
Door Hinge Condition	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			

LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE