



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 LAND ROVER RANGE ROVER SPORT

HSE | 103,334 KM

VIN: SALWA2VF3GA559667

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat, Memory Seats

Basic Details

 Kilometers	103334	 Specs	Yes
 Engine	3.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Gold
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	SALWA2VF3GA559667		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Panoramic Sunroof		Cruise Control	
Memory Seats		Steering Mounted Audio Controls	
Power Tailgate/ Power Trunk			
 Exteriors			
Fog Light Front		Running Lights	



Safety & Security

Parking Sensors Front



Navigation



Parking Sensors Rear



Reverse Camera



Blind Spot Monitor



ABS



Central Locking



Entertainment

Bluetooth Player



USB Charging Port



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door
Condition: Scratched



Front right door
Condition: Scratched



Rear left door
Condition: Scratched



Rear right door
Condition: Scratched, Dented



Fenders Condition

Left Fender
Condition: Scratched



Right Fender
Right Fender: Scratched



Quarter Panels Condition

Left Quarter Panel
Condition: Scratched



Right Quarter Panel
Condition: Scratched



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk condition

Trunk



Pillars Condition

Left A Pillar



Right A Pillar



Left B Pillar



RHS Pillar B Condition



RHS Pillar C Condition



Left C Pillar



Left D pillar



Running Board Condition

Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		
No structural damage			
Chassis Condition	✓	Upper Cross Member Condition	✓
Lower Cross Member Condition	✓	Chassis Condition	✓
Radiator Support	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	!	Left Rear Alloy/ Rim	✓
Alloy Wheel: Scratched			
Right Front Alloy/ Rim	!	Right Rear Alloy/ Rim	!
Alloy Wheel: Scratched		Alloy Wheel: Scratched	
Grill Condition	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body	⚠	Engine Performance	✓
Damage & Leaks: Engine Belt Cracked			
Engine Oil (Condition & Level)	⚠	Exhaust System	✓
Leakage From Tappet Cover			
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Transmission Operation			
Drive Axle	✓	Transmission Operation	✓

Steering, Suspension & Brakes

Steering			
Steering wheel		Shock absorbers	✓
Condition: Trim Faded	⚠		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Suspension	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Door Locks			
Central Locking Operation	✓	Child Safety Locking	✓
Dashboard			
Instrument Panel	✓		
Cruise Control	✓	Radar (If Equipped)	✓
Navigation System	✓	Music System	✓
Bluetooth Operations	✓		
Sunroof Operation			

Sunroof	✓		
Camera	✓		
Lights			
Lights	✓	Running lights	✓
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓	Back Up Light	✓
Fog Lights	✓	Trunk Lid Release/Trunk Lid Light Operation	✓
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Memory Seats	✓

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Dashboard And Instrument Panel: Trim Scratched	⚠	Condition: Fabric Torned	⚠
Cup Holder	✓	Sunvisors	✓
Seat Upholstery		Manual Seat Movement	✓
Driver Seat: Torned	⚠	Seat Belt with issues	✓
Seat Belts	✓	Door Controls And Trim	✓
Head Rest	✓		

Door Hinge Condition



Carpet



Headliner

Headliner condition: Torn/Dirty



Rear View Mirror



Toolkit

Luggage Compartment: Parcel Tray Missing



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE