



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





## 2015 MASERATI QUATTROPORTE

| 64,378 KM

VIN: ZAMSP56F3F1131953

### Car highlights



#### **Sunroof**

This car has a sunroof



#### **Cruise control**

Cruise control to drive with ease & comfort



#### **Bluetooth**
















Enjoy your drive with bluetooth



#### **Amazing Comfort**










Power driver seat, Memory Seats & more

Basic Details

 Kilometers	64378	 Specs	Yes
 Engine	3.0L	 Option Type	Basic Option
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Gold
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	ZAMSP56F3F1131953		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Sunroof		Cruise Control	
Memory Seats		Steering Mounted Audio Controls	
Central Armrest			
 <b>Exteriors</b>			
Fog Light Front		Running Lights	



## Safety & Security

Parking Sensors Front



Navigation



Parking Sensors Rear



Reverse Camera



Central Locking



## Entertainment

Bluetooth Player



USB Charging Port



Infotainment System



# 150 Point Detailed Inspection Report


We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
Condition: Scratched			

Rear left door		Rear right door	
----------------	---	-----------------	---

### Fenders Condition

Left Fender		Right Fender	
Condition: Scratched			

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
		Condition: Dented, Scratched	

### Front Bumper Condition

Front Bumper	
Condition: Scratched	

### Rear Bumper Condition

Rear Bumper	
Rear Bumper: Scratched	

### Hood Condition

Hood	
Bonnet: Scratched	

### Trunk conditon

Trunk	
-------	---

### Pillars Condition

Left A Pillar		Right A Pillar	
Condition: Scratched			

Left B Pillar		RHS Pillar B Condition	
---------------	---	------------------------	---

RHS Pillar C Condition		Left C Pillar	
------------------------	---	---------------	---

Left D pillar	
---------------	---

### Running Board Condition

Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield Condition: Spots	!	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		
No structural damage			
Chassis Conditon	✓	Upper Cross Member Condition	✓
Lower Cross Member Condition	✓	Chassis Condition	✓
Radiator Support	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror Body: Motor Not Working	!	Left Side Mirror	✓
Right Side Mirror Body: Minor Noise During Operation	!	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim Alloy Wheel: Scratched	!
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition	✓	Window Glass Front Left: Spots	!
Wiper	✓		
Panel Condition			
Rear Trunk Panel Scratched	!		



## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



### Battery

Battery Terminal & Tightness



### Transmission Operation

Drive Axle



Transmission Operation



## Steering, Suspension & Brakes

### Steering

Steering wheel

Condition: Trim Scratched, Media Control  
Scratched, Cruise Control Scratched



Shock absorbers



### Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



## Electricals, Controls & Lights

### Keys

Master Key



### Door Locks

Central Locking Operation



Child Safety Locking



### Dashboard

Instrument Panel



Cruise Control



Navigation System



Music System



Bluetooth Operations



### Sunroof Operation

Sunroof



## Lights

Lights



Running lights



Headlight



Interior Lights



Left: Adjuster Not Working

Tail Light Cluster



Turn Signal Lights



License Plate Light



Back Up Light



Fog Lights



Trunk Lid Release/Trunk Lid Light Operation



## Air Conditioning

AC Air Direction Switch



Blower Motor



Compressor



Condenser



AC Cooling



AC Switch



AC System Leaks



Heater



AC Heater Operation Switch



AC Blower Switch



AC Wind Direction



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



Seat Heaters



Memory Seats



## Interiors & Luggage

### Dashboard And Instrument Panel

Dashboard And Instrument Panel: Trim Scratched, Trim Faded, Infotainment System Scratched



### Central Console

Condition: Gear Knob Scratched, Trim Scratched, Parking Brake Scratched



Cup Holder



Sunvisors



Seat Upholstery

Driver Seat: Scratched



Manual Seat Movement



Seat Belts



Seat Belt with issues



Head Rest



Door Controls And Trim





Door Hinge Condition	✓	Carpet	⚠
		Front floor carpet: Torn/Damaged	
Headliner	⚠	Rear View Mirror	✓
Headliner condition: Scratched			
Toolkit	✓		

## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<85%
RHS Front Tyre	<85%	RHS Rear Tyre	<85%
Spare Tyre	<90%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE