



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 KIA CADENZA

LX | 85,592 KM

VIN: KNALB4125L5169367

Car highlights

Service History

Service history available



Cruise control

Cruise control to drive with ease & comfort



Apple play















Enjoy your drive with apple play



Amazing Comfort











Power driver seat

Basic Details

| | | | |
|----------------------------------------------------------------------------------------------------|--------------------------|-----------------------------------------------------------------------------------------------------|-----------------------------|
|  Kilometers | 85592 |  Specs | Yes |
|  Engine | 3.3L |  Option Type | Basic |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SEDAN |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color White |
|  Interior Trim | Fabric Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | KNALB4125L5169367 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  Comfort & Convenience | | | |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------|---------------------------------------------------------------------------------------|
| Climate Control AC |  | Cruise Control |  |
| Rear Armrest with cupholder |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors |  | Rear Defogger |  |
| Central Armrest |  | Automatic Headlights |  |
| Steering Column Adjuster |  | | |



Exteriors

Fog Light Front



Running Lights



Halogen Headlights



Performance

Paddle Shift



Safety & Security

Parking Sensors Rear



Reverse Camera



Traction Control



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Entertainment

Bluetooth Player



Apple Play



Android Auto Play



Infotainment System



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door
Condition: Scratched



Front right door
Condition: Scratched



Rear left door



Rear right door
Condition: Scratched



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper
Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood
Bonnet: Paint Chip-off < 5mm



Trunk Condition

Trunk



Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



| | | | |
|------------------------------------------------|---|------------------------------|---|
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| RHS Pillar B Condition | ✓ | Right C Pillar Trim | ✓ |
| RHS Pillar C Condition | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Left D pillar | ✓ | | |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Windshield Condition | | | |
| Front Windshield | | | |
| Beading: Mouldings Crack/ Fair Use Wear < 50mm | ⚠ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |
| No structural damage | | | |
| Chassis Conditon | ✓ | Upper Cross Member Condition | ✓ |
| Lower Cross Member Condition | ✓ | Chassis Condition | ✓ |
| Radiator Support | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | Right Hand Side Mirror | ✓ |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |

| | | | |
|------------------|---|-----------------|---|
| Antenna | ✓ | Grill Condition | ✓ |
| Monogram | ✓ | Window Glass | ✓ |
| Wiper | ✓ | | |
| Panel Condition | | | |
| Rear Trunk Panel | ✓ | | |

Engine & Transmission

Engine

| | | | |
|--------------------------------|---|--------------------|---|
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Turbocharger/ Supercharger | ✓ | Radiator Condition | ✓ |
| Radiator Coolant | ✓ | | |
| Battery | | | |
| Battery Terminal & Tightness | ✓ | | |
| Fuel System | | | |
| Fuel Tank | ✓ | | |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Gear shift | ✓ |
| Drive Axle | ✓ | Transmission Fluid | ✓ |
| Transmission Operation | ✓ | | |

Steering, Suspension & Brakes

Steering

| | | | |
|---------------------------------------------|---|-----------------------|---|
| Steering wheel Condition: Trim Scratched | ⚠ | Shock absorbers | ✓ |
| Brake System | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
| Suspension | | | |

Suspension



Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Central Locking Operation



Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Heads Up Display



Infotainment Display



OBD Connector



Music System



Bluetooth Operations



Camera



Lights

Lights



Running lights



Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Back Up Light



Fog Lights



Trunk Lid Release/Trunk Lid Light Operation



Air Conditioning

AC Air Direction Switch



Blower Motor



Compressor



Condenser



AC Cooling



AC Switch



AC System Leaks



Center AC Vent



| | | | |
|----------------------------|---|-----------------------|---|
| Front Right AC Vent | ✓ | Heater | ✓ |
| AC Heater Operation Switch | ✓ | AC Blower Switch | ✓ |
| Rear Blower Switch | ✓ | AC Wind Direction | ✓ |
| Parking Sensors | ✓ | Rear Defogger | ✓ |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |
| Memory Seats | ✓ | | |

Interiors & Luggage

| | | | |
|------------------------------------------------------------------|---|--------------------------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel Steering Wheel Fair Use Wear | ⚠ | Sunvisors | ✓ |
| Sunvisor | ✓ | Seat Upholstery Rear Seat: Stained | ⚠ |
| Manual Seat Movement | ✓ | Seat Belts | ✓ |
| Seat Belt with issues | ✓ | Head Rest | ✓ |
| Door Controls And Trim Rear Left Door: Scuffing/Disfiguration | ⚠ | Door Hinge Condition | ✓ |
| Grab Handle | ✓ | Carpet Front floor carpet: Torn/Damaged | ⚠ |
| Headliner | ✓ | Rear View Mirror | ✓ |
| Toolkit | ✓ | | |

Tyres

| | | | |
|----------------------------|---|---------------------------|---|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |

Spare Tyre



Life remaining

LHS Front Tyre

<55%

LHS Rear Tyre

<55%

RHS Front Tyre

<55%

RHS Rear Tyre

<55%

Spare Tyre

<75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE