



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 MASERATI GHIBLI

S | 74,294 KM

VIN: ZAMYS57F9K1309124

Car highlights



Great condition

Car has low imperfections



Adaptive cruise control

Adaptive cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort






Power driver seat, Seat Heaters & more




Basic Details

| | | | |
|--|--------------------------|---|----------------------------|
|  Kilometers | 74294 |  Specs | Yes |
|  Engine | 3.0L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | Rear Wheel Drive |
|  Body Type | SEDAN |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Blue |
|  Interior Trim | Leather Trim |  Number of Airbags | 6 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | ZAMYS57F9K1309124 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  Safety & Security | | | |
|---|---|----------------------|---|
| Adaptive cruise control |  | 360 degree Camera |  |
| Lane Departure Warning System |  | Navigation |  |
| Parking Sensors Front |  | Parking Sensors Rear |  |
| Reverse Camera |  | Blind Spot Monitor |  |
| Collision Warning System |  | Traction Control |  |

| | | | |
|--|---|---------------------------------|---|
| Front Camera | ✓ | Side Camera | ✓ |
| Airbag Curtain Shield | ✓ | Airbag Driver Front | ✓ |
| ABS | ✓ | Central Locking | ✓ |
| Child Safety Locking | ✓ | | |
|  Comfort & Convenience | | | |
| Climate Control AC | ✓ | Cruise Control | ✓ |
| Rear Armrest with cupholder | ✓ | Steering Mounted Audio Controls | ✓ |
| Soft Door Close | ✓ | Power Folding Mirrors | ✓ |
| Ventilated Seat | ✓ | Power Tailgate/ Power Trunk | ✓ |
| Rear Defogger | ✓ | Central Armrest | ✓ |
| Remote Engine Start | ✓ | Automatic Headlights | ✓ |
| Steering Column Adjuster | ✓ | | |
|  Performance | | | |
| Paddle Shift | ✓ | | |
|  Exteriors | | | |
| Running Lights | ✓ | LED Headlights | ✓ |
|  Entertainment | | | |
| Bluetooth Player | ✓ | Infotainment System | ✓ |
| USB player | ✓ | | |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Panel: Paint Chip-off < 5mm

Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk Condition

Trunk



Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



| | | | |
|---------------------------------------|---|------------------------------|---|
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| RHS Pillar B Condition | ✓ | Right C Pillar Trim | ✓ |
| RHS Pillar C Condition | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Left D pillar | ✓ | | |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Sunroof Glass Condition (If Equipped) | | | |
| Sun Roof Glass | ✓ | | |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |
| No structural damage | | | |
| Chassis Conditon | ✓ | Upper Cross Member Condition | ✓ |
| Lower Cross Member Condition | ✓ | Chassis Condition | ✓ |
| Radiator Support | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | Right Hand Side Mirror | ✓ |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ! | Left Rear Alloy/ Rim | ✓ |
| Alloy Wheel: Scratched | | | |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ! |
| | | Alloy Wheel: Scratched | |

| | | | |
|----------------------------|---|----------|---|
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel cover | ✓ | Antenna | ✓ |
| Grill Condition | ✓ | Monogram | ✓ |
| Window Glass | ✓ | Wiper | ✓ |
| Panel Condition | | | |
| Rear Trunk Panel | ✓ | | |

Engine & Transmission

| | | | |
|--------------------------------|---|--------------------|---|
| Engine | | | |
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Turbocharger/ Supercharger | ✓ | Radiator Condition | ✓ |
| Radiator Coolant | ✓ | | |
| Battery | | | |
| Battery Terminal & Tightness | ✓ | | |
| Fuel System | | | |
| Fuel Tank | ✓ | | |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Gear shift | ✓ |
| Drive Axle | ✓ | Transmission Fluid | ✓ |
| Transmission Operation | ✓ | | |

Steering, Suspension & Brakes

| | | | |
|------------------------|---|-----------------------|---|
| Steering | | | |
| Steering wheel | ✓ | Shock absorbers | ✓ |
| Brake System | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
| Suspension | | | |

Suspension



Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Central Locking Operation



Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Heads Up Display



Infotainment Display



OBD Connector



Radar (If Equipped)



Navigation System



Music System



Bluetooth Operations



Sunroof Operation

Sunroof



Camera



Lights

Lights



Running lights



Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Back Up Light



Fog Lights



Trunk Lid Release/Trunk Lid Light Operation



Air Conditioning

| | | | |
|----------------------------|---|-------------------|---|
| AC Air Direction Switch | ✓ | Blower Motor | ✓ |
| Compressor | ✓ | Condenser | ✓ |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| AC Heater Operation Switch | ✓ | AC Blower Switch | ✓ |
| Rear Blower Switch | ✓ | AC Wind Direction | ✓ |
| Rear Left AC Vent | ✓ | | |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | Seat Heaters | ✓ |
| Memory Seats | ✓ | | |

Interiors & Luggage

| | | | |
|--------------------------------|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console Box: Minor Crack/Fair Use Wear/ Scuffing | ⚠ |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ✓ | Sunvisors | ✓ |
| Sunvisor | ✓ | Seat Upholstery | ✓ |
| Manual Seat Movement | ✓ | Seat Belts | ✓ |
| Seat Belt with issues | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Door Hinge Condition | ✓ |
| Grab Handle | ✓ | Carpet | ✓ |
| Headliner | ✓ | Rear View Mirror | ✓ |
| Toolkit | ✓ | | |

Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<65%

LHS Rear Tyre

<75%

RHS Front Tyre

<65%

RHS Rear Tyre

<75%

Spare Tyre

<45%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE