



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.







**2015 BENTLEY FLYING SPUR**

**FLYING SPUR V8 | 67,776 KM**

VIN: SCBEN5ZAXFC046297

## **Car highlights**



### **Power packed**

Engine size of 4.0 Litres & 8.0 cylinders



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**

Enjoy your drive with bluetooth


















### **Amazing Comfort**

Power driver seat, Memory Seats












Basic Details



 Kilometers	67776	 Specs	Yes
 Engine	4.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	SCBEN5ZAXFC046297		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Sunroof		Cruise Control	
Memory Seats		Steering Mounted Audio Controls	
Power Tailgate/ Power Trunk		Central Armrest	
Remote Engine Start			
 <b>Exteriors</b>			



Fog Light Front	✓	Running Lights	✓
 <b>Safety &amp; Security</b>			
Parking Sensors Front	✓	Navigation	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Central Locking	✓		
 <b>Entertainment</b>			
Bluetooth Player	✓		



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
Condition: Beading Faded		Condition: Beading Faded, Scratched	
Rear left door		Rear right door	
Condition: Scratched, Beading Faded, Exit Light Not Working		Condition: Scratched, Beading Faded	

### Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Sunblind Damaged			

### Front Bumper Condition

Front Bumper	
Condition: Scratched	

### Rear Bumper Condition

Rear Bumper	
Rear Bumper: Scratched	








### Hood Condition

Hood	
------	---

### Trunk conditon

Trunk	
-------	---

### Pillars Condition

Left A Pillar		Right A Pillar	
Condition: Cover Broken			
Left B Pillar		RHS Pillar B Condition	
RHS Pillar C Condition		Left C Pillar	
Left D pillar			



Running Board Condition			
Left Running Board	✓	Right Running Board Condition: Faded	!
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield Condition: Beading Missing/Broken, Scratched	!	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		
No structural damage			
Chassis Conditon	✓	Upper Cross Member Condition	✓
Lower Cross Member Condition	✓	Chassis Condition	✓
Radiator Support	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition	✓	Window Glass Rear Right: Beading Missing/Broken, Spots	!
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		



## Engine & Transmission

### Engine

#### Engine Body

Damage & Leaks: Engine Belt Cracked



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Leakage From Tappet Cover

Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



### Battery

Battery Terminal & Tightness



Transmission Operation

Drive Axle



Transmission Operation



## Steering, Suspension & Brakes

### Steering

Steering wheel

Condition: Trim Faded, Minor Vibration



Shock absorbers



### Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



## Electricals, Controls & Lights

### Keys

Master Key

Scratched



Remote Key Operations

Keyless/ Remote Start



### Door Locks

Central Locking Operation



Child Safety Locking



### Dashboard

Instrument Panel



Controls



Cruise Control





Navigation System



Music System

Condition: Minor Buzz Noise When Operating



Bluetooth Operations



Sunroof Operation

Sunroof



Camera



Lights

Lights



Running lights



Headlight

Left: Faded



Interior Lights



Tail Light Cluster

Left Tail Lamp: Scratched



Turn Signal Lights



License Plate Light



Back Up Light



Fog Lights



Trunk Lid Release/Trunk Lid Light Operation



Air Conditioning

AC Air Direction Switch



Blower Motor



Compressor



Condenser



AC Cooling



AC Switch



AC System Leaks



Heater



AC Heater Operation Switch



AC Blower Switch



AC Wind Direction



Rear Defogger



USB Charging Port



Power/ Manual Windows



Memory Seats



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Sunvisors



Seat Upholstery

Driver Seat: Depressed/Pressure Mark



Manual Seat Movement





Seat Belts	✓	Seat Belt with issues	✓
Head Rest	✓	Door Controls And Trim	✓
Door Hinge Condition	✓	Carpet	✓
Headliner			
Headliner condition: Roof Light Not Working/Broken	!	Rear View Mirror	✓
Toolkit	✓		

## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<55%
RHS Front Tyre	<75%	RHS Rear Tyre	<55%
Spare Tyre	<55%		





## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE