



#### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



# 2015 RENAULT DUSTER PE | 121,489 KM

VIN: VF1HSRCH4FA531190

## **Car highlights**



## **Running Lights**

This car has a Running lights



#### **Bluetooth**

Enjoy your drive with bluetooth



#### **Music System**


Enjoy your drive with music system



## **Amazing Comfort**


Power driver seat


#### **Basic Details**



## **Specs and features**

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.






#### **150 Point Detailed Inspection Report**


Trunk conditon

Trunk

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



## **Roof Condition** Roof Pillars Condition Left A Pillar Right A Pillar Left A to B Pillar Beading Right A to B Pillar Beading Left B Pillar Right A to B Pillar Condition: Light Scuffing Scratch < 50mm Left B Pillar Trim Left B to C Pillar Beading Right C Pillar Trim Right B to C Pillar Right B to C Pillar Beading Left C Pillar Beading Crack/ Tear < 5mm **Running Board Condition** Right Running Board Left Running Board (!) (!) Condition: Light Scuffing < 80mm Condition: Light Scuffing < 80mm Windshield Condition Front Windshield Condition: Driver Side/Stone Chip (!) Rear Windshield Mark<5mm, Passenger Side/Stone Chip Mark<8mm Structural Assessment **Chassis Condition** Radiator Support Apron **Boot Floor** Firewall Condition Cowl Top Head Light Support Condition Cowl Top Cowl Top Rear View Mirror Condition Left Hand Side Mirror Right Side Mirror Body: Light Scuffing < 50mm Right Hand Side Mirror Alloy Wheel/ Rim Spare Alloy/ Rim Condition





## **Electricals, Controls & Lights**

| 1/ | -  |  |
|----|----|--|
| n  | -1 |  |
|    |    |  |

Master Key (!) **Button Faded** 

Spare Key(s)

Door Locks

Child Safety Locking

Dashboard

Instrument Panel

Airbags

Controls

**Engine Sensors** 

Airbags

Infotainment Display

**OBD** Connector

Music System

Lights

Headlight Left: Light Scuff Marks < 50mm

(!) Interior Lights

Tail Light Cluster

Left Tail Lamp: Light Scuffing < 50mm

Daylight Running Lights

License Plate Light

Fog Lights

Air Conditioning

AC Cooling

AC Switch

AC System Leaks

Center AC Vent Colour Faded

Front Right AC Vent

Color Faded

Heater

**USB Charging Port** 

Power/ Manual Windows



🚊 Interiors & Luggage

| Dashboard And Instrument Panel Dashboard Upholstery: Minor Color Dullness  | (!)   | Central Console  Box: Minor Crack/Fair Use Wear/ Scuffing | !            |
|--|---|---|--------------|
| Cup Holder   | <b>✓</b>  | Glove Box   | <b>✓</b>     |
| Steering Wheel Steering Wheel Fair Use Wear  | (!)   | Sunvisor  | •            |
| Seat Upholstery Driver Seat: Minor Smudge/ Cracks, Minor Fair Wear/Fade off  | (!)   | Manual Seat Movement                                      | •            |
| Seat Belts   | <b>✓</b>  | Head Rest   | <b>✓</b>     |
| Door Controls And Trim Front Left Door: Light Scuffing   | (!)   | Grab Handle   | •            |
| Carpet Trunk Floor Carpet: Fair Use Wear < 80mm  | !   | Headliner Rear Left: Smudge/Disfiguration                 | (!)          |
|  |   |   |              |
| Rear View Mirror  De Silvered Mirror<10%   | !   | Toolkit   | <b>✓</b>     |
|  | !   | Toolkit   | •            |
| De Silvered Mirror<10%   | <u>.</u>  | Toolkit   |              |
| De Silvered Mirror<10%  Tyres  | •   | Toolkit  Left Hand Side Rear Tyre                         |              |
| De Silvered Mirror<10%  Tyres  Tyres Condition   | (!)  • • • • • • • • • • • • • • • • • •  |   |              |
| De Silvered Mirror<10%  Tyres  Tyres Condition  Left Hand Side Front Tyre  | (!)  **Y  **Y   | Left Hand Side Rear Tyre                                  |              |
| De Silvered Mirror<10%  Tyres  Tyres Condition  Left Hand Side Front Tyre  Right Hand Side Front Tyre              |   | Left Hand Side Rear Tyre                                  |              |
| Tyres  Tyres Condition  Left Hand Side Front Tyre  Right Hand Side Front Tyre  Spare Tyre                          | <ul><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li><li>.</li>&lt;</ul> | Left Hand Side Rear Tyre                                  | <75%         |
| Tyres  Tyres Condition  Left Hand Side Front Tyre  Right Hand Side Front Tyre  Spare Tyre  Tyres Depth (Remaining) | <ul><li></li><li></li><li></li></ul>  | Left Hand Side Rear Tyre Right Hand Side Rear Tyre        | <75%<br><55% |



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE