



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 TOYOTA YARIS

SE | 91,994 KM

VIN: MHFB29F35K2045276

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Rear



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat

Basic Details

 Kilometers	91994	 Specs	Yes
 Engine	1.5L	 Option Type	Mid Option
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MHFB29F35K2045276		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Rear Defogger	
Central Armrest			
 Safety & Security			
Parking Sensors Rear		Traction Control	
Airbag Driver Front		ABS	

Central Locking	✓	Child Safety Locking	✓
 Entertainment			
Bluetooth Player	✓	USB player	✓
 Exteriors			
Halogen Headlights	✓		





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
Handle: Paint Chip-off < 5mm		Panel: Light Scuffing < 50mm	
Rear left door		Rear right door	
Handle: Light Scuffing < 50mm		Panel: Paint Chip-off < 5mm	

Fenders Condition

Left Fender		Right Fender	
Condition: Light Scuffing < 50 mm		Condition: Acid Marks/ Bird Dropping < 5mm	

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Light Scuffing<50mm		Condition: Light Scuffing<50mm	

Front Bumper Condition

Front Bumper	
--------------	---


Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm	

Hood Condition

Hood	
Bonnet: Light Scuffing < 50mm, Acid Marks/ Bird Dropping < 5mm	

Trunk Condition

Trunk	
Door Trim: Light Scuffing < 50mm	

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar
Inner Condition: Fair Use Wear



Left A to B Pillar Beading



Right A to B Pillar



Left B Pillar Trim



Right C Pillar Trim



Right B to C Pillar Beading



Running Board Condition

Left Running Board

Front Left Sill Trim: Minor Scuffing < 80mm



Windshield Condition

Front Windshield



Structural Assessment

Chassis Condition



Apron



Firewall Condition



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror

Body: Light Scuffing < 50mm



Right Side Mirror

Body: Light Scuffing < 50mm



Alloy Wheel/ Rim

Spare Alloy/ Rim Condition



Wheel Arch



Antenna



Right A Pillar

Inner Condition: Light Scuffing



Right A to B Pillar Beading



Left B Pillar



Left B to C Pillar Beading



Right B to C Pillar

Low Visual Dent < 50mm



Left C Pillar



Right Running Board

Front Right Sill Trim: Light Scuffing < 80mm



Rear Windshield

Tint Fair Use Wear < 30mm



Radiator Support



Boot Floor



Cowl Top



Left Side Mirror



Right Hand Side Mirror



Wheel cover

Front Left: Light Scuffing < 50mm, Scuffing > 50mm



Grill Condition

Light Scuffing < 50mm



Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	License Plate Light	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted, Minor Scuffing/ Crack/ Fair Use Wear	!	Cigarette Lighter: Cigarette Lighter Missing	!
Cup Holder	✓	Glove Box	
		Glove Box: Minor Scuffing/Crack/Fair Use Wear	!

Steering Wheel	!	Sunvisor	✓
Steering Wheel Fair Use Wear			
Seat Upholstery	!	Manual Seat Movement	✓
Driver Seat: Minor Smudge/ Cracks, Minor Fair Wear/Fade off			
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	!	Grab Handle	✓
Front Left Door: Light Scuffing/ Disfiguration			
Carpet	!	Headliner	!
Front Left Floor Carpet: Smudge/Fair Use Wear		Front Left: Light Smudge/Disfiguration	
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<55%	LHS Rear Tyre	<75%
RHS Front Tyre	<55%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE