



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2014 JAGUAR F TYPE

S | 119,843 KM

VIN: SAJAA65G2E8K07204

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat








Basic Details

 Kilometers	119843	 Specs	Yes
 Engine	3.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	COUPE	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Leather Trim	 Number of Airbags	4 Airbags
 Seating Capacity	2 Seats	 Number of keys	1 Keys
 VIN number	SAJAA65G2E8K07204		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Steering Mounted Audio Controls	
Central Armrest			
 Safety & Security			
Navigation		Parking Sensors Rear	
Reverse Camera		ABS	

Central Locking		
 Exteriors		
Running Lights		
 Entertainment		
Bluetooth Player		USB Charging Port 
Infotainment System		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door

Condition: Scratched



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Condition: Scratched

Right Quarter Panel



Condition: Scratched

Front Bumper Condition

Front Bumper



Condition: Scratched

Rear Bumper Condition

Rear Bumper



Rear Bumper: Scratched

Hood Condition

Hood



Bonnet: Scratched

Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left B Pillar



Condition: Scratched

RHS Pillar B Condition































RHS Pillar C Condition












Left C Pillar



Left D pillar			
Running Board Condition			
Left Running Board		Right Running Board	
Windshield Condition			
Front Windshield			
Condition: Beading Missing/Broken, Scratched		Rear Windshield	
Structural Assessment			
Chassis Condition		Apron	
Boot Floor			
Condition: Carpet Torn		Firewall Condition	
Head Light Support Condition			
No structural damage			
Chassis Conditon		Upper Cross Member Condition	
Lower Cross Member Condition		Chassis Condition	
Radiator Support			
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Body: Scratched			
Right Side Mirror		Right Hand Side Mirror	
Body: Scratched			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Alloy Wheel: Scratched			
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Alloy Wheel: Scratched			
Grill Condition		Window Glass	
Broken			
Wiper			
Panel Condition			
Rear Trunk Panel			







 **Engine & Transmission**

Engine

Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Turbocharger/ Supercharger		Radiator Condition	
Radiator Coolant			
Battery			
Battery Terminal & Tightness			
Transmission Operation			
Drive Axle		Transmission Operation	






 **Steering, Suspension & Brakes**

Steering

Steering wheel Condition: Trim Faded, Media Control Faded		Shock absorbers	
Brake System			
Parking Brake		Brake Master Cylinder	
Brake Fluid			
Suspension			
Suspension			

 **Electricals, Controls & Lights**

Keys

Master Key			
Door Locks			
Central Locking Operation			
Dashboard			
Instrument Panel			
Cruise Control		Navigation System	

Music System	✓	Bluetooth Operations	✓
Camera	✓		
Lights			
Lights	✓	Running lights	✓
Headlight Left: Scratched	!	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓	Back Up Light	✓
Trunk Lid Release/Trunk Lid Light Operation	✓		
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Dashboard And Instrument Panel: Knob Broken	!	Condition: Gear Lever Knob Scratched, Trim Scratched, Cup Holder Stained	!
Cup Holder	✓	Sunvisors	✓
Seat Upholstery		Manual Seat Movement	✓
Driver Seat: Depressed/Pressure Mark, Cushion Broken	!	Seat Belt with issues	✓
Seat Belts	✓		

Head Rest



Door Controls And Trim



Front Left Door: Scratched

Door Hinge Condition



Carpet



Headliner

Headliner condition: Torn/Dirty



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<75%

RHS Front Tyre

<75%

RHS Rear Tyre

<75%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE