



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





## 2019 NISSAN KICKS

SV | 71,389 KM

VIN: 3N1CP5C90KL480775

### Car highlights



#### **Great Parking Assistance**

Reverse Camera



#### **Navigation**

Navigation to drive with ease & comfort



#### **Bluetooth**
















Enjoy your drive with bluetooth



#### **Amazing Comfort**










Power driver seat



Basic Details

 Kilometers	71389	 Specs	Yes
 Engine	1.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Orange
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	3N1CP5C90KL480775		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

<div> Exteriors</div>			
Fog Light Front	<div></div>	Roof Rails	<div></div>
Halogen Headlights	<div></div>		
<div> Safety &amp; Security</div>			
Navigation	<div></div>	Reverse Camera	<div></div>
Traction Control	<div></div>	Airbag Driver Front	<div></div>

ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 <b>Comfort &amp; Convenience</b>			
Steering Mounted Audio Controls	✓	Rear Defogger	✓
Central Armrest	✓	Automatic Headlights	✓
 <b>Entertainment</b>			
Bluetooth Player	✓	Infotainment System	✓
USB player	✓		





# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior



### Doors condition

Front left door		Front right door	
Inner Beading: Rubber Crack/ Tear < 5mm		Panel: Light Scuffing < 50mm	
Rear left door		Rear right door	
Panel: Light Scuffing < 50mm			

### Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---


### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
		Condition: Low Visual Dent < 30mm, Chip<5mm	


### Front Bumper Condition

Front Bumper	
--------------	---


### Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm	

### Hood Condition

Hood	
Bonnet: Paint Chip-off < 5mm	

### Trunk Condition

Trunk	
Door Trim: Light Scuffing < 50mm, Scuff/Disfiguration< 50mm	

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	
------	---

### Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm	!	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror Body: Scratch < 50mm	!	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim Rim: Alloy Edge Scuffing > 50mm, Alloy Face Light Scuffing < 50mm	!
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim Rim: Alloy Edge/Scuffing<80mm	!
Spare Alloy/ Rim Condition	✓		

Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Navigation System



Music System

Steering Mounted Audio Controls: Button(s)  
Faded



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



USB Charging Port



Power/ Manual Windows



## Interiors & Luggage



Dashboard And Instrument Panel	✓	Central Console Cigarette Lighter: Cigarette Lighter Missing	!
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor Left: Sunvisor LHS Minor Crack/Fair Use Wear, Sunvisor RHS Minor Crack/Damage	!
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Front Left Door: Light Scuffing	!	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE