



#### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



# 2018 AUDI A5 40 TFSI SPORT | 55,702 KM

VIN: WAUZZZF53JN007739

## **Car highlights**



#### **Great condition**

Car has low imperfections



#### **Cruise control**

Cruise control to drive with ease & comfort



#### **Bluetooth**


Enjoy your drive with bluetooth



### **Amazing Comfort**


Power driver seat, Memory Seats


#### **Basic Details**



## **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.





### **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left A to B Pillar Beading	<b>✓</b>	Right A to B Pillar Beading	<b>✓</b>
Right A to B Pillar	<b>✓</b>	Left B Pillar	<b>✓</b>
Left B Pillar Trim	<b>✓</b>	Right C Pillar Trim	<b>✓</b>
Running Board Condition			
Left Running Board	<b>✓</b>	Right Running Board	<b>✓</b>
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	<b>✓</b>		
Windshield Condition			
Front Windshield	<b>✓</b>	Rear Windshield	<b>✓</b>
Structural Assessment			
Chassis Condition	<b>✓</b>	Radiator Support	<b>✓</b>
Apron	<b>✓</b>	Boot Floor	<b>✓</b>
Firewall Condition	<b>✓</b>	Cowl Top	•
Head Light Support Condition	<b>✓</b>		
Cowl Top			
Cowl Top	<b>✓</b>		
Rear View Mirror Condition			
Left Hand Side Mirror	<b>✓</b>	Left Side Mirror	<b>✓</b>
Right Side Mirror	<b>✓</b>	Right Hand Side Mirror	<b>✓</b>
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	<b>✓</b>	Left Rear Alloy/ Rim	<b>✓</b>
Right Front Alloy/ Rim	<b>✓</b>	Right Rear Alloy/ Rim	<b>✓</b>
Spare Alloy/ Rim Condition	<b>✓</b>		
Wheel cover	<b>✓</b>	Antenna	<b>✓</b>
Grill Condition	(!)	Monogram	<b>✓</b>
Light Scuffing < 50mm			
Window Glass	<b>✓</b>	Wiper	<b>✓</b>
Panel Condition			

Rear Trunk Panel	•		
<b>■</b> Engine & Transmission			
Engine			
Engine Body	<b>✓</b>	Engine Performance	<b>✓</b>
Engine Oil (Condition & Level)	<b>✓</b>	Exhaust System	~
Turbocharger/ Supercharger	<b>✓</b>	Radiator Condition	~
Radiator Coolant	<b>✓</b>		
Battery			
Battery Terminal & Tightness	<b>✓</b>		
Fuel System			
Fuel Tank	<b>✓</b>		
Transmission Operation			
Gear Shifting	<b>✓</b>	Gear shift	<b>✓</b>
Drive Axle	<b>✓</b>	Transmission Fluid	<b>✓</b>
Steering, Suspension & Brakes			
Steering			
Steering wheel	<b>✓</b>		
Brake System			
Parking Brake	<b>✓</b>	Brake Master Cylinder	<b>✓</b>
Brake Disc & Brake Pad	<b>✓</b>	Brake Fluid	<b>✓</b>
Pedals	<b>✓</b>		
Suspension			
Shock Absorbers	<b>✓</b>		
Electricals, Controls & Lights			
Keys			
Master Key	<b>✓</b>		
Dashboard			

Instrument Panel	~		
Airbags			
Airbags	<b>✓</b>		
Cruise Control	<b>✓</b>	Infotainment Display	•
Engine Sensors	<b>✓</b>	OBD Connector	•
Radar (If Equipped)	<b>✓</b>	Navigation System	•
Music System	<b>✓</b>		
Sunroof Operation			
Sunroof	<b>✓</b>		
Camera	•		
Lights			
Headlight	<b>✓</b>	Interior Lights	•
Tail Light Cluster	<b>✓</b>	Turn Signal Lights	<b>~</b>
Daylight Running Lights	<b>✓</b>	License Plate Light	<b>✓</b>
Air Conditioning			
AC Cooling	<b>✓</b>	AC Switch	<b>~</b>
AC System Leaks	<b>✓</b>	Center AC Vent	<b>✓</b>
Front Right AC Vent	<b>✓</b>	Heater	•
Rear Blower Switch	<b>✓</b>		
Rear Defogger	~	USB Charging Port	•
Power/ Manual Windows	•	Memory Seats	•
🖺 Interiors & Luggage			
Dashboard And Instrument Panel	~	Central Console	•
Glove Box	<b>✓</b>	Steering Wheel	<b>✓</b>

Sunvisor	•	Seat Upholstery	<b>✓</b>
Manual Seat Movement	<b>✓</b>	Seat Belts	•
Head Rest	<b>✓</b>	Door Controls And Trim	<b>✓</b>
Grab Handle	<b>✓</b>	Carpet	<b>✓</b>
Headliner	<b>✓</b>	Rear View Mirror	•
Toolkit	<b>✓</b>		
Tyres			
Tyres Condition			
	•	Left Hand Side Rear Tyre	<b>✓</b>
Tyres Condition	<b>⋄</b>	Left Hand Side Rear Tyre Right Hand Side Rear Tyre	<ul><li></li><li></li></ul>
Tyres Condition  Left Hand Side Front Tyre	<ul><li></li><li></li><li></li><li></li><!--</td--><td></td><td><b>✓</b></td></ul>		<b>✓</b>
Tyres Condition  Left Hand Side Front Tyre  Right Hand Side Front Tyre	<b>&gt;</b>		✓
Tyres Condition  Left Hand Side Front Tyre  Right Hand Side Front Tyre  Spare Tyre	<65%		<65%
Tyres Condition  Left Hand Side Front Tyre  Right Hand Side Front Tyre  Spare Tyre  Life remaining	<65% <65%	Right Hand Side Rear Tyre	<65% <65%



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE