

# **Car Report**



#### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2017 AUDI A6 35 TFSI | 131,495 KM

VIN: WAUACCFC5HN062312

### Car highlights



### Supercharger/turbocharger

This car has a Supercharger/turbocharger



**Cruise control** 

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



**Amazing Comfort** 

Power driver seat, Memory Seats

### **Basic Details**

Kilometers 131495	GCC Specs Yes
Engine 1.8L	Option Type Basic Option
Transmission Automatic	Front Wheel Drive
Body Type SEDAN	Fuel Petrol
Image: Wheel Type         Alloy Wheels	Exterior Color Exterior Color White
Interior Trim     Leather Trim	Number of Airbags 6 Airbags
Beating Capacity 5 Seats	Number of keys 2 Keys
VIN number WAUACCFC5HN062312	

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

🖄 Comfort & Convenience			
Climate Control AC	~	Cruise Control	~
Memory Seats	~	Rear Armrest with cupholder	~
Steering Mounted Audio Controls	<ul> <li>Image: A start of the start of</li></ul>	Power Folding Mirrors	~
Rear Defogger	~	Central Armrest	~
Automatic Headlights	~		

Exteriors			
Fog Light Front	~	Running Lights	~
LED Headlights	~	HID Headlights	~
Safety & Security			
Navigation	~	Parking Sensors Front	~
Parking Sensors Rear	~	Reverse Camera	~
Traction Control	~	Airbag Curtain Shield	~
Airbag Driver Front	~	ABS	~
Central Locking	~	Child Safety Locking	~
Bluetooth Player	~	Infotainment System	~
USB player	~		

## **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed			
🕾 Exterior			
Doors condition			
Front left door	<ul> <li></li> </ul>	Front right door Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm	(!)
Rear left door	<ul> <li></li> </ul>	Rear right door Panel: Paint Chip-off < 5mm	(!)
Fenders Condition			
Left Fender	<ul> <li>Image: A start of the start of</li></ul>	Right Fender	~
Quarter Panels Condition			
Left Quarter Panel	<ul> <li>Image: A start of the start of</li></ul>	Right Quarter Panel	<ul> <li>Image: A start of the start of</li></ul>
Front Bumper Condition			
Front Bumper	~		
Rear Bumper Condition			
Rear Bumper Rear Bumper: Light Scuffing < 80mm	(!)		
Hood Condition			
Hood Bonnet: Low Visibility Dent < 30mm, Paint Chip-off < 5mm	(!)		
Trunk Condition			
Trunk	<ul> <li></li> </ul>		
Trunk conditon			
Trunk	<ul> <li></li> </ul>		
Pillars Condition			
Left A Pillar	<ul> <li>Image: A start of the start of</li></ul>	Right A Pillar	~
Left A to B Pillar Beading	<ul> <li>Image: A start of the start of</li></ul>	Right A to B Pillar Beading	~

Right A to B Pillar	<ul> <li>Image: A start of the start of</li></ul>	Left B Pillar	~
Left B Pillar Trim	<ul> <li>Image: A start of the start of</li></ul>	Left B to C Pillar Beading	~
Right C Pillar Trim	<ul> <li></li> </ul>	Right B to C Pillar	~
Right B to C Pillar Beading	<ul> <li></li> </ul>	Left C Pillar	<ul> <li></li> </ul>
Running Board Condition			
Left Running Board	<ul> <li></li> </ul>	Right Running Board Condition: Light Scuffing < 80mm	(!)
Windshield Condition			
Front Windshield	<ul> <li>Image: A start of the start of</li></ul>	Rear Windshield	•
Structural Assessment			
Chassis Condition	<ul> <li>Image: A start of the start of</li></ul>	Radiator Support	~
Apron	<ul> <li>Image: A start of the start of</li></ul>	Boot Floor	~
Firewall Condition	~	Cowl Top	~
Head Light Support Condition	<ul> <li>Image: A start of the start of</li></ul>		
Cowl Top			
Cowl Top	<ul> <li>Image: A start of the start of</li></ul>		
Rear View Mirror Condition			
Left Hand Side Mirror Body: Light Scuffing < 50mm	!	Left Side Mirror	~
Right Side Mirror	<ul> <li>Image: A start of the start of</li></ul>	Right Hand Side Mirror	~
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Rim: Alloy Face Light Scuffing < 50mm, Alloy Edge Scuffing > 50mm	(!)	Left Rear Alloy/ Rim Rim: Alloy Face Light Scuffing < 50mm, Alloy Edge Scuffing > 50mm	!
Right Front Alloy/ Rim Rim: Alloy Face Light Scuffing < 50mm, Alloy Edge Scuffing < 80mm	(!)	Right Rear Alloy/ Rim Rim: Alloy Face/Light Scuffing<50mm, Alloy Edge/Scuffing<80mm	(!)
Spare Alloy/ Rim Condition	<ul> <li>Image: A start of the start of</li></ul>		
Antenna	~	Grill Condition Light Scuffing < 50mm	!
Monogram	~	Window Glass	~

Wiper	
Panel Condition	
Rear Trunk Panel	

🖲 Eng	ine &	Transm	ission
-------	-------	--------	--------

Engine			
Engine Body	<ul> <li></li> </ul>	Engine Performance	<ul> <li></li> </ul>
Engine Oil (Condition & Level)	<ul> <li>Image: A start of the start of</li></ul>	Exhaust System	<ul> <li></li> </ul>
Turbocharger/ Supercharger	<ul> <li></li> </ul>	Radiator Condition	<ul> <li></li> </ul>
Radiator Coolant	<ul> <li></li> </ul>		
Battery			
Battery Terminal & Tightness	<ul> <li></li> </ul>		
Fuel System			
Fuel Tank	<ul> <li>Image: A start of the start of</li></ul>		
Transmission Operation			
Gear Shifting	<ul> <li></li> </ul>	Gear shift	<ul> <li>Image: A start of the start of</li></ul>
Drive Axle	<ul> <li></li> </ul>	Transmission Fluid	<ul> <li></li> </ul>

### Steering, Suspension & Brakes

Steering			
Steering wheel	<ul> <li></li> </ul>		
Brake System			
Parking Brake	<ul> <li></li> </ul>	Brake Master Cylinder	~
Brake Disc & Brake Pad	<ul> <li>Image: A start of the start of</li></ul>	Brake Fluid	<ul> <li>Image: A start of the start of</li></ul>
Pedals	<ul> <li></li> </ul>		
Suspension			
Shock Absorbers	<ul> <li></li> </ul>		

# Electricals, Controls & Lights

Master Key	~	Spare Key(s)	<ul> <li>Image: A start of the start of</li></ul>
Door Locks			
Child Safety Locking	<ul> <li>Image: A start of the start of</li></ul>		
Dashboard			
Instrument Panel	<ul> <li>Image: A start of the start of</li></ul>		
Airbags			
Airbags	~		
Controls	~	Cruise Control	<ul> <li>Image: A start of the start of</li></ul>
Infotainment Display	~	Engine Sensors	~
OBD Connector	<ul> <li></li> </ul>	Navigation System	~
Music System	<ul> <li></li> </ul>		
Lights			
Headlight	~	Interior Lights	<ul> <li>Image: A start of the start of</li></ul>
Tail Light Cluster	~	Turn Signal Lights	<ul> <li>Image: A start of the start of</li></ul>
Daylight Running Lights	~	License Plate Light	~
Air Conditioning			
AC Cooling	<ul> <li>Image: A start of the start of</li></ul>	AC Switch	<ul> <li>Image: A start of the start of</li></ul>
AC System Leaks	~	Center AC Vent	<ul> <li>Image: A start of the start of</li></ul>
Front Right AC Vent	<ul> <li>Image: A start of the start of</li></ul>	Heater	<ul> <li>Image: A start of the start of</li></ul>
Rear Blower Switch	~	Rear Left AC Vent	<ul> <li>Image: A start of the start of</li></ul>
Rear Defogger	<ul> <li></li> </ul>	USB Charging Port	<ul> <li></li> </ul>
Power/ Manual Windows	<ul> <li></li> </ul>	Memory Seats	<ul> <li>Image: A start of the start of</li></ul>
Ӓ Interiors & Luggage			
Dashboard And Instrument Panel	~	Central Console	~
Glove Box	<ul> <li></li> </ul>	Steering Wheel	~

Sunvisor	~	Seat Upholstery	~
Manual Seat Movement	<ul> <li>Image: A start of the start of</li></ul>	Seat Belts	<ul> <li></li> </ul>
Head Rest	<ul> <li>Image: A start of the start of</li></ul>	Door Controls And Trim	~
Grab Handle	<ul> <li>Image: A start of the start of</li></ul>	Carpet	<ul> <li>Image: A start of the start of</li></ul>
Headliner	<ul> <li>Image: A start of the start of</li></ul>	Rear View Mirror	~
Toolkit	~		

# Tyres

Tyres Condition			
Left Hand Side Front Tyre	~	Left Hand Side Rear Tyre	~
Right Hand Side Front Tyre	~	Right Hand Side Rear Tyre	~
Spare Tyre	<ul> <li>Image: A start of the start of</li></ul>		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<45%		



## A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE