



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 MITSUBISHI LANCER EX

GLX | 141,306 KM

Car highlights



Amazing Comfort
















Power driver seat



Tilt Steering wheel

Tilt steering wheel for extra comfort

Basic Details

 Kilometers	141306	 Specs	Yes
 Engine	2.0L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	1 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	JMYSTCY4AFU741344		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



Safety & Security

Parking Sensors Rear



Reverse Camera



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door Handle: Light Scuffing < 50mm	
-----------------	---	---	---

Rear left door		Rear right door Moulding: Paint Chip-off < 5mm	
----------------	---	---	---

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---


Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

Front Bumper Condition

Front Bumper			
--------------	---	--	--

Rear Bumper Condition

Rear Bumper			
Rear Bumper: Paint Faded, Crack/ Misaligned			

Hood Condition

Hood			
------	---	--	--

Trunk Condition

Trunk			
Door Trim: Light Scuffing < 50mm			

Trunk condition

Trunk			
-------	---	--	--

Roof Condition

Roof			
------	---	--	--

Pillars Condition

Left A Pillar		Right A Pillar	
Inner Condition: Fair Use Wear		Inner Condition: Light Scuffing	

Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	!	Left C Pillar	✓
Beading Crack/ Tear < 5mm			
Running Board Condition			
Left Running Board	✓	Right Running Board	!
		Front Right Floor Trim: Light Scuffing < 80mm	
Windshield Condition			
Front Windshield	✓	Rear Windshield	!
		Tint Fair Use Wear < 30mm	
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
		Boot Floor	
Apron	✓	Door Skirting: Acid Marks/ Bird Dropping < 5mm	!
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	!
		Light Scuffing < 50mm	

Monogram		Window Glass	
Wiper			
Panel Condition			
Rear Trunk Panel Dent < 30mm			

Engine & Transmission

Engine			
Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Radiator Condition		Radiator Coolant	
Battery			
Battery Terminal & Tightness			
Fuel System			
Fuel Cap		Fuel Tank	
Transmission Operation			
Gear Shifting		Drive Axle	
Transmission Fluid			

Steering, Suspension & Brakes

Steering			
Steering wheel			
Brake System			
Parking Brake		Brake Master Cylinder	
Brake Disc & Brake Pad		Brake Fluid	
Pedals			
Suspension			
Shock Absorbers			

Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System

Condition: Button(s) Faded



Camera



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



Turn Signal Lights
Left ORVM: Crack



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent
Crack/Fair Use Wear



Front Right AC Vent

Fair Use Wear



Heater



Parking Sensors



Rear Defogger



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Color Dullness,
Minor Scuffing/ Crack/ Fair Use Wear



Central Console

Box: Minor Crack/Fair Use Wear/ Scuffing



Cup Holder		Glove Box	
Steering Wheel		Sunvisor Left: LHS Sunvisor Holder Crack/ Broken, Sunvisor RHS Color Low Brightness	
Seat Upholstery Driver Seat: Minor Fair Wear/Fade off		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim Front Right Door: Light Scuffing/Disfiguration		Grab Handle	
Carpet		Headliner Front Left: Light Smudge/Disfiguration	
Rear View Mirror		Toolkit	

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE