



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2017 MITSUBISHI MONTERO SPORT**

**GLX | 115,919 KM**

VIN: MMEMC21X5HH018374

## Car highlights



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear



### **Music System**














Enjoy your drive with music system



### **Amazing Comfort**










Power driver seat

## Basic Details

 Kilometers	<b>115919</b>	 Specs	<b>Yes</b>
 Engine	<b>3.0L</b>	 Option Type	<b>Basic Option</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Rear Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Brown</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>7 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>MMEMC21X5HH018374</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Power Folding Mirrors		Rear Defogger	
Central Armrest			
 <b>Exteriors</b>			

Fog Light Front		Halogen Headlights	
 <b>Safety &amp; Security</b>			
Parking Sensors Rear		Reverse Camera	
Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 <b>Entertainment</b>			
USB player			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door



Front right door



Panel: Light Scuffing < 50mm

Rear left door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm



Rear right door

Panel: Light Scuffing < 50mm



### Fenders Condition

Left Fender

Condition: Low Visual Dent < 30mm, Light Scuffing < 50 mm



Right Fender

Condition: Light Scuffing < 50mm



### Quarter Panels Condition

Left Quarter Panel

Condition: Light Scuffing<50mm



Right Quarter Panel

Condition: Light Scuffing<50mm



### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



### Hood Condition

Hood

Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm



### Trunk Condition

Trunk



Trunk conditon

Trunk



### Roof Condition

Roof



Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar Low Visual Dent < 50mm	!
Right B to C Pillar Beading	✓	Left C Pillar	✓

Running Board Condition

Left Running Board	✓	Right Running Board	✓
--------------------	---	---------------------	---

Windshield Condition

Front Windshield Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm	!	Rear Windshield	✓
--	---	-----------------	---

Structural Assessment

Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Antenna	✓

Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

---

## Engine & Transmission

### Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

---

## Steering, Suspension & Brakes

### Steering

Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

---

## Electricals, Controls & Lights

## Keys

Master Key



Spare Key(s)



## Door Locks

Child Safety Locking



## Dashboard

Instrument Panel



## Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Camera



## Lights

Headlight



Interior Lights



Tail Light Cluster



License Plate Light



Fog Lights



## Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent  
Crack/Fair Use Wear



Front Right AC Vent



Heater



Rear Blower Switch



Rear Left AC Vent



Rear Defogger



USB Charging Port



Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console

Cigarette Lighter: Cigarette Lighter Not





Working

Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<75%
Spare Tyre	<85%		



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE