



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 MERCEDES BENZ C 200**

**PREMIUM | 47,292 KM**

VIN: WDDWJ8AB7KF807854

## Car highlights



### **Low Mileage**

This car has been driven less than 15,000 km  
a year



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**









Power driver seat, Memory Seats





## Basic Details

 Kilometers	<b>47292</b>	 Specs	<b>Yes</b>
 Engine	<b>2.0L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Rear Wheel Drive</b>
 Body Type	<b>COUPE</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Beige</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>9 Airbags</b>
 Seating Capacity	<b>4 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>WDDWJ8AB7KF807854</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Safety &amp; Security</b>			
360 degree Camera		Lane Departure Warning System	
Navigation		Parking Sensors Front	
Parking Sensors Rear		Auto Park Assist	
Reverse Camera		Blind Spot Monitor	
Traction Control		Front Camera	

Side Camera	✓	Airbag Curtain Shield	✓
Airbag Knees	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
 <b>Comfort &amp; Convenience</b>			
Climate Control AC	✓	Cruise Control	✓
Memory Seats	✓	Steering Mounted Audio Controls	✓
Power Folding Mirrors	✓	Power Tailgate/ Power Trunk	✓
Rear Defogger	✓	Central Armrest	✓
Automatic Headlights	✓		
 <b>Exteriors</b>			
Fog Light Front	✓	Running Lights	✓
LED Headlights	✓		
 <b>Performance</b>			
Paddle Shift	✓		
 <b>Entertainment</b>			
Bluetooth Player	✓	Infotainment System	✓
USB player	✓		

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door Panel: Low Visibility Dent < 30mm	
-----------------	---	---	---

### Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

### Quarter Panels Condition

Left Quarter Panel Condition: Paint Chip-off < 5mm		Right Quarter Panel Condition: Dent < 30mm	
---	---	---	---

### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper	
-------------	---

### Hood Condition

Hood	
------	---

### Trunk Condition

Trunk	
-------	---

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	
------	---

### Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading		Right A to B Pillar Beading	
----------------------------	---	-----------------------------	---














Right A to B Pillar		Left B Pillar	
---------------------	---	---------------	---

Left B Pillar Trim	✓	Right C Pillar Trim	⚠
Running Board Condition		Light Scuffing	
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition		Monogram	✓
Light Scuffing < 50mm	⚠	Wiper	✓
Window Glass	✓		
Panel Condition			
Rear Trunk Panel	✓		

---

## Engine & Transmission








### Engine

Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Turbocharger/ Supercharger		Radiator Condition	
Radiator Coolant			
Battery			
Battery Terminal & Tightness			
Fuel System			
Fuel Tank			
Transmission Operation			
Gear Shifting		Gear shift	
Drive Axle		Transmission Fluid	

---

## Steering, Suspension & Brakes



### Steering

Steering wheel			
Brake System			
Parking Brake		Brake Master Cylinder	
Brake Disc & Brake Pad		Brake Fluid	
Pedals			
Suspension			
Shock Absorbers			

---

## Electricals, Controls & Lights

### Keys

Master Key	
Dashboard	
Instrument Panel	

Airbags			
Airbags	✓		
Cruise Control	✓	Infotainment Display	✓
Engine Sensors	✓	OBD Connector	✓
Radar (If Equipped)	✓	Navigation System	✓
Music System	✓		
Sunroof Operation			
Sunroof	✓		
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
Daylight Running Lights	✓	License Plate Light	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Memory Seats	✓

---

 **Interiors & Luggage**

Dashboard And Instrument Panel	✓	Central Console	✓
Glove Box	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	✓



Manual Seat Movement		Seat Belts	
Head Rest		Door Controls And Trim	
Carpet		Headliner	
Rear View Mirror		Toolkit	
		Jack Availability: Mobility Kit Not Available for non RFT tires	

## Tyres

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Life remaining			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE