



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2015 HYUNDAI ELANTRA

GL | 173,069 KM

VIN: KMHDG41C8FU160413

Car highlights



Steering Mounted Audio Controls

Enjoy your drive with steering mounted audio controls



Amazing Comfort

Power driver seat



Airbag safety
















Airbag Driver Front



Central Arm Rest









Central arm rest for extra comfort






Basic Details

| | | | |
|--|-------------------|---|-----------------------|
|  Kilometers | 173069 |  Specs | Yes |
|  Engine | 1.6L |  Option Type | Basic |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SEDAN |  Fuel | Petrol |
|  Wheel Type | Steel Wheels |  Exterior Color | Exterior Color Silver |
|  Interior Trim | Fabric Trim |  Number of Airbags | 1 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 1 Keys |
|  VIN number | KMHDG41C8FU160413 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|---|--|---|---|
|  Exteriors | | | |
| Fog Light Front | |  | |
| | | Halogen Headlights |  |
|  Comfort & Convenience | | | |
| Rear Armrest with cupholder | |  | |
| | | Steering Mounted Audio Controls |  |
| Central Armrest | |  | |
|  Safety & Security | | | |

| | |
|--|--|
| | |
| Airbag Driver Front  | Central Locking  |
| Child Safety Locking  | |
|  Entertainment | |
| USB player  | |





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|------------------------------------|---|--|---|
| Front left door |  | Front right door | |
| | | Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm |  |
| Rear left door |  | Rear right door |  |
| Panel: Dent < 30mm, Scratch < 50mm | | Panel: Dent > 30mm | |

Fenders Condition

| | | | |
|---------------------------|---|---|---|
| Left Fender |  | Right Fender |  |
| Condition: Scratch < 50mm | | Right Fender: Dent < 30mm, Scratch < 50mm | |


Quarter Panels Condition

| | | | |
|--|---|---------------------------|---|
| Left Quarter Panel |  | Right Quarter Panel |  |
| Condition: Dent < 30mm, Scratch < 50mm | | Condition: Scratch < 50mm | |

Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|---|---|
| Rear Bumper | |
| Rear Bumper: Light Scuffing < 80mm, Dent < 50mm |  |

Hood Condition

| | |
|---|---|
| Hood | |
| Bonnet: Light Scuffing < 50mm, Low Visibility Dent < 30mm |  |

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | |
|------|---|
| Roof |  |
|------|---|

Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



Running Board Condition

Left Running Board



Condition: Scratch < 80mm

Right Running Board



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor

Condition: Refurbished to RTA standards



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Body: Scratch < 50mm

Right Hand Side Mirror



Alloy Wheel/ Rim

Spare Alloy/ Rim Condition



Wheel Arch



Wheel cover



Antenna



Grill Condition

Light Scuffing < 50mm



Monogram



Window Glass



| | | |
|------------------|---|--|
| Wiper | ✓ | |
| Panel Condition | | |
| Rear Trunk Panel | ! | |
| Dent < 30mm | | |

Engine & Transmission

| | | |
|---|---|----------------------|
| Engine | | |
| Engine Body | | |
| Bulk Head Condition: Visible Fair Use Wear/Bend | ! | Engine Performance ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System ✓ |
| Radiator Condition | ✓ | Radiator Coolant ✓ |
| Battery | | |
| Battery Terminal & Tightness | ✓ | |
| Fuel System | | |
| Fuel Cap | ✓ | Fuel Tank ✓ |
| Transmission Operation | | |
| Gear Shifting | ✓ | Drive Axle ✓ |
| Transmission Fluid | ✓ | |

Steering, Suspension & Brakes

| | | |
|------------------------|---|-------------------------|
| Steering | | |
| Steering wheel | ✓ | |
| Brake System | | |
| Parking Brake | ✓ | Brake Master Cylinder ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid ✓ |
| Pedals | ✓ | |
| Suspension | | |
| Shock Absorbers | ✓ | |

Electricals, Controls & Lights

| | | | |
|---|---|---|---|
| Keys | | | |
| Master Key | ✓ | | |
| Door Locks | | | |
| Child Safety Locking | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Infotainment Display Infotainment Display: Damaged Display | ! |
| Engine Sensors | ✓ | OBD Connector | ✓ |
| Music System Condition: Not Working | ! | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Turn Signal Lights | ✓ |
| License Plate Light | ✓ | Fog Lights | ✓ |
| Air Conditioning | | | |
| AC Cooling AC Temperature: Temp in Idling/Drive < 14°C | ! | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent Crack/Fair Use Wear | ! |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |

Interiors & Luggage

| | | | |
|--|---|-----------------|---|
| Dashboard And Instrument Panel Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted | ! | Central Console | ✓ |
| Cup Holder | ✓ | Glove Box | ✓ |

| | | | |
|--|---|----------------------|---|
| Steering Wheel Steering Wheel Fair Use Wear | ⚠ | Sunvisor | ✓ |
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |
| Seat Belts Rear Right Seat: Fair Use Wear | ⚠ | Head Rest | ✓ |
| Door Controls And Trim Front Left Door: Light Scuffing/ Disfiguration | ⚠ | Grab Handle | ✓ |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

| | | | |
|----------------------------------|------|---------------------------|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre Crack/ Uneven Wear | ⚠ | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <65% | LHS Rear Tyre | <55% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <55% |
| Spare Tyre | <55% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE