



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 NISSAN PATROL

LE PLATINUM | 114,135 KM

VIN: JN8AY2NY6K9365082

Car highlights



Power packed

Engine size of 5.6 Litres & 8.0 cylinders



Cruise control

Cruise control to drive with ease & comfort



Rear Seat Entertainment














Enjoy your drive with Rear Seat Entertainment



Amazing Comfort













Power driver seat, Seat Heaters

Basic Details

 Kilometers	114135	 Specs	Yes
 Engine	5.6L	 Option Type	Mid Option
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Seating Capacity	7 Seats
 VIN number	JN8AY2NY6K9365082		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Sunroof		Cruise Control	
Rear Seat Entertainment		Steering Mounted Audio Controls	
Power Tailgate/ Power Trunk		Central Armrest	
 Safety & Security			
Parking Sensors Front		Parking Sensors Rear	
Reverse Camera		ABS	



Exteriors

Running Lights



Entertainment

Bluetooth Player



USB Charging Port



Infotainment System







150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
Condition: Scratched		Condition: Scratched	
Rear left door		Rear right door	
Condition: Dented, Scratched		Condition: Scratched	

Fenders Condition

Left Fender		Right Fender	
Condition: Scratched		Condition: Scratched	

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Scratched		Condition: Scratched	

Front Bumper Condition

Front Bumper	
Condition: Scratched	

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Scratched, Dented	








Hood Condition

Hood	
------	---

Trunk conditon

Trunk	
-------	---

Pillars Condition

Left A Pillar		Right A Pillar	
Condition: Scratched		Condition: Scratched	
Left B Pillar		RHS Pillar B Condition	
Condition: Scratched			
RHS Pillar C Condition		Left C Pillar	
Left D pillar			

Running Board Condition

Left Running Board

Condition: Scratched, Dented



Right Running Board

Condition: Scratched



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield

Condition: Beading Missing/Broken, Spots



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



No structural damage

Chassis Condition



Upper Cross Member Condition



Lower Cross Member Condition



Chassis Condition



Radiator Support



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror

Body: Faded



Left Side Mirror



Right Side Mirror

Body: Faded



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim

Alloy Wheel: Scratched



Left Rear Alloy/ Rim

Alloy Wheel: Scratched



Right Front Alloy/ Rim

Alloy Wheel: Scratched



Right Rear Alloy/ Rim

Alloy Wheel: Scratched



Grill Condition

Chrome Chipped



Window Glass



Wiper

Rear Wiper Blade: Cap Missing



Panel Condition

Rear Trunk Panel

Scratched



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Transmission Operation

Drive Axle



Transmission Operation



Steering, Suspension & Brakes

Steering

Steering wheel

Condition: Trim Scratched



Shock absorbers



Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



Suspension

Suspension



Electricals, Controls & Lights

Dashboard

Instrument Panel



Cruise Control



Music System



Bluetooth Operations



Sunroof Operation

Sunroof



Camera



Lights

Lights



Running lights



Headlight Left: Scratched	⚠	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓	Back Up Light	✓
Fog Lights Left Fog Light: Scratched	⚠	Trunk Lid Release/Trunk Lid Light Operation	✓
Air Conditioning			
AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Heater	✓
AC Heater Operation Switch	✓	AC Blower Switch	✓
AC Wind Direction	✓		
Rear Defogger	✓	USB Charging Port	✓
Rear Entertainment	✓	Power/ Manual Windows	✓
Seat Heaters	✓	Memory Seats	✓



Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Condition: Gear Knob Scratched, Scratched	⚠
Cup Holder	✓	Sunvisors Cover Torn	⚠
Seat Upholstery Driver Seat: Faded, Cover Torn, Scratched	⚠	Manual Seat Movement	✓
Seat Belts	✓	Seat Belt with issues	✓
Head Rest	✓	Door Controls And Trim Front Left Door: Scratched	⚠
Door Hinge Condition	✓	Carpet Front floor carpet: Carpet Torn/Damaged	⚠
Headliner	✓	Rear View Mirror	✓



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<85%

LHS Rear Tyre

<85%

RHS Front Tyre

<85%

RHS Rear Tyre

<85%

Spare Tyre

<85%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE