



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 RENAULT DUSTER

PE | 109,519 KM

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Running Lights

This car has a Running lights



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat









Basic Details

 Kilometers	109519	 Specs	Yes
 Engine	2.0L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color Green
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	VF1HSRCH5HA537809		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front		Roof Rails	
Running Lights		Halogen Headlights	
 Comfort & Convenience			
Cruise Control		Steering Mounted Audio Controls	
 Safety & Security			

Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 Entertainment			
Bluetooth Player		USB player	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door

Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm



Rear left door

Panel: Dent < 30mm, Scratch < 50mm



Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm



Fenders Condition

Left Fender

Condition: Dent < 30mm, Scratch < 50mm



Right Fender

Right Fender: Dent < 30mm, Scratch < 50mm



Quarter Panels Condition

Left Quarter Panel

Condition: Dent < 30mm, Scratch > 50mm, Paint Chip-off > 5mm



Right Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood



Trunk Condition

Trunk



Trunk condition

Trunk



Roof Condition

Roof

Roof Moulding Condition: Minor Rubber Beading Fair Use Wear



Pillars Condition

Left A Pillar	⚠	Right A Pillar	⚠
Inner Condition: Fair Use Wear		Inner Condition: Light Scuffing	
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	⚠
		Beading Crack/ Tear < 5mm	
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	⚠	Right B to C Pillar	✓
Light Scuffing		Left C Pillar	✓
Right B to C Pillar Beading	✓		

Running Board Condition

Left Running Board	⚠	Right Running Board	⚠
Front Left Sill Trim: Scratch < 80mm		Rear Right Sill Trim: Light Scuffing < 80mm	

Windshield Condition

Front Windshield	✓	Rear Windshield	✓
------------------	---	-----------------	---

Structural Assessment

Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	⚠
Firewall Condition	✓	Condition: Light Scuffing < 80mm	
Head Light Support Condition	✓	Cowl Top	✓

Rear View Mirror Condition

Left Hand Side Mirror	✓	Right Side Mirror	⚠
Right Hand Side Mirror	✓	Body: Scratch < 50mm	

Alloy Wheel/ Rim

Left Front Alloy/ Rim	⚠	Left Rear Alloy/ Rim	⚠
Rim: Paint Faded		Rim: Paint Faded	
Right Front Alloy/ Rim	⚠	Right Rear Alloy/ Rim	⚠
Rim: Paint Fade/Paint Defect		Rim: Paint Faded/Light Rusting	
Spare Alloy/ Rim Condition	✓		

Wheel cover	✓	Antenna	✓
-------------	---	---------	---

Grill Condition	✓	Monogram	✓
-----------------	---	----------	---

Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓	Spare Key(s)	!

Buttons Faded

Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent
Colour Faded



Front Right AC Vent
Color Faded



Heater



Rear Defogger

Extensive Wear Of Strip



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard And Instrument Panel: Light
Scuffing/Crack



Central Console



Glove Box



Steering Wheel

Steering Wheel Fair Use Wear



Sunvisor		Seat Upholstery	
		Driver Seat: Minor Cigarette Burn	
Manual Seat Movement		Seat Belts	
Head Rest		Door Controls And Trim	
		Front Left Door: Light Scuffing	
Grab Handle		Carpet	
Headliner		Rear View Mirror	
Front Left: Crack/Fair Use Wear			
Toolkit			

Tyres

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<65%
RHS Front Tyre	<75%	RHS Rear Tyre	<65%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE