



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2012 HYUNDAI VELOSTER

GLS | 127,161 KM

VIN: KMHTC61C4CU082131

Car highlights



2 door style

Stylish car design having 2 doors



Cruise control

Cruise control to drive with ease & comfort



Music System
















Enjoy your drive with music system



Amazing Comfort










Power driver seat












Basic Details

 Kilometers	127161	 Specs	Yes
 Engine	1.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	HATCHBACK	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	4 Seats	 Number of keys	2 Keys
 VIN number	KMHTC61C4CU082131		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

<div> Exteriors</div>				
Fog Light Front		<div></div>	Rear Bumper Spoiler	<div></div>
Halogen Headlights		<div></div>		
<div> Comfort & Convenience</div>				
Cruise Control		<div></div>	Steering Mounted Audio Controls	<div></div>
Power Folding Mirrors		<div></div>	Rear Defogger	<div></div>

Central Armrest		
 Safety & Security		
Parking Sensors Rear		Reverse Camera 
Airbag Driver Front		ABS 
Central Locking		Child Safety Locking 
 Entertainment		
Infotainment System		USB player 

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior



Doors condition

Front left door		Front right door	
Inner Handle: Color/Chrome Dullness		Inner Beading: Rubber Crack/ Tear < 5mm	



Rear right door

Panel: Light Scuffing < 50mm, Low Visual Dent < 30mm, Scuffing > 50mm, Paint Chip-off < 5mm 

Fenders Condition

Left Fender		Right Fender	
Condition: Paint Chip-off < 5mm, Scratch < 50mm		Right Fender: Scratch > 50mm, Scratch < 50mm	

Quarter Panels Condition


Left Quarter Panel		Right Quarter Panel	
Condition: Paint Chip-off < 5mm, Scratch < 50mm		Condition: Scratch < 50mm, Paint Chip-off < 5mm	

Front Bumper Condition

Front Bumper 

Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip< 8mm 


Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm 


Trunk Condition

Trunk

Door Trim: Light Scuffing < 50mm 

Trunk conditon

Trunk

Lock: Switch Fair Use Wear/ Not Working 

Roof Condition			
Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Right C Pillar Trim	✓
Right B to C Pillar	!	Right B to C Pillar Beading	✓
Light Scuffing < 80mm			
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip	!	Rear Windshield	✓
Mark<5mm, Passenger Side/Stone Chip			
Mark<8mm			
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	!	Right Hand Side Mirror	✓
Body: Scratch < 50mm, Paint Chip-off < 5mm			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Rim: Alloy Edge/ Scuff > 80mm, Alloy Face/	!	Rim: Alloy Edge/ Scuff > 80mm, Alloy Face/	!
Scuff < 50mm		Scuff < 50mm	
Right Front Alloy/ Rim	!	Right Rear Alloy/ Rim	!
Rim: Alloy Edge/ Scuff > 80mm, Alloy Face/		Rim: Alloy Edge/ Scuff > 80mm, Alloy Face/	

Scuff < 50mm		Scuff < 50mm	
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Antenna	✓
Grill Condition	!	Monogram	✓
Light Scuffing < 50mm			
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	!		
Paint Chip Off < 5mm			

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		

Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Camera



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



Turn Signal Lights

Left ORVM: Light Scuffing < 50mm



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Defogger

Extensive Wear Of Strip



USB Charging Port



Power/ Manual Windows

Front Left: Master Switch Buttons Faded





Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/
Disfiguration/ Melted, Minor Scuffing/ Crack/
Fair Use Wear



Central Console

Box: Minor Disfiguration, Minor Crack/Fair
Use Wear/ Scuffing



Cup Holder



Glove Box

Glove Box: Minor Scuffing/Crack/Fair Use
Wear



Steering Wheel

Steering Wheel Fair Use Wear



Sunvisor

Left: LHS Sunvisor Holder Crack/ Broken,
Sunvisor LHS Minor Disfiguration, Sunvisor
RHS Minor Disfiguration



Seat Upholstery

Driver Seat: Minor Cigarette Burn, Minor Fair
Wear/Fade off



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim

Front Left Door: Light Scuffing, Light Scuffing/
Disfiguration



Grab Handle



Carpet

Front Left Floor Mat: Smudge/Burn/Crack



Headliner

Front Left: Light Smudge/Disfiguration, Light
Scuffing



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<45%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE