



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2014 TOYOTA COROLLA**

**XLI | 129,939 KM**

VIN: RKLBL9HE7E5205283

## **Car highlights**



### **Great Parking Assistance**

Parking Sensors Rear



### **Steering Mounted Audio Controls**

Enjoy your drive with steering mounted audio controls



### **Amazing Comfort**
















Power driver seat



### **Airbag safety**










Airbag Driver Front

Basic Details

 Kilometers	129939	 Specs	Yes
 Engine	2.0L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	3 Keys
 VIN number	RKLBL9HE7E5205283		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Safety &amp; Security</b>				
Parking Sensors Rear			Airbag Driver Front	
ABS			Central Locking	
Child Safety Locking				
 <b>Comfort &amp; Convenience</b>				
Steering Mounted Audio Controls			Rear Defogger	

Central Armrest



**Exteriors**

Halogen Headlights



**Entertainment**

USB player







# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
Handle: Paint Chip-off < 5mm		Handle: Paint Chip-off < 5mm	
Rear left door		Rear right door	
		Handle: Paint Chip-off < 5mm	

### Fenders Condition

Left Fender		Right Fender	
Condition: Paint Chip-off < 5mm		Right Fender: Scratch < 50mm, Paint Chip-off < 5mm	


### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Dent < 30mm, Paint Chip-off < 5mm		Condition: Scratch < 50mm	

### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper	
Rear Bumper: Refurbished to RTA standards	

### Hood Condition

Hood	
------	---

### Trunk Condition

Trunk	
-------	---

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	
------	---

### Pillars Condition

Left A Pillar	⚠	Right A Pillar	✓
Inner Condition: Fair Use Wear			
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	⚠	Left B Pillar	✓
Light Scuffing < 50mm			
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	⚠	Right Running Board	✓
Front Left Sill Trim: Scratch < 80mm			
Windshield Condition			
Front Windshield	⚠	Rear Windshield	✓
Condition: Passenger Side/Light			
Scuffing<50mm			
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	⚠		
Crack/ Fair use Wear			
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	⚠	Left Side Mirror	✓
Body: Paint Chip-off < 5mm			
Right Side Mirror	⚠	Right Hand Side Mirror	✓
Body: Paint Chip-off < 5mm			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	⚠	Left Rear Alloy/ Rim	⚠
Rim: Alloy Edge/ Scuff < 80mm		Rim: Alloy Face/ Scuff < 50mm	
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		

Wheel Arch	✓	Wheel cover	✓
Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel			
Dent < 30mm	!		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		



## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



### Door Locks

Child Safety Locking



### Dashboard

Instrument Panel



### Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System



### Lights

Headlight



Right: Light Scuff Marks < 50mm

Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



### Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Fair Use Wear

Heater



Rear Defogger



USB Charging Port



Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console





Glove Box	✓	Steering Wheel Color Faded	!
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim Front Right Door: Light Scuffing	!
Grab Handle	✓	Carpet Front Left Floor Mat: Smudge/Burn/Crack	!
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE