



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 RENAULT DUSTER

SE | 147,562 KM

VIN: VF1HSRCAXFA514543

Car highlights



Bluetooth

Enjoy your drive with bluetooth



Music System

Enjoy your drive with music system



Amazing Comfort
















Power driver seat



Airbag safety









Airbag Driver Front


Basic Details

 Kilometers	147562	 Specs	Yes
 Engine	2.0L	 Option Type	Mid Option
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	VF1HSRCAXFA514543		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front		Roof Rails	
Halogen Headlights			
 Comfort & Convenience			
Steering Mounted Audio Controls		Rear Defogger	
 Entertainment			

Bluetooth Player	✓	USB player	✓
 Safety & Security			
Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door

Handle: Light Scuffing < 50mm



Front right door

Handle: Paint Chip-off < 5mm



Rear left door

Frame: Acid Marks/ Bird Dropping < 5mm



Rear right door

Frame: Light Scuffing < 50mm



Fenders Condition

Left Fender

Condition: Light Scuffing < 50 mm, Low Visual Dent < 30mm



Right Fender

Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm



Quarter Panels Condition

Left Quarter Panel

Condition: Light Scuffing<50mm, Low Visual Dent<30mm, Acid Marks/ Bird Dropping<5mm



Right Quarter Panel

Condition: Low Visual Dent < 30mm, Light Scuffing<50mm, Acid Marks/Bird Dropping<5mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood

Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm



Trunk Condition

Trunk

Door Trim: Light Scuffing < 50mm



Trunk condition

Trunk



Roof Condition

Roof


Roof Moulding Condition: Minor Rubber 


Beading Fair Use Wear

Pillars Condition

Left A Pillar 

Right A Pillar 


Left A to B Pillar Beading
Beading Crack/ Tear < 5mm 

Right A to B Pillar Beading 


Right A to B Pillar
Low Visual Dent < 30mm 

Left B Pillar 

Left B Pillar Trim 

Left B to C Pillar Beading
Beading Crack/ Tear < 5mm 

Right C Pillar Trim 


Right B to C Pillar
Light Scuffing < 80mm 

Right B to C Pillar Beading 

Left C Pillar 


Running Board Condition


Left Running Board 

Right Running Board
Condition: Light Scuffing < 80mm 

Windshield Condition

Front Windshield

Condition: Driver Side/Stone Chip
Mark<5mm, Passenger Side/Stone Chip
Mark<8mm 


Rear Windshield
Tint Fair Use Wear < 30mm 

Structural Assessment

Chassis Condition 

Radiator Support 

Apron 

Boot Floor
Condition: Light Scuffing < 80mm 

Firewall Condition 

Cowl Top 

Head Light Support Condition 


Cowl Top

Cowl Top 

Rear View Mirror Condition

Left Hand Side Mirror
Body: Light Scuffing < 50mm 

Left Side Mirror 

Right Side Mirror
Body: Light Scuffing < 50mm 

Right Hand Side Mirror 

Alloy Wheel/ Rim

Left Front Alloy/ Rim Rim: Paint Faded	⚠	Left Rear Alloy/ Rim Rim: Paint Faded	⚠
Right Front Alloy/ Rim Rim: Paint Fade/Paint Defect	⚠	Right Rear Alloy/ Rim Rim: Fair Use Wear/ Paint Faded	⚠
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition Light Scuffing < 50mm	⚠
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel Scratch < 50mm	⚠		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering	
Steering wheel	✓
Brake System	

Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		



Electricals, Controls & Lights

Keys

Master Key	✓	Spare Key(s)	✓
------------	---	--------------	---

Door Locks

Child Safety Locking	✓		
----------------------	---	--	--

Dashboard

Instrument Panel	✓		
------------------	---	--	--

Airbags

Airbags	✓		
---------	---	--	--

Controls

Controls	✓	Infotainment Display	!
		Infotainment Display: Scuffing < 50mm	

Engine Sensors

Engine Sensors	✓	OBD Connector	✓
----------------	---	---------------	---

Music System

Steering Mounted Audio Controls: Not Working Properly	!		
---	---	--	--

Lights

Headlight	✓	Interior Lights	✓
-----------	---	-----------------	---

Tail Light Cluster

Rear Windscreen Brake Lamp: Light Scuffing < 30mm	!	License Plate Light	✓
---	---	---------------------	---

Fog Lights

Fog Lights	✓		
------------	---	--	--

Air Conditioning

AC Cooling	✓	AC Switch	✓
------------	---	-----------	---

AC System Leaks

AC System Leaks	✓	Center AC Vent	✓
-----------------	---	----------------	---

Front Right AC Vent Light Scuffing	!	Heater	✓
USB Charging Port	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel Dashboard And Instrument Panel: Light Scuffing/Crack	!	Central Console Gear Shift Knob: Knob Fair Use Wear	!
Cup Holder	✓	Glove Box Glove Box: Minor Scuffing/Crack/Fair Use Wear	!
Steering Wheel Steering Wheel Fair Use Wear	!	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts Driver Seat: Fair Use Wear	!	Head Rest	✓
Door Controls And Trim Front Left Door: Light Scuffing/ Disfiguration, Light Scuffing	!	Grab Handle	✓
Carpet	✓	Headliner Front Left: Light Smudge/Disfiguration, Light Scuffing	!
Rear View Mirror De Silvered Mirror<10%	!	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE