



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 BMW X4

XDRIVE 30i EXCLUSIVE | 107,963 KM

VIN: WBAUJ3A01KLF98504

Car highlights

Service History

Service history available



Cruise control

Cruise control to drive with ease & comfort



Apple play
















Enjoy your drive with apple play



Amazing Comfort

Power driver seat, Memory Seats





Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 107963 |  Specs | Yes |
|  Engine | 2.0L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | All Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Black |
|  Interior Trim | Leather Trim |  Number of Airbags | 8 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | WBAUJ3A01KLF98504 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|---|---|-------------------------------|---|
|  Safety & Security | | | |
| 360 degree Camera |  | Lane Departure Warning System |  |
| Navigation |  | Parking Sensors Front |  |
| Parking Sensors Rear |  | Auto Park Assist |  |
| Reverse Camera |  | Blind Spot Monitor |  |
| Collision Warning System |  | Traction Control |  |

| | | | |
|--|---|-----------------------------|---|
| Front Camera | ✓ | Side Camera | ✓ |
| Airbag Curtain Shield | ✓ | Airbag Driver Front | ✓ |
| ABS | ✓ | Central Locking | ✓ |
| Child Safety Locking | ✓ | | |
|  Comfort & Convenience | | | |
| Climate Control AC | ✓ | Cruise Control | ✓ |
| Memory Seats | ✓ | Rear Armrest with cupholder | ✓ |
| Steering Mounted Audio Controls | ✓ | Power Folding Mirrors | ✓ |
| Power Tailgate/ Power Trunk | ✓ | Rear Defogger | ✓ |
| Central Armrest | ✓ | MagSafe Wireless Charging | ✓ |
| Automatic Headlights | ✓ | | |
|  Performance | | | |
| Paddle Shift | ✓ | | |
|  Exteriors | | | |
| Roof Rails | ✓ | Running Lights | ✓ |
| LED Headlights | ✓ | | |
|  Entertainment | | | |
| Bluetooth Player | ✓ | Apple Play | ✓ |
| Infotainment System | ✓ | USB player | ✓ |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|-----------------|---|--|---|
| Front left door |  | Front right door Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm |  |
|-----------------|---|--|---|

| | | | |
|--|---|-----------------|---|
| Rear left door Panel: Paint Chip-off < 5mm, Dent < 30mm |  | Rear right door |  |
|--|---|-----------------|---|

Fenders Condition

| | | | |
|--|---|--------------|---|
| Left Fender Condition: Paint Chip-off < 5mm |  | Right Fender |  |
|--|---|--------------|---|


Quarter Panels Condition

| | | | |
|--|---|---------------------|---|
| Left Quarter Panel Condition: Dent < 30mm, Paint Chip-off < 5mm |  | Right Quarter Panel |  |
|--|---|---------------------|---|

Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|--|---|
| Rear Bumper Rear Bumper: Light Scuffing < 80mm, Chip< 8mm |  |
|--|---|

Hood Condition

| | |
|------|---|
| Hood |  |
|------|---|

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | |
|------|---|
| Roof |  |
|------|---|

Pillars Condition

| | | | |
|--|---|---|---|
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board Condition: Light Scuffing < 80mm | ! |
| Sunroof Glass Condition (If Equipped) | | | |
| Sun Roof Glass | ✓ | | |
| Windshield Condition | | | |
| Front Windshield Beading: Mouldings Crack/ Fair Use Wear < 50mm | ! | Rear Windshield Windsheild Beadings < 50mm | ! |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | ✓ |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | Right Hand Side Mirror | ✓ |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim Rim: Alloy Edge Scuffing > 50mm | ! |
| Right Front Alloy/ Rim Rim: Alloy Edge Scuffing < 80mm | ! | Right Rear Alloy/ Rim Rim: Alloy Edge/Scuffing<80mm | ! |
| Wheel cover | ✓ | Antenna | ✓ |

| | | | |
|------------------|---|----------|---|
| Grill Condition | ✓ | Monogram | ✓ |
| Window Glass | ✓ | Wiper | ✓ |
| Panel Condition | | | |
| Rear Trunk Panel | | | |
| Dent < 30mm | ! | | |

Engine & Transmission

| | | | |
|--------------------------------|---|-------------------------------|---|
| Engine | | | |
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Turbocharger/ Supercharger | ✓ | Radiator Condition | ✓ |
| Radiator Coolant | ✓ | | |
| Battery | | | |
| Battery Terminal & Tightness | ✓ | | |
| Fuel System | | | |
| Fuel Tank | ✓ | | |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Gear shift | ✓ |
| Drive Axle | ✓ | 4*4 Condition (If Applicable) | ✓ |
| Transmission Fluid | ✓ | | |

Steering, Suspension & Brakes

| | | | |
|------------------------|---|-----------------------|---|
| Steering | | | |
| Steering wheel | ✓ | | |
| Brake System | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
| Pedals | ✓ | | |
| Suspension | | | |

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Radar (If Equipped)



Navigation System



Music System



Sunroof Operation

Sunroof



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Parking Sensors



Rear Defogger



| | | | |
|-------------------|---|-----------------------|---|
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |
| Memory Seats | ✓ | | |

Interiors & Luggage

| | | | |
|--------------------------------|---|----------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel Color Faded | ! | Sunvisor | ✓ |
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Carpet | ✓ |
| Headliner | ✓ | Rear View Mirror | ✓ |
| Toolkit | ✓ | | |

Tyres

| | | | |
|----------------------------|------------------|---------------------------|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <75% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <75% | RHS Rear Tyre | <75% |
| Spare Tyre | No spare tyre | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE