



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2015 CHEVROLET CRUZE**

**LS | 132,204 KM**

VIN: KL1PJ5C56FK007913

## Car highlights



### **Cruise control**

Cruise control to drive with ease & comfort



### **Steering Mounted Audio Controls**

Enjoy your drive with steering mounted audio controls



### **Amazing Comfort**
















Power driver seat



### **Tilt Steering wheel**






Tilt steering wheel for extra comfort

## Basic Details

 Kilometers	<b>132204</b>	 Specs	<b>Yes</b>
 Engine	<b>1.8L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Steel Wheels</b>	 Exterior Color	<b>Exterior Color Silver</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>KL1PJ5C56FK007913</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>	
Cruise Control 	Steering Mounted Audio Controls 
 <b>Entertainment</b>	
USB Charging Port 	

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door

Handle: Paint Chip-off < 5mm



Front right door



Rear left door

Panel: Low Visual Dent < 30mm



Rear right door



### Fenders Condition

Left Fender

Condition: Paint Chip-off < 5mm, Light

Scuffing < 50 mm



Right Fender



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Dent > 30mm



### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Refurbished to RTA standards



### Hood Condition

Hood

Bonnet: Acid Marks/ Bird Dropping < 5mm



### Trunk Condition

Trunk



Trunk conditon

Trunk



### Roof Condition

Roof



### Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board Condition: Light Scuffing < 80mm	⚠	Right Running Board Front Right Sill Trim: Low Visual Dent < 50mm	⚠
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror Body: Light Scuffing < 50mm	⚠	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover Rear Left: Scuffing > 50 mm	⚠
Antenna	✓	Grill Condition Light Scuffing < 50mm	⚠
Monogram	✓	Window Glass	✓

Wiper ✓

Panel Condition

Rear Trunk Panel ✓

---

### Engine & Transmission

Engine

Engine Body ✓

Engine Performance ✓

Engine Oil (Condition & Level) ✓

Exhaust System ✓

Radiator Condition ✓

Radiator Coolant ✓

Battery

Battery Terminal & Tightness ✓

Fuel System

Fuel Tank ✓

Transmission Operation

Gear Shifting ✓

Drive Axle ✓

Transmission Fluid ✓

---

### Steering, Suspension & Brakes

Steering

Steering wheel ✓

Brake System

Parking Brake ✓

Brake Master Cylinder ✓

Brake Disc & Brake Pad ✓

Brake Fluid ✓

Pedals ✓

Suspension

Shock Absorbers ✓

---

### Electricals, Controls & Lights

Keys

Master Key !

Spare Key(s) ✓

Button Faded

Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System

Condition: Button(s) Faded



Sunroof Operation

Sunroof



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent

Fair Use Wear



Heater



USB Charging Port



Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console

Coin Box: Crack/Fair Use Wear



Glove Box



Steering Wheel

Steering Wheel Fair Use Wear



Sunvisor	✓	Seat Upholstery Driver Seat: Minor Fair Wear/Fade off	!
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim Front Left Door: Light Scuffing	!
Grab Handle	✓	Carpet Front Left Floor Mat: Smudge/Burn/Crack	!
Headliner Front Left: Light Smudge/Disfiguration	!	Rear View Mirror De Silvered Mirror<10%	!
Toolkit	✓		

## Tyres

### Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<55%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<55%
Spare Tyre	<65%		





## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE