



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 KIA SORENTO

LX | 94,634 KM

VIN: KNAPH8120G5175073

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Front, Reverse Camera & more



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat



Basic Details

 Kilometers	94634	 Specs	Yes
 Engine	2.4L	 Option Type	Basic Option
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	KNAPH8120G5175073		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Power Folding Mirrors		Rear Defogger	
Central Armrest		Automatic Headlights	
 Exteriors			

Fog Light Front	✓	Roof Rails	✓
Rear Bumper Spoiler	✓	Halogen Headlights	✓
 Safety & Security			
Parking Sensors Front	✓	Parking Sensors Rear	✓
Reverse Camera	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 Entertainment			
Bluetooth Player	✓	USB player	✓





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
		Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm	
Rear left door		Rear right door	
Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Acid Marks/ Bird Dropping < 5mm		Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Acid Marks/ Bird Dropping < 5mm	

Fenders Condition

Left Fender		Right Fender	
		Condition: Light Scuffing < 50mm, Acid Marks/ Bird Dropping < 5mm	

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Trim: Light Scuffing<80mm			

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
-------------	---

Hood Condition

Hood	
------	---

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Beading Crack/ Tear < 5mm

Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



Running Board Condition

Left Running Board



Right Running Board



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Body: Light Scuffing < 50mm

Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim

Rim: Alloy Edge Scuffing > 50mm



Right Front Alloy/ Rim

Rim: Alloy Edge Scuffing < 80mm, Alloy Face



Light Scuffing < 50mm

Right Rear Alloy/ Rim



Spare Alloy/ Rim Condition



Wheel Arch



Wheel cover



Front Right: Crack/ Fair Use Wear

Antenna



Grill Condition



Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body

Mount Condition: Minor Crack/Fair Use Wear



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System

Condition: Button(s) Faded



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch

Button(s) Faded



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Defogger



USB Charging Port

Rear: Cigarette Lighter Missing



Power/ Manual Windows

Front Left: Master Switch Buttons Faded





Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/
Disfiguration/ Melted



Central Console

Gear Shift Knob: Knob Missing, Knob Fair
Use Wear



Cup Holder



Glove Box



Steering Wheel

Color Faded



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet

Trunk Floor Carpet: Fair Use Wear < 80mm



Headliner

Front Left: Crack/Fair Use Wear



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<55%

LHS Rear Tyre

<55%

RHS Front Tyre

<55%

RHS Rear Tyre

<55%

Spare Tyre

<55%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE